#### COMMERCIAL CAR JOURNA

with which is combined Operation & Maintenance Reg. U. S. Pat. Off.

Acceptance under the Act of June 5, 1934, authorized December 18, 1934.

Published monthly

Vol. LI

Philadelphia, June, 1936

No. 4

#### **Editorial Department**

JULIAN CHASE, Directing Editor GEORGE T. HOOK, Editor

STANLEY GERSTIN HENRY JENNINGS GEOFFREY GRIER Managing Editor Technical Editor **Art Editor** 

HAROLD E. GRONSETH **Detroit News Editor** 

JOSEPH GESCHELIN Detroit Technical Editor

#### **EDITORIAL CONTENTS**

Copyright 1936, by Chilton Company (Inc.)

#### **Feature Articles**

What Can Fleets Expect of Expander Type Piston Rings?
If In Quest of Safety-Try a Quiz
Shop Mechanics Are Faithful Hands at Keeping Records
The Value of Vulcanizing Is in the Method
Drivers Trained to Administer First Aid
A Shipper Gives Motor Freight Classifications the 3rd Degree
Keeping Up With Keeshin
The Album

			D	Descriptions								
New	Mack	Model	l EH	Has	"Doggier"	Look	28					
New	Ross	Gear f	or B	etter	Steering		21					

Departments	
The Overload	
Ears to the Ground	]
After Hours	6
New Products On Parade	-
News	-
New Truck Registrations By Makes By Months	;
Commercial Car Journal Truck Specifications	1
Free Money Makers for You	
Advertisers' Index	1

C. A. Musselman, Pres. and Gen. Mgr.; J. S. Hildreth, Vice-Pres. and Manager; W. I. Ralph, Vice-Pres.; G. C. BUZBY, Vice-Pres.

**OFFICERS** 

Philadelphia—Chestnut & 56th Sts., Phone Sherwood 1424. New York—239 W. 39th St., Phone Pennsylvania 6-1100. Chicago—Room 916, London Guarantee & Accident Bidg., Phone Franklin 9494. Detroit—1015 Stephenson Bidg., Phone Madison 2090. Cleveland—609 Guardian Bidg., Phone Main 6860. San Francisco—444 Market St., Room 305, Phone Garfield 6788. Long Beach, Cal.—1595 Pacific Ave., Phone Long Beach 613-238.

SUBSCRIPTION RATES: United States and United States Possessions and all countries in the Postal Uniton—\$2.00 per year. Canada and Foreign—\$3.00 per year. Single copies—25 cents.

Owned and Published by



#### CHILTON COMPANY

(Incorporated) .

#### **Executive Offices**

Chestnut and 56th Streets, Philadelphia, Pa., U. S. A.

C. A. MUSSELMAN, President
FRITZ J. FRANK, Executive Vice-President
FREDERIC C. STEVENS, JOSEPH S. HILDRETH, GEORGE H.
GRIFFITHS, EVERIT B. TERHUNE, ERNEST C. HASTINGS, Vice-Presidents,
WILLIAM A. BARBER, Treasurer, JOHN BLAIR MOFFETT, Secretary

HANSEN COMMERCIAL BODY HARDWARE is made 80 simple and dependable in design is made so simple and dependable in design under severe under service under parties that it gives lasting personnel parties and dependable in design that it gives lasting personnel parties and dependable in design that it gives lasting personnel parties and dependable in design that it gives lasting personnel parties and dependable in design that it gives lasting personnel usage. It includes Refrigerator Body Hardware Cab and Body Hardware ASK FOR CATALOG! Sliding Door Hardware. usage.

RNAL

# How..Your Truck Engines

An entirely new kind of oil gives more miles...more effective lubrication...

HERE'S new economy for Truck Fleet Operators.

This new oil—made by an entirely different refining process—has changed, overnight, the usual conception of what a *good* motor oil should be.

This new treatment—the Furfural Process—frees the New Texaco Motor Oil, entirely, from all tar and gum forming elements... frees it from other non-lubricating materials, too. It is all lubricant... no waste.

You get a stronger, more protective oil film . . . a film that has greater resistance to heat inside the engine. We call this the "Furfural'd Film."

Your mileage records will show

that this oil lasts longer. Here is lower oil cost.

But, more important, this "Furfural'd Film" so completely lubricates and protects that it will reduce cylinder and bearing wear, keep rings free, give maximum compression, and prevent gasoline waste.

You will get longer periods between overhauls and maintenance costs will be reduced.

A Texaco representative will be glad to provide practical engineering service to prove the economies you can get with the New Texaco Motor Oil.

THE TEXAS COMPANY

135 East 42nd Street • New York City
Nation-wide distribution facilities
assure prompt delivery





COMMERCIAL CAR JOURNAL





Goodyear lug tires enabled this Helms and Boettcher milk truck to operate over Wisconsin's snow-blocked roads without chains and without stalling. When this picture was taken, the thermometer registered 10 below but ye editor has only just succeeded in thawing it out

#### 10,000 Questionnaires . . .

BACK of that article on Expander Type Piston Rings on page 12 is the story of 10,000 questionnaires, no more, no less. Ordinarily we'd hate to admit that 10,000 questionnaires pulled only 100 or so replies. Direct mail experts would shake their heads, tsk-tsk disappointedly, and tell you that the return should have been at least two per cent. Of course, even that wouldn't have satisfied us because we've had too many 10 and even 20 per cent returns on such practical questionnaires. So naturally, the one per cent return has set us to wondering, to thinking and to planning.

#### ... Set Us to Wondering ...

WE first began to wonder back in March when returns to the first batch of 5000 questionnaires started dribbling in. The awful 1 per cent stared us in the face. Something's wrong, we said, and proceeded to prove it by sending 5000 more out in May. Well, something's wrong but we didn't prove it. So that set us to thinking. What can be the reason for such a poor showing? we asked ourselves. For one thing the piston ring manufacturers have not made a real attempt to sell the fleet market on expander rings. Jobber salesmen have doubtless been active but the manufacturers have not paved the way for them by means of advertising. (We think the manufacturers have overlooked a bet, but that's another mat-



ter.) Therefore, we soothed ourselves, the unfamiliarity of fleets with expander rings might be the reason for the lack of returns.

#### ... To Thinking and ...


**B**UT we didn't stop at that reason. We went over the questionnaire again and again, studying it for "bugs." We thought we detected one and made some personal visits to the smaller fleets. It looks to us as if it were another reason for the low returns. One of the questions asked was: "At what cylinder taper do you install expander type rings?" Now it may not be true in your case, but years of contact with fleet shops convinced us long ago that there are too many shopmen who couldn't read a micrometer if their lives depended on it. Apparently there has been no improvement on that score, and that, plus the reluctance of most individuals to reveal their ignorance, however excusable, may have made the cylinder taper a stumbling block-with the 1 per cent effect.

#### ... To Planning

So that has set us to planning. The article on page 12 tells you all that we have found out about the use of expander rings in fleets. Its practical slant should prove of value to every fleet. However, we are going to do something about those micrometers. We are going to give you an article on how to read a micrometer. If you can't read one now, the 15 or 20 minutes you spend on the article will enable you to graduate with the degree of Master-Mind on Micrometers. We're pushing it through for the July issue.

#### Kicks on Keeshin

THE "Keeping Up with Keeshin" yarn on page 25 deserves some background comment. It probably won't come as a surprise to Mr. Keeshin himself that there are a lot of operators who see red at the mere mention of his name. In the past this antagonism was aroused by his aggressiveness, by some of his ideas and by the utter frankness



This is the diesel powered unit on which W. L. Knebel of Pocahontas, Ill., has banked to save \$2,140.49 on fuel in a year. The Hug model 42-A hauls 20,000 to 24,000 lb. from St. Louis to Boston every 10 days. The original 428 cu. in. engine was replaced with a 415 cu. in. Buda diesel. Fuel cost per trip with gas was \$79.36 and for fuel oil \$18.20. He also got 9½ m.p.g. with the diesel against 5 m.p.g. with gas. We "gas" this is a pretty good saving

URNAL



with which he has the habit of expressing them. At the moment this antagonism is being perpetuated and is gaining additional converts because of aggressiveness which is being expressed in terms of expansion by the acquisition of motor freight lines. We were not unaware of this antagonism but recently we have been made doubly conscious of it. It seems that there is some resentment among many of our readers at the manner in which we are chronicling the Keeshin development. They think we are giving too much attention to Keeshin.

#### We Kash Out; You Kash in

ON our part we can't see why such resentment should exist. If our articles revealed some silly hero-worship or represented mere publicity piffle the resentment would be justified. (Although you'll never have cause to feel that way about any part of our editorial section, so long as we have anything to do with it.) We are keeping an eye on the Keeshin enterprise because it is the outstanding development of the Motor Carrier Act regulating interstate haulage. That eye is costing us money and we're going to keep it peeled so that you may know what is happening on that front-and you should know. If something unsavory should develop, don't think you'll have to look elsewhere for it.

#### More Keeshin Koming

THERE'S more Keeshin in the article giving motor freight classifications the third degree. Shippers should know what's good and what's not so good so far as they are concerned, so you needn't expect us to argue with them if they think Keeshin is doing a pretty good job of classifications, and that other agencies are not so hot. And we might as well prepare you now for the motor freight rate yarn in the July issue. Keeshin seems to get a pretty good break there, too. It is our impression that there is a lot that will have to be done on rates if truckers wish to avoid incurring the undying displeasure of shippers. We hope we are contributing in our small way to a realization of the causes of shipper dissatisfaction so that reasonable steps may be taken to eliminate them.



Peggy the ponderous pachyderm proves Plymetl can take it. She and her keeper were both skeptical of this, at first, being mindful of the beast's 21/2-ton weight. Now see Peggy performing tricks on the box without fear of crashing. But there's no trick to the Plymetl cooler box. It's waterproofed plywood panel with a metal facing. Its strength, in view of its light weight, fooled Peggy's keeper

#### Calling All Costs

READER reactions reveal there are quite a number of fleet men who would like to get operating cost figures for comparative purposes. Frankly, we have steered clear of publishing such figures for a number of reasons. First, the figures . . . complete and honest figures...are difficult to procure. The small percentage of operators who keep complete records, guard them jealously for obvious reasons. They have a fear which may not have occurred to you. It is that the cost figures that are published will prompt executives higher up to make comparisons which may not be flattering and may result in drastic action, because those higher-ups never seem to consider that variations in operating conditions are a perfect reason for variations in costs. However, if there are any operators in the audience who are entirely free of inhibitions, who would like to compare their costs with others, we wish they would step forward. We'll be glad to start the figures rolling. Company names need not be revealed. The figures can be just as interesting without them.

#### Costs . . . Free of Cost

ALL of which leads us to mention a couple of sizable booklets prepared by the Metropolitan Life Insurance Co. with the help of some of their fleet-operating policyholders. One book is on Operating Cost of Heavy Duty Trucks and the other on Light Trucks. We offered the latter in May, but you now can have both by checking the coupon hereabouts. The cost analyses are comprehensive and, it's a guarantee, very interesting. They cost you nothing. The line forms on the right.

#### An AC Safety "Plug"

THE AC Spark Plug Co. has just completed a 12-year record during

which their trucks were operated 1,520,-000 miles, mostly city driving, without a single accident. (We know, that as a practical operator, you will let go a skeptical "Oh, yeah? What do they call an accident?") We don't intend to argue the point. We do think, however, that, judging by the safe-driving philosophy of five of their drivers, the company should have a very outstanding safety record. They all express themselves in different ways but the sum of their statements boils down to what Driver Yuch has to say: "I avoid accidents by being alert, keeping within the speed limit, stopping promptly, watching the other driver and anticipating what he is going to do. I drive according to the condition of the streets and am careful all the time." To which might be added Driver Roy Behrendt's choice bit: "If I can avoid an accident by giving the other driver the right-of-way. I let him have it."


#### Free Pack of Packings

N order to acquaint every fleet operator who has his own shop and every recognized repair shop operator with Wilco valve packings the Wilkening Mfg. Co., 70th St. and Church Lane, Phila., Pa., offers free of charge one complete set of Wilco valve packings for any given engine. This sounds like quite a bit of "all right" considering that all the reader has to do is check A on the coupon and specify the engine his gift is to fit.

#### Cooling System Cocktail

THE Philadelphia Gas Works mixes its radiator cocktails in a large shaker. The water and anti-freeze are mixed in a large tank located inside the shop in such proportions that the radiators are protected to a safe known temperature. From the tank the solution is pumped to the radiator filling tower in the driveway. No one is then responsible for freeze-ups because there are none.





This two-cylinder opposed, 15-18 hp. diesel engine for light trucks will be sold by the Covic Diesel Engine Co., Los Angeles, Cal. Covic secured license for its manufacture and sale in this country from the Victor Oil Engines, Ltd., Coventry, England. Its weight is said to be 280 lb. with an engine speed range of 500 to 3500 r.p.m.

#### Patents for Parcels

ıt

as

11

to

r,

S-

n-

ng

n-

of

at

ci-

in

ly,

ci.

ve

ets

To

oy

oid

ver

er.

ery

ith

ing

ne,

one

ngs

ike

ing

c A

ine

ixes

ker.

d in

p in

are

ure.

ped

rive-

for

NAL

One of our spies did a commendable job this month. He not only tracked down a rumor but he actually saw exhibit A. In addition he got out a pad and pencil and took down details and made his way to this office with his notes intact. notebook reveals that a very large delivery fleet is actually manufacturing at least one truck which incorporates the features they want in a truck. It is a 112-in. wheelbase truck with a very heavy chassis frame and a substantial X member. Hydraulic brakes are larger than any current design provides for a truck of similar capacity. The axles are oversize, the rear axle having two speeds. Power is supplied by a six-cylinder engine of relatively low horsepower. The body is expected to be extremely light and the driver is to be ensconced upon a swivel seat.

#### Laundry Literature

Edward Loscheider, American Institute Laundry, Joliet, Ill., has two small trucks that cover 80 mile routes on certain days and on these days the drivers are able to solicit more laundry than they are able to load on the trucks. Mr. Loscheider has considered two-wheel trailers having a floor space 4 ft. x 7 ft. Mr. Loscheider would appreciate communication with interested manufacturers and fleet operators who could give him some advice.

#### Baking Babble

Things are stirring in the paint business, this department learns from its dispatches. For instance, this very month outlets are being opened up for the distribution of a new enamel which can be baked at such a low temperature that it is unnecessary to remove tires, batteries, etc., from the vehicle for the baking process. Still such modest baking requirements give the desired results of sealed surface and high lustre.

#### **Delivery Definition**

Knowing that headquarters never forgets or never passes up a tip, one of our men has given us this simple warning: "Be on the lookout for a new light delivery truck model to list between \$400 and \$500. It

will be a 106-in. wheelbase and will have phenomenal gas mileage as a result of direct fuel injection. A goodly number of experimental cars are averaging 32 m.p.g."

#### Alignment Agendum

Fighting for recognition among the items placed before this department for consideration this month is a confidential note stating that a piece of shop equipment will soon be marketed that when mounted on the floor will indicate whether or not the wheels of a truck are out of line when a truck is driven into the shop.

#### Piston Performance

Every now and then one of our spies turns in a report on something that causes us to either doubt his sincerity or his ability. When this happens the head spy checks up and invariably is forced to apologize, at least mentally, to the hard-working operative. The most recent report that caused such discomfort concerns a ringless piston. The piston is composed of welded sections and the force of the explosion causes certain sections to move radially against the cylinder wall with the result that piston rings are not necessary.

#### Delayed Data

Right up to press time we thought we would be able to give you full details on a new ¾-1-ton truck by Diamond T Motor Car Co., but the news eluded our most carefully laid plans. However all of the effort was not wasted as our spy managed to garner these facts. Engine, six-cylinder, 190 cu. in.; wheelbase 119 in.; tires 6.00/16 and weight (chassis) 2750 lb; chassis list price, \$525. We should not miss on full details next month.

#### Cushion Canto

A new company has taken the truck driver's comfort so seriously that they are starting to manufacture air cushions for seats and sleeper cab mattresses. The container is made of a special rubber lined with a cotton pad for coolness.

#### lanition Interlocution

Finding its way into our dispatches this month is the information that an ignition

maker is almost ready to announce equipment that will provide the hottest spark yet. It will be a 12-volt system with a special coil and a distributor fitted with two condensers. It is designed to provide a hot spark for use in connection with a gasoline to fuel oil convertor or in the Hesselman type engine. A vacuum attachment permits the hottest spark at low speeds to prevent fouling of plugs when idling. If we understand it correctly, it is a replacement item that can be installed by the fleet operator.

#### Analyzer Accouterment


Unable to trace down a rumor to a positive conclusion we give you the substance of the rumor without being too sure of our ground. 'Tis said that one manufacturer plans to recognize the fleetman to the extent of producing a portable engine analyzer which can be carried from truck to truck. Current to operate the unit will be supplied by a small motor generator.

#### FREE

(Check and mail to the Editor, Commercial Car Journal, Philadelphia, Pa.)

☐ A—Wilkening's free sample set of

Valve Packing (specify en-
☐ B—Victor Gasket Guide
C—Booklet of information on Eaton two-speed axles
☐ D—Complete Catalog on DeVilbiss air compressors
E-Goodrich Tire Calculator
☐ F—Technical data and catalog of Ohio gears
☐ G—Booklets on operating costs of
light and heavy duty trucks
light and heavy duty trucks  ☐ H—Cornell catalog of rolling
light and heavy duty trucks  H—Cornell catalog of rolling grilles and doors
light and heavy duty trucks  H—Cornell catalog of rolling grilles and doors
light and heavy duty trucks  H—Cornell catalog of rolling grilles and doors  Name  Title
light and heavy duty trucks  H—Cornell catalog of rolling grilles and doors  Name  Title  Firm Name





Illustrations are of various types of oil control rings. Reading across from L to R: Pedrick hydraulic; Perfect Circle's new X90; Ramco's spring type; Simplex's Molium ring

INETY-SEVEN fleet operators reporting upon the operation of 7582 trucks and 1947 passenger cars establish the fact that expander type piston rings have a definite place in fleet maintenance programs. The 9529 fleet-operated vehicles involved in this survey consume piston rings, both conventional and expander type, at the rate of 5.3 piston rings per vehicle, per year which is about five times the rate of consumption of the average owner-operated passenger car.

The rate of consumption, which establishes the fleet operator as a quantity buyer of piston rings, was obtained by dividing the number of piston rings bought by these fleets during the period of one year by the number of trucks which they operate. Some questionnaires had to be discarded in obtaining these totals as they did not contain enough information of a concrete nature to permit their use for this purpose but these questionnaires were extremely useful for other phases of this survey since they contained some very pertinent information on the use of expander rings.

AN even 60 fleet operators buy and use expander type piston rings in maintaining their fleets and 37 do not. From the comments it is possible to see that expander type rings are not as popular on large-size heavy-duty engines as they are for use in the lighter equipment, although it is obvious that some operators are successful in using expander type rings on the heavy equipment. Scattered here and there throughout the questionnaires are warnings that the technique of installation has much to do with the success of the expander type ring. It may be possible that a little closer study on the installation of the particular type of ring that appears to be the best to the individual operator would result in an even greater popularity.

It is noteworthy that those who are among the 37 non-users who comment

What Can Fleets Expect of TYPE PISTON RINGS?


Longer Life With Adequate Oil Control In New Or Reconditioned Cylinders and Much Longer Life In Worn Cylinders is the Nearly Unanimous Answer from 97 Fleets Operating 9529 Trucks and Passenger Cars

on expander type rings do not condemn the expander ring in a positive manner nor do they offer any evidence that they will not use expander type rings in the future. Some state that their experience has not been satisfactory and others that expander type rings are not economical in their opinion. In view of the highly successful results obtained by other fleets it seems probable that some of these opinions would change and some of the unsatisfactory experiences could be corrected with a combination of the right ring and more knowledge of installation.

The installation part of an expander ring job cannot be too highly emphasized. Several jobbers' salesmen who sell expander type rings have told us that some of their customers are uniformly successful in obtaining satisfactory jobs with expander type rings while a few shops are uniformly unsuccessful in getting satisfactory results. Since all of the shops in question are installing the same type of rings in the

same general run of cars the difference in success and failure must be in the installation methods.

T WENTY fleet operators or about onefifth of all the fleet operators contributing information use only expander type rings. They install them in both worn and reconditioned cylinders. Seventysix fleet operators do not install expander type rings in new or reconditioned cylinders. Since 60 fleet operators use expander type rings and only 20 operators install expander type rings in new or reconditioned cylinders it follows that 40 operators use conventional



COMMERCIAL CAR JOURNAL




rings in new or reconditioned cylinders and expander rings in worn cylinders.

Adequate oil control can be maintained with expander rings in new or reconditioned cylinders for 32,400 miles according to an average figure taken from the mileages given by 15 operators who have records covering this phase of piston ring work. The lowest figure given was 9000 miles and the highest (Turn to Page 46, Please)

Right—McQuey-Norris' Superoyle ring; Below right—Hastings' steel-vent oil control ring; Left—Burd expander type; Far left—Sealed Power's Statite. Compression and scraper rings are also made in expander types







June, 1936



HE smart truck operator looks at the safety record of his fleet from the economic as well as the humanitarian standpoint. Useless waste of life and limb and useless destruction of trucks are economic wastes which every owner and driver of a motor vehicle should do his part to reduce.

What Decatur Cartage Co. of Chicago did in promoting safety can be equalled by any fleet, provided, of course, that the desire to promote

safety is sincere, and it should be, if for no other than the selfish reason of eliminating costly accidents to one's own equipment.

Our first step in the direction of organized safety promotion was taken in June, 1933. New features have since been added to our program steadily and we are constantly striving to improve our methods of driver training and studying ways to make our equipment safer. That our efforts proved

profitable is shown by the fact that our 1935 accident frequency was 40 per cent less than our 1933 frequency and 10 per cent less than the 1934 frequency. The loss ratio has kept pace with frequency reduction. Our fleet has doubled in size since 1933 giving us a high percentage of new men, most of them with little previous experience. Seventy-five per cent of our equipment are tractor trailer units in long distance work. Our chargeable frequency for

## of Safety-Try a Quiz

Mid-West Fleet's Driver **Questionnaire Sheds Light** on Individual Accident Causes and Indicates What Should Be Emphasized in Safety Education; Cuts Accidents 40% in Two Years

the last six months of 1935 was 1.73 accidents per 100,000 miles. Statistics are kept on the basis of total accidents. Our total mileage for 1935 was about 5,000,000 miles. Based on completed years only, our men drove approximately 5,000,000 accident-free miles between January 1, 1933, and December 31,

W HAT we have accomplished has been done through diligent, hard work, not by some magic formula. Our study of accident contributing factors and safety-mindedness of our drivers was facilitated by a quiz.

We gave every driver in our employ a questionnaire in which we asked about 50 questions relating to proper driving. A study of the answers clearly shows that our educational program has been productive of good results. Eighty-five per cent of the men made passing grades. Considerable interest was evidenced, aided by three cash prizes for the three best sets of answers. Some light was thrown on individual accident records. Education is attempted on the questions most often missed. Some accident causes (TURN TO PAGE 107, PLEASE)

#### How Would Your Drivers Answer These Questions?

- I. How can backing accidents be avoided?
- 2. Name three places where it is unsafe to back up.
- 3. Who is responsible for backing accidents?
- 4. How can right hand turn accidents be avoided?
- 5. Which has the right of way, a vehicle going straight through an in-tersection or one making a left turn? (Vehicles meeting) Why?
- 6. Does a left turn ever have the right of way?
- 7. How far from intersection and from what position in roadway should a left turn be started? Right Turn?
- 8. How do you indicate to other persons your intention of turning left? Turning right?
- 9. Vehicle approaching intersection on your left, does it have right of way if it reaches intersection first?
- 10. Of what benefit to you is legal right of way?
- 11. Vehicle coming fast into intersection on your left, you reach intersection first, does other vehicle have right of way? Why?
- 12. What is your method of driving through an intersection?
- 13. Do you overtake and pass other vehicles in intersections?
- 14. When do you have right of way in crossing a boulevard?
- 15. When does a pedestrian have right of way?
- 16. If you are approaching street from alley or driveway, who has right of
- 17. When is it OK to pass a standing street car? Can you pass on left of street car?
- 18. Name five places where it is dangerous to pass another vehicle going in the same direction.
- 19. What is speeding? 20. Do most accidents occur in cities or
- on the highway? 21. Do most accidents occur in daylight
- or dark? 22. Do most accidents occur in good
- weather or bad? 23. Which movement of vehicle prevails in most accidents; turning, backing, or going straight?
- 24. What parts of your vehicle should be checked before going on the run with it?
- 25. What proportion of accidents are caused by the drivers?
- 26. Do you drive downhill faster than on the level? Do you coast out of gear?
- 27. How can you insure control of your vehicle on a steep down grade?
- do you determine when

- weather and road conditions make it advisable to stop?
- If your motor were governed at 35 m.p.h., how much clear highway would be required to safely overtake and pass another vehicle going in the same direction and maintaining a speed of 20 m.p.h. assuming load, weather, light and pavement conditions to be favorable?
- 30. With reference to braking, what is reaction time?
- 31. With adequate brakes, good tires and dry pavement, what is safe stopping dry pavement, what is sate stopping distance in feet, from following speeds? 15 m.p.h.? 20 m.p.h.? 25 m.p.h.? 30 m.p.h.? 35 m.p.h.? 32. What importance do you attach to the stopping of the stopping distance of the stoppin
- keeping all lights burning on a vehicle at night?
- 33. What lights are required after dark on a parked vehicle?

  34. What advice should you give a sleepy
- driver?
- 35. What is the proper way to park a vehicle to insure it's remaining in place?
- 36. Would courteous actions in driving have any effect on accident causes?
- 37. If a vehicle is overtaking you from the rear and the situation in front might be productive of an accident, what should you do?
- 38. If the other party in an accident were wrong in his actions and you had done all the law required you to do, yet you might have avoided the accident by giving up all your rights, would you be willing to shere the blame for the accident?
- 39. What are you supposed to do in case of injury to other persons in an accident involving your vehicle?
- 40. What information should you secure in all cases of accident involving your vehicle?
- 41. Who adjusts all accident claims?
- 42. Are all accidents reportable?
- 43. What are some of the standard safety appliances used on motor trucks?
- In case of an enforced stop on the highway or alongside it at night what do you do to warn other traffic? In daytime?
- 45. How can accidents be prevented?
- 46. What is reckless driving?
- 47. What causes accident increases when pavements are slippery?
  48. When can you use the left side of
- the road?
- 49. How do you drive in a curve?
- 50. Have you a suggestion for safe
- (If you would like to have the right answers, write the editor and he'll see that you get them.)



M. PRIDE, Safety Director, Decatur Cartage Company, Chicago.

De-

hev

000

Side

how

uip

our per

and

fre-


pace

fleet ving most nce. ment

ance for

RNAL





SHOP MEGHANICS

ARE

At Keeping Records

If They Are Simple

Truck Record Book, Service Record, Job Sheet, Battery Record and Tool Tab Are Forms That Promote Shop Efficiency If They Are Easy to Keep

O successfully handle fleet shop service: keep records, avoid lost time, save steps, care for tools and equipment, make accurate charges, keep stock in dependable state, do the work that pays, watch purchases for discount savings, that's the way to manage the fleet shop for profit. Reducing shop practice to the simple formula of keeping simple records is the first step in making faithful hands of shopmen and in promoting their efficiency.

Methodical line-up of all activities makes this path to profits easier. A

division-of-labor schedule for the day must be worked out. Our service shop takes care of the gas, oil, water, air, greasing, washing, polishing, top dressing, tire work, brake work, body repairs, tune-ups, and every other service job that can be efficiently done by us. Complete paint jobs, machine shop work, special electrical jobs, radiator and new body jobs are sent out.


Working time is carefully proportioned. Men are carded and a punch clock does the accounting. Four men service 17 trucks and eight passenger


By BILLIE BURGAN Hage's Ice Cream Co., San Diego, Cal.



m an to

COMMERCIAL CAR JOURNAL





cars and do some plant work, too. A fifth man is employed two or three weeks every 60 days for polishing and touching up damaged finishes. Division of labor is as follows:

One man on at 7.30 a.m. Off at 5 p.m. Off Saturday afternoon.

Two men on at 8 a.m. Off at 5 p.m. Work Saturday afternoon.

One man on at 9 a.m. Off at 6 p.m. Works Saturday afternoon.

All have 1 hr. for lunch. The early man cleans shop and wipes up oil spots as this is the only hour in the 24 that the garage is clear enough for such work.

Service procedure is routinized so that each man knows what he has to do from day to day. Managers' and salesmen's cars receive first attention. They are washed, dusted, filled and parked to go. By 10.30 a. m. all light car service is complete. Starting here, trucks are coming in, and on through the day until at 6 p. m. when all are washed, serviced and parked in their stalls. Trucks begin departing at 1 a. m. and by 7 a. m. all except two reserve trucks are en route.

THE service plan. A positive distaste for writing by shop men causes us to think and plan in terms of little writing. For instance: instead of writing a service description on the record, a mechanic writes only a date in the

space provided for each service to tires, batteries, greasing and inspection, and drainings.

Drainings are on the even thousands, as 2000, 4000, 6000 and so on, and the date is written in red.

To make it easy to remember, we use the truck number as the date for inspection and greasing. No. 1 on the first of the month, No. 2 on the second and on through.

Service batteries on Tuesday-tires on Thursday of each week.

Garage daily report. To charge out gas, oil, grease, and hours of labor only the amount is written in the space for it on the truck number line on the daily report.

Parts and material charges. A bill of parts costing more than \$1 is by requisition, less than \$1 is by cash . . . saves bookkeeping.

A monthly memorandum charge sheet shows items taken from garage stock. An entry on this sheet would carry our truck number, date, item and price.

Accounting department posts from this sheet. It takes the place of many small invoices each month and saves time for both office and garage.

A "want" pad is used to note items running low which helps to keep stock in dependable state.

Keeping records. A year page for every car in the fleet is in this book and in the service file. Entries in this book consist of dates, names of materials, prices, speedometer readings, sources of supply names, brief job descriptions, paint jobs and prices, body weights and sizes, load descriptions, sizes and weights.

This is really the "fleet journal" because first entry of anything of more than passing importance is entered here for reference. Later such items as tires and brake linings are pasted to the current service record in the file containing service information.

(TURN TO PAGE 38, PLEASE)

June, 1936

OES it really pay to vulcanize a truck tire?"

"I never have any luck with repaired tires."

These are the familiar remarks of many fleet operators. My answer is definitely, "Yes." Most of the Pacific Highway Transport Co.'s 115 trucks are equipped with 9.75/20 tires and the average mileage of all 9.75/20 tires we scrapped during the year 1935 including several whose useful life came to an abrupt end through some accident, such as being run flat, etc., was 57,513 miles, operating over West Coast highways. The greatest mileage received from any one tire was 113,423 miles and the least was 21,071. They ran an average of 19,026 miles before being repaired and 38,487 miles after being repaired. One section job ran 99,752 miles. Of course some of the tires would have run some distance more without necessarily having to be repaired at that time, but



Above—Tireman Criswell holds the matrix used in vulcanizing the tire shown at the left. Opposite—Draftsman's details of the vulcanizing process described in the story. Left—A corner of the shop where Criswell performs his tire operations

## The Value of Vulcanizing


we find it a good policy to repair all cuts of any size as soon as possible. On the other hand, any number of tires would have been practically worthless after the first few miles, if they had not had sections put in them. For instance, a year ago we purchased some new semi-trucks and trailers equipped with 9.75/20 tires. One truck had run but 387 miles when it picked up a broken spring leaf in one of the rear

tires. A section was put in the tire and it was put back in service in its original position on the truck. It ran 29,-637 miles on the rear wheel of the truck and was then shifted to the semitrailer. To date it has run 42,175 miles. This tire would have been a total loss after the first 387 miles if it had not been repaired as the hole was too large to have been held by a boot.

These tires that give us such good

mileage are all repaired and vulcanized in our own shop. The vulcanizing shop was installed with the idea that if it paid to repair one's own trucks, why not tires?

I was placed in charge of tire maintenance and my only instruction was. "Make the tires pay a dividend, we know nothing about them." In order to determine whether the tires were paying a dividend, it was necessary to



TIRE-DOCTOR CRISWELL of Pacific Highway Transport makes injured tires pay dividends by performing a special operation in which a cavity in the tire plug permits flexing of the vulcanized section. This eliminates the possibility of separation between the rubber plug and skived ends of the ruptured cords. Here in detail, is his method, which adds miles to tire life.

Is in the Method

keep a complete record of each tire as to mileage and cost of repairs. Therefore, I branded each tire with an individual number and installed a card system. I started in on the theory that if tires were carefully inspected and cuts were promptly repaired before they had an opportunity to enlarge and for separation to set in, the tires would last much longer.

I repaired every cut of any size

for a while and then after they had run about five thousand miles, the spots began to peel out or the section jobs to blow out. I became quite alarmed. The tires which blew out were practically a total loss. I thought possibly my work was at fault, so I sent several tires out to other shops to be repaired, but their work proved to be no better than my own. I visited other repair shops, studied and tried all of the ap-

proved methods of repairing tires but to no avail. I came to the conclusion that the best thing to do was to let the tires run as long as they would without molesting them or if they were cut entirely through to just put in a boot. The trouble with that was the cuts enlarged rapidly and eventually the tire wore out at that spot while the rest of the tire was in fair condition. The desired dividends lay in the yet good portion of the tire that had to be thrown away. I reasoned there must be some way to put in a repair that would last as long as the rest of the tire with a small percentage of failures.

A TIRE with a fairly large cut through it backed by a boot seldom blew out. The reason is that the open cut is allowed to flex freely without friction. I dissected all section jobs which blew out and discovered that invariably there was separation between the rubber plug and the skived ends of the ruptured cords. This separation caused friction which developed heat. The heat caused the repair to blow out by softening the rubber and disintegrating the cotton fabric or cords. The solid rubber plug and the cotton fabric of the carcass are of essentially different texture, therefore, it is impossible to have the flexibility, compressibility and resiliency of the two the

The ideal repair would, therefore, in-



corporate the desirable frictionless properties of the open cut and yet have the ruptured ends of the cords sealed against the intrusion of the destructive elements, water and sand. I began to experiment and eventually developed

(TURN TO PAGE 66, PLEASE)

JUNE, 1936

e matown at details bed in e shop ire

anized g shop

mainn was, d, we order were

ary to

HE idea of training drivers to administer first aid to the injured on the highways is rapidly gaining ground among fleets because of its good-will promoting features. This opportunity to make drivers safety conscious and at the same time perform a public service and gain public goodwill is available to all fleets both large and small through the Red Cross which has skilled instructors ready and willing to train drivers in first aid methods at no cost to the operator.

Here is the first of the driver first-aid stories describing how drivers for the Theo. Hamm Brewing Co., Milwaukee, were so well trained in first aid that they had only two accidents in 1935, gave first aid to 500 injured, saved three lives directly and 20 lives indirectly and won the gratitude of the public and state officials and the highest awards from the Red Cross.



# TRUCK DRIVERS

Trained to Administer

HAT American truck operator equalled or excelled the safety record made by the Theo. Hamm Brewing Co. fleet in 1935? The St. Paul, Minn., Hamm fleet attained a total of 852.000 miles during 1935 and had only two accidents!

In addition to that Hamm drivers and helpers gave first aid in some 500 minor injuries, gave vital first aid treatments in 20 serious road accidents and were directly responsible for the saving of at least three lives, although it is likely that many more were preserved.

One Hamm driver has been awarded

Tirst Tid

Win Goodwill of Public

a life-saving citation by the American Red Cross.

The Hamm fleet has received the highest recognition from the Minnesota state industrial commission for the high record of safety obtained. Safety di-

rectors, safety publications, newspapers and many other officials and organs interested in safety have given great praise to the Hamm operation.

By PAUL SCHULER

Director of Transportation and Safety,
Theo. Hamm Brewing Co., St. Paul, Minn.

att

be

niş

qu

ser

of

an

niş

SCI

ca

ba

Ju

It all began in the basement of the Hamm garage. There, a first aid school

COMMERCIAL CAR JOURNAL



Above—Driver Walter Lemon points out the "first-aid" sign that is on every truck in the Hamm fleet. He is holding a first-aid kit and on his sleeve may be seen both the American Red Cross insignia given to graduates of the first-aid training school and the symbol of the Hamm Brewing Co. Opposite page shows two Hamm drivers administering first aid. A tourniquet has been applied to the arm of the victim and a bandage about his head. The miniature street intersection and models are kept in the office of Safety Director Schuler for the benefit of drivers who have had accidents

meets five nights each week. Any employee of the Hamm organization may attend the school, but attendance and graduation is compulsory for drivers and helpers. Each man attends only one night a week, but so popular has become the first aid course that it is necessary to operate the school five nights a week.

The preliminary first aid course requires attendance one night a week for 11 weeks. The advanced course requires attendance one night a week for seven additional weeks.

Since the school was started, a total of 332 Hamm employees have attended and been graduated. At present there are an average of 30 employees in each nightly class. It is easy to be seen that first aid is a popular subject.

The truckmen are given the prescribed first aid course which includes practically everything a trained layman can do to preserve life and limb at the scene of an accident.

It is just as important for our driver to know that a man with an injured back must not be moved by inexperienced men as it is for them to know how to apply artificial respiration or digital pressure on a flowing wound.

The school room is a dequately equipped with charts, diagrams, dressings, splints (rough and finished) of all sizes, manufactured and improvised litters and all manner of devices and apparatus for caring for the ill and injured. Students are required to apply dressings, treat the "drowned," carry the injured and meet practically any "emergency" that they might encounter on the highway. When they finish the school they are thoroughly trained in first aid and are given an American Red Cross First Aid chevron to sew upon their left sleeve.

An interesting example of the thoroughness of the school is found in the little "one man play" each driver is required to stage before his fellow students. He must assume the role of a driver, at the scene of an accident, telephoning for a doctor. The student is handed a telephone and he goes into action. He "tells" the doctor on the other end of the wire, exactly where the accident has taken place, where the patient or injured person is at the moment, what the nature and extent of the injuries are, what first aid has

been administered, what medical supplies are on hand—and the doctor must hang up first. If the driver terminates the conversation he makes a grievious error and is immediately hopped on by instructors. Also the driver should have had someone else make the call so he could devote all his time to the victim. And a patient who complains of bad pains must not be moved.

On the front and rear of every Hamm truck is a metal sign saying "In case of accident stop this truck-driver first aid trained and equipped." The sign means what it says. If you're in a highway accident and a Hamm truck comes into view, you have the right to stop that truck and demand that the driver help you-but you won't have to make the demand. The driver is under orders to stop and help and even if he wasn't under orders, he'd stop and help anyway. Because he's safety minded and he's first aid minded. He'll stop anywhere and do anything to preserve life and limb. Best of all, he knows how to work in such an emergency. Moreover, each truck is equipped with a complete first aid kit.

(TURN TO NEXT PAGE, PLEASE)

June, 1936

1C

news

s and

given

of the school

URNAL

on.

TRUCK

Trained to Administer

Win Goodwill of Public

Right—First-aid dispensary in the Hamm Brewery. It contains every first-aid facility. Circle—Driver Patterson, whose quick administration of first aid saved a girl's life, and won for him a life-saving award from the Red Cross. Below—Hamm drivers demonstrate a proper three-man lift designed to prevent complicating internal injuries



There are two outstanding cases on Hamm records where drivers saved human lives.

The hero of one was driver Benjamin J. Patterson. Patterson was going his daily rounds when he came upon an automobile accident. One Florence Pollock of Fargo, N. D., lay on the roadside. Her jugular vein and mastoid muscle had been severed. Patterson immediately applied digital pressure and took other first aid measures to prevent shock. It was an hour before a doctor arrived at the scene. When the doctor did arrive, he called Patterson's work "professional." The girl is alive today. Her letter, in Paul Schuler's office, states that Patterson saved her life and indicates her gratitude. The American Red Cross cited Patterson.

The other case is somewhat different. One cold wintry morning, two Hamm drivers arrived at the garage a little ahead of time. They noticed a big sleeper-cab truck parked outside and, for a moment thought nothing of it.

It was a foreign truck, probably a long hauler coming for beer. But finally, one of the Hamm drivers thought he would awaken the truck drivers and tell them that the brewery was open for business. As he swung open the cab door, he noticed that the motor was panting quietly and that both men in the cab were asleep.

Then, in a flash, the Hamm driver noticed something else. Both sleeping men had splotchy red spots on their faces. Instantly the Hamm driver knew that both men were suffering from carbon monoxide poisoning-fumes in the closed cab had gotten into their lungs. There was instant action. Six or seven other Hamm drivers whipped into the job of bringing those two truckmen back. They got them out of the cab, gave them artificial respiration, washed their lungs with oxygen, gave them back their lives. Both truck men were back on thier jobs that afternoon, still frightened at their close call, but filled with undying gratitude for the training that is given all Hamm drivers.

The Hamm drivers find daily uses for their training. Not a day passes but one, two or three, sometimes more, will administer First Aid to some injured person. In fact, there is a little slotted box—on the way to the showers—for reports of first aid treatments.


They take pride in their work. They take pride in keeping themselves out of accidents and helping out others who are in accidents. Of course we give them a cash bonus for driving without accidents and we also give them an engraved gold plate recording their accident-free service. But those things are not necessary. They want to drive safely and they want to provide safety and health for others.

It is true that our workmen's compensation costs were reduced 15 per cent in 1934 and 20 per cent in 1935—and that saved the company money—but the biggest thing we get out of it is knowing that our own people are not getting hurt and that they are helping others.

Every truck company should give its drivers First Aid training. Every salesman who travels by car, every service station attendant, in fact everyone should be given this training. It's simple and inexpensive to do—and the American Red Cross will help any company that is so inclined.

NOW, let us see what is behind such a successful safety operation. In the first place, of course, there is William Hamm, Jr., president of the company.

(TURN TO PAGE 36, PLEASE)



# Gives Motor Freight CLASSIFICATIONS the Malyree

A Constructive Criticism of Representative Truck Classifications Reveals Good and Bad Features

By RALPH L. WOODS (Industrial Traffic Specialist)

AFTER several weeks of work with and study of the new truck classifications and tariffs filed with the Interstate Commerce Commission one is not able merely to say that they are good or that they are bad. In truth, they are both. One publication cheers, another saddens. One inspires admiration, another induces disgust. One is easy on the eyes and brain, another is

irritating. About the only generalization that safely may be hazarded is that a large and important step has been made by the trucking industry, and that for all its defects the present setup has a distinctly encouraging flavor.

In assuming the role of commentator and sometime critic I am not unmindful of the great readjustment that has been demanded of the trucking industry. of the conflicting interests that had to be compromised, and of the lack of formulae and definitely fixed objectives in the establishment of rates, rules and regulations for transportation by motor truck. However, a keen appreciation of these difficult circumstances does not preclude a critical examination of the results and suggestions for revisions.

WHEN the first MF ICC No. 1 reached my desk in late March, I had no definite ideas how the new truck tariffs should be. Of course, like most industrial traffic men, I had hoped they would not duplicate the errors and frequent absurdities of railroad tariffs. I really expected that they would be more simply constructed and readable.

The first new tariff that I examined produced my first disappointment. It was the National Motor Freight Classification. Although it is not difficult to use and interpret, and in spite of the fact that it is certainly comprehensive, still it did not meet my expectations. No doubt the fact that the American Trucking Association sponsored this publication led me to expect a classification that would not hesitate to de-

(TURN TO PAGE 78, PLEASE)

re, in-

tle ers its. ney out

ers

we

ing

ive

ing

ose

ant

ro-

omper

fit

not

ing

ive

ery

ser.

one

It's

the

any


uch

the

am

ny.

NAL



#### The Whole Truth About the Railroad Safety Record

E really dislike to throw sand in the railroads' journal-boxes on the subject of safety, particularly since safety is a matter in which conscientious effort, even if unaccompanied by accident reduction, is deserving of the highest commendation. And we wouldn't toss these scoopfuls of sand if it were not that the railroads have been guilty of a singularly vicious attempt to take unmerited credit while holding up highway transportation for scornful comparison.

The plain fact is that the safety record of the railroads is not what they would have you believe it is. The paid advertisements in the newspapers early this year, declaring that not a single passenger had been killed in a train accident during 1935, represented the statement of a partial fact, cleverly designed to create an impression with the public that the railroads had a perfect safety record while highway vehicles were killing thousands. This is slick propaganda of the type for which railroads have become notorious. It is the effect of this propaganda that we are out to wreck because even safetyminded representatives of the trucking industry are getting into the habit of blowing the railroad whistle by pointing to these sworn enemies of highway transportation as shining examples of safety perfection.

#### 4889 Killed; 16,591 Injured

THE raw fact is that the railroads' safety record is in serious collision with perfection. It may knock you off your seat—as it did us—to know that in 1935 no less than 4889 persons were killed and 16,591 were injured in what are described in official reports to the Interstate Commerce Commission as "train accidents and train-service ac-

cidents," a distinction that we shall comment upon presently. These figures, which are an increase over those of 1934, represent the true accident record of the railroads so far as trains are concerned.

Now the railroads, mind you, were not stating an untruth when they blatantly called the public's attention to the fact that no passengers were killed in train accidents. The I.C.C. record corroborates that statement if you will regard leniently the fact that one was killed when a heater in a standing train exploded. But not until you study the book of rules governing the filing of statistics do you realize what opportunities there are for juggling facts and polishing half-truths to bedazzle the public

#### Two Kinds of Accidents

RAIN-SERVICE accidents resulted in 17 persons killed and 1505 injured. To the layman the terms train accident and train-service accident represent no difference. The actual difference may be said to represent \$1 because, according to the rules, if the damage to equipment is less than \$150 it is a trainservice accident and if more than \$150 it is a train accident. If the records had been reversed, that is, if the train accidents had resulted in the 17 passengers being killed, and no passengers had been killed in train-service accidents, there can be no doubt that the railroads would have advertised their train-service perfection and conveyed the same impression to the public.

#### Dead But Not Killed?

So that, speaking honestly, 17 passengers were killed and 1505 injured on the railroads in 1935. But even that

may not be the actual whole truth so far as fatalities are concerned. Let us explain. In computing highway accidents, the terms used are "deaths by motor vehicle" and "injuries by motor vehicle." In other words, whether a person is killed outright or dies some time after the accident he is a "motor vehicle death." It's different on the railroads. The book of rules defines "killed" as a death that occurs within 24 hours after the accident. Presumably, if a passenger should die 24 hours after an accident he has not been killed in the railroad statistical sense, and therefore not recorded as a fatality. We need not enlarge upon this point to show the opportunity for making unfair comparisons with statistics of competing forms of transportation that attempt no evasions in computing actual fatalities.

That disposes of the passenger angle which the railroad advertisements dished up so invitingly to the public. But what about the thousands of employees, the so-called trespassers and non-trespassers, and the motorists who were killed or injured by and on the railroads? Are they to be ignored in appraising the safety record of the railroads? Of course not. It is counted against trucks if a driver, a rider or a jaywalker is killed or injured.

The facts here (aside from the passenger angles) are that in train accidents 238 persons were killed and 689 injured in 1935, and in train-service accidents 4633 were killed and 14,030 injured. Of these totals 1680 were killed and 4658 injured in highway grade crossing accidents. The statistics are not to be minimized on the latter score. Admittedly there is difficulty in placing the responsibility for gradecrossing accidents, but there is also difficulty in placing responsibility for motor vehicle pedestrian accidents although the results are always recorded against the motor vehicle. Moreover, the railroads are not entirely innocent of negligence in grade-crossing accidents and consequently must accept the results as a reflection on their safety record.

#### Railroads Are Negligent

THIS negligence was never more competently portrayed than at the recent Interstate Commerce Commission hearings on the subject of installation of mechanical stokers on railroad locomotives. Twenty-five or 30 railroad firemen testified and their statements disclosed that fast passenger trains constantly are running on a chance-taking basis because overworked firemen are

(TURN TO PAGE 48, PLEASE)



# With KEESHIN

Bringing You Up to Date On the Pace-Setting Plans of the Country's Largest Motor Freight Operation

#### By GEORGE APPLEGREN

An Authorized Interview With John L. Keeshin

FFICES of the Keeshin Motor Express of Chicago are thinking in terms of two, three, five and ten years hence. The things they are doing now, and the things they are planning to do, those about which John L. Keeshin tells, are all weighed in the sense of their adaptability to future performance.

At the rate which the Keeshin parent organization is growing it is sometimes difficult to lay plans on a firm foundation—but it has to be done. The front office in Washburn Avenue in Chicago doesn't issue many commandatory orders, believing that department heads can get along best by doing their own thinking and working out their own solutions, but this is one rule which did come from there and from which there can be no exceptions.

Ordinarily, when writing about a trucking concern statistics can be used

with reasonable assurance that they will stand up at least until the article appears in print. Statistics with the Keeshin outfit vary every day. The best thing that can be done is to give them as for the present, and then say

that they will all be doubled, or more than doubled before two years have passed.

As examples:

THERE are approximately 17 trucking lines affiliated with the Keeshin organization today. Petitions to acquire four more were placed on file with the Interstate Commerce Commission recently. Hearings on three petitions are scheduled in various parts of the country. There is no secret about the fact that Keeshin agents are dickering to acquire additional lines.

The Keeshin black triangle of "Dependable Service" emblazons some 80-odd terminal depots today. Another month should see that number swelled to more than a hundred. If present plans work out, as Mr. Keeshin explained them, two years should find the black triangle flying over at least 200 depots.

One of the things which is occupying considerable attention in the Keeshin offices right now is the problem of shorter runs to serve advantageous points between present termini. These in-between centers are called control points. Much progress has been made on this throughout Pennsylvania and other New England industrial states.

The Keeshin system employs more than 2,500 persons over the 17,000 (Turn to Page 72, Please)

Above — Architect's drawing of the new Keeshin terminal, now under construction in Chicago, 1000 ft. long, 300 ft. wide with two loading platforms to accommodate 268 trucks. Since this drawing was made, new plans call for a third floor to the right wing. Right—This is one of 85 camel-back trucks recently purchased by Keeshin for pick-up and delivery service



i

a e r e e s n n - r s d d e to n -

n-

t

al

le

ts

n-

nd

10

he

in

il-

ed

ci.

89

ce

30

re

ay

ics

ter

in

de

lif-

for

al-

ed

er.

ent

ci-

the

ety

ore

re-

ion

ion

co-

oad

nts

on-

ing


are

NAL



1. BROCKWAY may well be proud of this truck built for Cobako (Cortland Baking Co.), Cortland, N. Y. Chassis is a special model 160X, five-ton on a 240-in. wheelbase powered by a 95-hp. engine. The body, designed and built by Brockway, is 22 ft. 7 in. long, 8 ft. wide and 81 in. high. Upper panels of the body are of duraluminum. Interior is fitted with racks to accommodate 5500 standard size loaves of bread in 193 trays. Weather-tight compartments in the skirt in front of the rear wheels carry five 20-loaf trays. Rear doors are controlled by a spring lifting mechanism and are equipped with hydraulic snubbers and can be opened wholly or partially. A rear step closes flush with the body. Special equipment includes directional signals, illuminated front sign, exhaust-operated sand equipment for rear traction on icy surfaces, etc. The lettering in the rear is studded with reflector buttons.

2. DODGE says it with flowery colors. Inpressed panels are pale lavender and the rest of the body and hood are finished in two-tone orchid and purple shades. Copper plating has been used on all parts and ornaments. Cab compartment is integral with the body which is insu-



up fo



lated with Dry Zero throughout. The floor has metal skid strips. Double doors are at the rear, and a special door on the curb side permits easy handling of small flowers. A raised screen shelf in the interior also facilitates handling of small packages.

3. WITH this Fruehauf semi-trailer and IHC chassis, the Olson Transportation Co. can add the words "in style" to the sign lettered on the side of the van. The "semi" is a Model 723 DF with 20,000 lb. capacity. The name of the operator on the nose of the trailer is outlined with reflector buttons, so going or coming you can't miss seeing this nifty job on the highway.

4. HIGHWAY Trailer designed and built this "semi" job for hauling grain to rural districts from the granary and also to haul flour to outlying towns. It's a model 77-B, 20-ft. frame. The steel body is 20 ft. by 8 ft. by 5 ft. with open top. Tarpaulin rack is on the nose of the trailer. Cab is de luxe. Chassis is a Federal.

5. TRAILMOBILE trailer model TD-22, Highland body and Diamond T chassis model 212 present a united front and Kay Bros. presents this advance unit in advance of its circus. It totes publicity and billboard men. Trailer has two sleeping berths for the billers, storage place for placards and other advertising material, a work bench and desk and typewriter. The wilder (shall we say?) animals are carried in other trailers of this motorized circus.


6. UNLIKE the "One Hoss Shay" this unit looks as though it were built to go on forever—and never fall apart. Tractor is a model IW-865 Studebaker. Edwards Iron Works built the trailer and body. The A-5 trailer is 24 ft. long. Body has solid roof, double doors and tailgate in rear. Cab is also an Edwarda de luxe type with sleeper compartments. Illumination of trailer is by shielded lighting from the top.

7. MAREMONT Automotive Products built this refrigerator body for Cudahy. It is refrigerated with dry ice to maintain a temperature of 35 deg., and is insulated with 2 in. of Dry Zero in the roof, walls and floor. Inside dimensions are 11 ft. long, 74 in. wide and 66 in. high. Chassis is a Reo.

8. THIS is a Four Wheel Drive job of 13,000 lb. gross operated by Whiting between its plant and shipping base in Wisconsin on scheduled trips of 60 miles each. Fair weather or foul means nothing to this baby. It has the good appearance and the power to hold its own under all circumstances.

9. COLUMBIAN Steel Tank Co. designed and built this unusual combination tank and bulk hauling semi-trailer. The lower section is a tank for carrying 2500 gal. of fuel, while bulk products may be carried in the apper section. Lux-Witwer Wholesale Grocery of Topeka, Kan., uses it for hauling the fuel and groceries, thus carrying payloads going and coming. A tarpaulin keeps out the rain.

10. EASTON Car and Construction Co. are the builders of this dump body and Autocar is the packhorse (chassis to you). Body is a model GS side dump quarry body. Sides open out and the load slides off neatly. Chassis is a model UNFT, 96 in. wheelbase, 43,000 lb. gross. Operator is Pennsylvania Glass Sand Corp.




M ODERN styling comes in for special emphasis on the new Model EH, announced by Mack Trucks, Inc., which rates at 18,000 lb. gross and lists at \$2,250. Creased fender design with high valleys between the hood and fenders, a V sloping chromium-plated radiator grille, extensive use of chromium plating and de-luxe streamline cab with sloping windshield are among the features contributing to the pleasing design. The cab roof is built integral with the cab of all-metal construction. Safety glass is standard.

Model EH is offered in standard wheelbase lengths of 146 in. and 158 in. for the truck and 139 in. for the tractor chassis, with optional lengths at extra cost. Gross weight distribution of approximately 30 per cent front and 70 per cent rear has been achieved through set-back front axle design; the front axle being but 74 in. ahead of the rear of the cab.

A six-cylinder Model BG engine with a 35% in, by 5 in, bore and stroke, develops 79 hp, at a governed speed of 2300 r.p.m.

Drive is from a single-plate clutch through a five-speed unit transmission. An overgeared fifth speed is available at extra cost. Rear axle is of the



Model EH rates at 18,000 lb. gross and lists at \$2250

#### New Mack Model EH Has "Doggier" Look

single-reduction, spiral-bevel type, with double reduction drive at extra cost. The driveshaft has three needle-bearing universal joints with a large self-aligning center bearing. There are 6 optional ratios on the single reduction drive, ranging from 4.40 to 7.40; two ratios of 7.35 and 8.21 on the double reduction drive.

Four-wheel hydraulic brakes are vacuum booster actuated. Total foot brake area is 370 sq. in. The chassis frame is 8½ in. x¼ in. x 3¼ in. It is staunchly braced by three, pressed steel, deep-flanged box girder cross members with alligator jaw attachment to the side members, and two channel cross members.

## New Ross Gear for Better Steering


THE new Ross Twin Lever steering gear manufactured by the Ross Gear and Tool Co., Lafayette, Ind., provides a greatly increased mechanical advantage for the driver. Steering linkage changes made possible by the application of the new gear, approximately double the ability of the driver to turn the front wheels in the parking ranges. Reversibility is minimized by large reduction of motion.

The angular arm travel is 100 per cent as compared to 80 per cent on the present Ross gears. Shorter turning radius can be obtained without sacrificing steering ease as greater lateral travel of the drag link may be obtained without lengthening the steering arm. This feature is desirable for maneuvering trucks in traffic areas.

Shorter steering arm is made pos-


sible by the greater angular travel available. This results in greater mechanical advantage for the driver and minimizes shock on the steering gear and the driver due to impacts against the front wheels. In the normal driving range two studs are in engagement with the cam as compared to a single stud on previous designs, reducing unit pressures 50 per cent. As the gear moves away

from normal driving range into parking range, the usual single stud is in working position. However the effective leverage of the single stud in-



Twin lever steering gear with 45 per cent more leverage

creases rapidly under this condition and in full parking position the effective leverage is 45 per cent greater than in present Ross gears.



ALL truck operators don't like the same kind of engines—or the cab and body styles—or the same wheelbases—or the same sort of axle equipment. Make all trucks alike and buying would fall off enormously.

All truck operators don't like the same kind of stopping.

But the FACT remains-

Thousands upon thousands of truck and bus buyers **do** demand Hydraulic Braking. For more than a dozen years Hydraulic Braking has been winning new friends year after year, as service proved conclusively the soundness and enduring good performance of Hydraulic Braking.

Car, truck and bus manufacturers in every price class—high, low and medium—have swung to Hydraulic Braking. The wisdom of their judgment is reflected in the sales records of their products.

HYDRAULIC BRAKE COMPANY
DETROIT, MICHIGAN

# LOCKHEED HYDRAULIC Four BRAKES Wheel

OFFICIALLY SERVICED THROUGHOUT THE NATION BY WAGNER ELECTRIC CORPORATION

### New Products on Parade

Descriptions of the Latest Items Put on the Truck Market by Equipment and Specialty Manufacturers

#### S-M Brake-Dokter

THE Stiles-Medart "brake-dokter" grinds relined brake shoes to fit drum surface at all points and the wheels may be replaced as soon as grinding is complete. A universal double-acting adapter instantly fits all front spindles and tapered rear axles. A special adapter quickly mounts on all full-floating axles and truck spindles. The unit will centralize, grind, and adjust brake shoes to exact drum size on the vehicle in one operation, reducing the time for this operation by one-half, the maker claims. Stiles-Medart Co., 3535 DeKalb Avenue, St. Louis.

#### Model G Jenny


HOMESTEAD Valve Mfg. Co., Coraopolis, Pa., is now marketing a new Hypressure Jenny, Model G, which operates on the same principle as previous models, but is more compact and smaller in design. Cleaning is accomplished by forcing a combination of water vapor, hot water and cleaning chemicals through a nozzle over a pressure range of 50 to 150 lb. per sq. in. The unit is mounted on rollers and may be easily moved from place to place. Price is \$395.

#### Steel Grilles

GALVANIZED steel rolling grilles are the product of Cornell Iron Works, Inc., 3600 13th Street, Long Island City, N. Y. Rolling grilles lock into channel-shaped side guides at the jambs and will resist a pressure of over three tons per foot of height. The grille shown is motor operated with straight bar design harmonizing with the brick. It raises by coiling around an overhead shaft and may be either hand or power operated. An eight-page catalog of illustrations and descriptions of grilles is available.

#### **Watson Transmission**

H. S. WATSON CO., national distributors for Watson-Brown-Lipe auxiliary transmissions, announces a new auxiliary transmis-




Brake Doktor grinds relined shoes



Smaller and compact Model G Jenny

Galvanized steel grille rolls up



sion designed especially for all makes of 1 to 3-ton trucks. It is said to have a more powerful underdrive ratio than is generally available on trucks of this size.


This new transmission when installed behind the usual 4-speed transmission, provides eight forward speeds. The auxiliary ratio is 1.96 to 1. It is said to be priced lower than similar equipment previously offered. This unit is adapted to special short-haul trucking jobs where power, or slow travel is necessary. H. S. Watson Co., 522 Fourth Street, San Francisco.

#### Handy Oil Filter

A NEW oil filtering and conditioning system is being marketed by the Handy Governor Corp. of Detroit. This Handy oil conditioner uses a purifying element known as Percolite, a special fibrous compound. It removes abrasives and other foreign materials, neutralizes acid, etc., so the manufacturers claim. A drain permits emptying the water and other materials thus collected. The chamber containing the filtering element is assembled in the form of a cartridge, renewable when found necessary to do so.

#### [Other Products Page 32]

Handy oil filter and conditioner



COMMERCIAL CAR JOURNAL



Wilkins Rogers Milling Co., Washington, D. C.



Hazle Milk & Ice Cream Company, Hazleton, Pa.



Chambersburg Branch of Capital Bakers

oil

nd. gn he

its als ing

ind

#### These four fleets, totaling 614 trucks, give proof that Exide Batteries cut costs . . .



Georgia Power Company

TERE are four representative operators—with H trucks of various types, used in widely different kinds of service-who agree on one important fact: You can't buy a more economical battery than an Exide.

Exides are rugged, well-built batteries that give thousands upon thousands of miles of trouble-free service. They mean freedom from costly tie-ups, dependability on short hauls or long, in winter and summer alike . . . but you pay no premium for the extra quality of an Exide.

It has been the experience of hundreds of others, as it can be your own experience, that the way to cut battery maintenance costs is to standardize on Exide.

THE ELECTRIC STORAGE BATTERY CO., Philadelphia The World's Largest Manufacturers of Storage Batteries for Every Purpose Exide Batteries of Canada, Limited, Toronto



**BATTERIES FOR EVERY TYPE TRUCK** 

#### **NEW PRODUCTS ON PARADE**

#### Governor for Light Trucks

CHICAGO GOVERNOR & MFG. CO., 507 South Laflin St., Chicago, is now marketing an inexpensive, highly efficient keytype governor, suitable for salesmen's cars and light delivery trucks of all makes carrying loads not exceeding 1 ton.

This governor is cut down to the small-



Chicago governor for light trucks

est dimension so it fits in easily between the carburetor and the manifold and can be installed in a few minutes. It has a speed range of from 20 to 50 miles. The adjustment is made with the key which is removed when the proper speed adjustment has been made and then the governor is sealed to the stud to avoid tampering. The retail price is \$3.25.

#### **Dietz Pilot Signal**

THE new Dietz "Pilot" direction signal employs four separate arrow lights, one at each corner of the vehicle, front and rear, thus presenting a clear warning to vehicles approaching from either direction on the road. The driver's control of this signal is a small metal box containing switch, fuse, relay and a pilot light. This is attached to the steering post, under the wheel. R. E. Dietz Co., New York City.

#### Lisle Rod Aligner

CONNECTING rods can now be aligned and straightened in less than two minutes according to the Lisle Corp., Clarinda, Iowa. All rods up to 15 in. long can be handled by the new Lisle aligner, the



Aligner for rods up to 15 in. long

cradle moving backward and forward on ways, and adjustable to any length rod. Twist and bend can both be checked from one setting, without removing the piston assembly, and without removing the rod from the aligner. Any inaccuracy in the rod may be instantly registered on the gage.

#### **Power Take-Off Unit**

THE Sullivan air compressor especially designed for truck mounting and truck operation, is of two-stage air cooled design with air cooled intercooler. It is for mounting on a 1½-ton chassis.

A Hercules split-shaft power take-off


makes available all the horsepower and torque of the truck motor. Power take-offs are in wide use in the operation of electric welders, rock crushers, grinders, core drills and other equipment. Contractors, utilities and municipalities will find this outfit especially valuable. Hercules Steel Products Co., Galion, Ohio.

#### King MT-250

THE Electric Heat Control Co., Cleveland, announces a new unit, the King MT-250, which is a combination of the King MT-210 ignition tester, with the exhaust gas analyzer added. It is claimed that the exhaust gas analyzer will indicate whether maximum power is being obtained from the fuel, and if not, where the trouble lies.

#### **Vacuum Tester**

THIS vacuum testing outfit is a time-saver in locating leaks in the vacuum system on trucks and trailers as well as in determin-




Vacuum tester for locating leaks

ing the amount of vacuum developed by the motor. The outfit includes an accurate vacuum gauge, a length of hose, and an assortment of fittings sufficient to make almost any connection. Vacuum Power Equipment Co., Detroit, Mich.

#### Oxweld Type CW-22

A NEW oxy-acetylene cutting attachment known as the Oxweld Type CW-22 has been announced by The Linde Air Products Co., 30 East 42nd Street, New York City. This new cutting attachment handles light sheet metal as well as all but the heaviest work at speeds and efficiency equal to those of the full size cutting blowpipe. The Type CW-22 cutting attachment can be used on




Oxweld for light sheet metal

either the Oxweld Type W-17 or W-22 welding blowpipe handle.

#### Cooke Nut

IN place of the usual six adjustments per turn, the Cooke micro-slotted nut offers from 10 to 22 adjustments depending on the size. This is accomplished by locating



Cooke nut has 10 to 22 adjustments

the keying wedges off center from one another, so that two keying positions are possible for each slot. A special key is supplied with each nut, the key being trimmed off to an internal V-shape so that it spreads readily when it strikes the wedge on the nut. Blatchford Corp., 80 E. Jackson Blvd., Chicago.

#### Valve Grinding Unit

A PORTABLE valve grinding unit, complete with everything necessary to do a first class valve job, is the latest development of Black & Decker Mfg. Co., Towson, Md. The valve refacing machine is mounted on a cabinet which contains an electric drill and valve seat conditioning equipment, and is wired for tools and lamp. A 20-ft. cable supplies current from the wall socket. Storage space is provided for hand tools, drills, spare parts, etc.



This is a restyled 1936 Dodge sleeper cab. The sleeping compartment which runs the full width of the cab behind the driver's seat has a special bed spring mattress. Small door towards rear of cab is the luggage compartment

#### **Gatke Brake Block**

HI-POWER brake blocks manufactured by the Gatke Corp. of Chicago, are now being sold on a guaranteed mileage basis. These blocks are made in all shapes and sizes for various types of power brakes. The improved block has been subjected to a special process giving it a high heat-resisting quality.

#### [Other Products Page 42]

COMMERCIAL CAR JOURNAL

son deli che

wro that oil t it h

the fori der

JUNI



"I thought I had the oil cost problem run down and treed.

"I compared prices per gallon...made some figures on a piece of paper...and deliberately went out and bought a lot of cheap oil for my fleet.

"Wrong? I couldn't have been more wrong if I'd been the one who told Noah that it wasn't going to rain! That cheap oil turned around and bit me right where it hurts most—in the pocketbook!

"Sure—I saved a few cents a gallon on the purchase price. But—that cheap oil formed a blanket of carbon in my cylinders. It choked up the oil lines with gum and sludge. It made the engines overheat and caused excess wear. And it got so thin that on long hauls it just laid down and died! So I decided it was high time to bark up the *right* tree. For only a little more per gallon, I got Gulflube—a *real* premium oil. From that day on, my maintenance costs took a nose dive. My hat's off to Gulf for what the Multi-sol process has done for Gulflube—and me!"

Gulflube is a premium-quality oil selling at non-premium prices. It cuts repair bills to the bone—because Gulf's exclusive Multi-sol refining process strips it clean of carbon, gum and sludge-forming compounds. It flows more freely in cold—stands up better under heat—and has an extra high viscosity index.

GULFLUBE MOTOR OIL



If you are a fleet owner, fill out the coupon below. It will bring you the complete Gulf story—how Gulflube can mean real savings to you. Mail the coupon today!

YOU MO	NEYI
CCJ-66	
GULF, 3800	Gulf Bldg., Pittsburgh, Pa
Gentlemen:	
	te to get the complete money
saving story	on Gulflube.
Name	
Address	

JUNE, 1936

at

ing mp.

the

ver's

ress.

d by

being

Chese

The to a

esist-

[2]

RNAL



#### ICC Reverses and Suspends Pick-Up

Sticks By Original Order Suspending C&D Service Until Nov. 1

The Interstate Commerce Commission, on Saturday, May 23, suspended until November 1, the store-door collection and delivery tariffs that were to have become effective on Eastern railroads May 25. Action was taken by the I.C.C. prior to the completion of plans by 2000 truckers for calling a general trucking strike in the East. It also followed a petition filed by the American Trucking Associations, Inc., asking the I.C.C. to withdraw the order issued several weeks earlier granting rails permission to conduct free store-door pick-up service for less-than-carload freight without the allowance feature.

The protesting truckers, attending a mass meeting May 24, appointed a representative to file an order of appearance before the I.C.C. hearings to be held prior to November 1. It is charged by truckers that railroads intend replacing thousands of truckers, now handling pick-up and delivery freight in New York City, with a few large trucking organizations.

#### NAPA Has Chevrolet Manual

A 48-page Mechanics' Repair Manual for Chevrolet has just been published by the National Automotive Parts Association, and is now available through all NAPA warehouses and jobbers.

#### DeLong is Waukesha Head

At the recent meeting of the board of directors of the Waukesha Motor Co., James E. DeLong, vice-president of the company who succeeded H. L. Horning as general manager, was elected president, and James B. Fisher, chief engineer of the company, was elected vice-president. Mr. DeLong's association with the Waukesha Motor Co. dates back to 1923 when he joined the company as field engineer in the development of the company's products for the oil industry.

#### McRoberts is Linderman Chairman

Samuel McRoberts has been elected Chairman of the Board, Linderman Devices, Inc., at a recent meeting. P. M. Chandler, O. M. Johnson and J. Sterling Rockefeller have also been elected board members. B. A. Linderman is president of Linderman Devices, manufacturing and selling brakes for the truck, bus, and trailer fleet field.

#### New Jersey Truck Show Nov. 3-7

The New Jersey Motor Truck Association is again sponsoring a motor truck show to take place in Newark, Nov. 3 to 7, inclusive. This will precede the New York Automobile show which will open on Nov.

The Society of Automotive Engineers has been invited to its National Transportation and Maintenance meeting in Newark at that time, and the National Association of Motor Bus Operators has also been asked to hold its convention in Newark during the period.

#### Banigan Joins Edison-Splitdorf

Leon F. Banigan, for 16 years editor of Motor World Wholesale and other Chilton publications, will join the executive staff of the Edison-Splitdorf Corp. on June 15 as merchandising director, according to an announcement by A. J. Clark, vice-president and general manager. The company, with headquarters in West Orange, N. J., is a subsidiary of Thomas A. Edison, Inc., and manufactures spark plugs.



E. W. Windsor, who has been appointed general manager of the newly organized automotive refinishing sales department of the Sherwin Williams company

#### **Railroads Report on Truck Investments**

The Interstate Commerce Commission has ordered all Class I railways to furnish information regarding their investments in highway motor vehicle enterprises for the carriage of persons or property. Returns in compliance with this order are to be filed with the commission on or before July 1 next.

#### Marvel Elects Kaltwasser

C. M. Kaltwasser was named President of the Marvel Carburetor Co., Flint, Mich.. a subsidiary of Borg-Warner Corp.

#### Traner Heads Borg-Warner Subsidiary

Emil C. Traner has been named president of the Mechanics Universal Joint Division of Borg-Warner Corp.

[Additional News Page 36]

#### Truck Sales Hit New High With 20% Gain; Output Up 14%

From all indications the truck industry is going to enjoy the best year of its history. Indications are that the first four months will not only exceed the same period of 1935 but will pass the first four months of 1929 by a very comfortable margin.

During the first third of the calendar year's sales, approximately 198,500 new commercial vehicles were retailed, as against 165,204 for the like period of 1929. This is an indicated gain of 20 per cent, or approximately 33,000 units. New registrations for April amounted to 62,000 units, an all-time high for any month since the beginning of official registration figures in 1926. This is about a 20 per cent gain over the 51,817 units registered in March and 35 per cent over April, 1935.

April production was 90,346 units or 12 per cent over March and 30 per cent over April, 1935. The 304,256 units produced the first four months of this year exceed by 14 per cent the 267,908 units produced the same period in 1935.

#### Ford Discount to Dealers

Discounts on Ford passenger cars were increased from 22 to 24 per cent effective May 10. The increase was not retroactive and hence does not apply to stocks in dealers' hands, nor does it apply to trucks and commercial cars on which the 22 per cent discount continues.

The quantity bonus announced by Ford in January is continued. This bonus affects dealers selling more than 100 cars annually and amounts to \$8 on 101 to 300 cars, \$10 on 301 to 500, and \$12 on 501 or more cars.

S. A. Jeffries who has been appointed chief truck engineer of the Studebaker Corp. He was formerly chief engineer of the truck division of Reo Motor Co.



#### Autocar Financing Approved

The revised refinancing plan recently submitted by the Autocar Co. of Ardmore to its stockholders, has been approved. It was also announced that the issue of new debentures amounting to \$310,000 has been purchased by the Phoenix Securities Corp.

#### Service Managers Visit Autocar

Service managers of the various factory branches throughout the country visited Autocar headquarters in Ardmore, Pa, where they discussed current service methods and new mechanical developments.

COMMERCIAL CAR JOURNAL



WHY DO YOU SAY THE GENERAL TREAD GIVES MORE MILEAGE AND BETTER DRIVING GRIP?

MR.OPERATOR, WE SAY THAT
BECAUSE THOUSANDS OF CUSTOMERS,
AND MILLIONS OF MILES HAVE PROVED
IT... BUT HERE ARE THE REASONS-



Girst the

ere tive

ealand

cent

afcars 300 501

sub-

re to

l. It

new

heen

Corp.

Pa, rvice nents.





sulphur

and



No second grade materials, no fillers; nothing is added merely for weight or bulk or to reduce costs. Proper compounding makes this rubber tough to resist chipping like this and elastic like this to give long wear.

Second the design of the General Traction Tread gives better road grip because these square blocks

set at 45° angle to the line of when driven into the road surface. No slipping, sliding or spinning like this

The surface does not "wipe" nor scuff unevenly like this but wears uniformly and evenly like this for these three reasons:

... (1) the blocks are short and square ... (2) there are dozens of blocks like this supporting and distributing the load at all times and ...

(3) each block over-laps half of every other block like this

In Canada — The General Tire and Rubber Company of Canada Limited, Toronto, Ontario

THE GENERAL TIRE & RUBBER CO. . AKRON, OHIO

#### FREE! INFLATO-TABLE!

This inflato-table will tell you how much air to put in your tires. It will show you when your tires are overloaded. It will tell you how much load a certain size tire can carry with safety. It's Free. Go to your General Tire dealer and ask for yours.



GENERAL BUILDS a complete, highly specialized line of truck tires. GENERAL TIRE DEALERS are practical truck tire men with wide experience and accurate knowledge in fitting the right type and size of tire to every kind of job. THIS COMBINATION is worth real money to you. If your job is tough, call in the General Tire dealer and let him prove these statements.

### GENERAL TRUCK TIRES

JUNE, 1936

#### **NEWS**

(CONTINUED FROM PAGE 34)

#### Young Appoints Ramsaur

W. R. Ramsaur has been appointed chief engineer of the Young Radiator Co., Racine, Wis. The company also announces the appointment of the C. E. Bull Co., San Francisco, as its West Coast representative.

#### White Receives War Order

Government orders for 685 White and Indiana trucks, representing a dollar volume of \$1,312,000, have recently been received from the United States Departments of War and Agriculture, according to Robert F. Black, president of the White Motor Co.

Production on the huge orders was started immediately and deliveries will be made in June and July.

#### New Borg-Warner Warehouse


Borg-Warner Service Parts Co., a division of Borg-Warner Corp., will open a new warehouse branch in Philadelphia. Over 6200 sq. ft. of floor space will be used for stocking a complete line of automotive products manufactured by this corporation.

#### Wilkening Adds to Plant

A contract for a monitor-type building of one story providing 22,500 ft. of additional floor space has been let by the Wilkening Mfg. Co., Philadelphia. The new structure will be situated on the property of the present plant, and is expected to be ready for production by September. Increased demand for Pedrick hydraulic piston rings necessitates the expansion.

#### Bear Easy Payment Plan

A special, long term, easy-payment plan has been instituted by the Bear Mfg. Co. to carry on where the old F.H.A. left off. Three years to pay with easy monthly payments at low interest are popular features of the plan.



Mastercraft house-to-house package delivery body built by Luce Mfg. Co., features jack-knife side doors, rear door that opens inside of body lines, 42 standard milk case capacity, one-step entrance, and panels of 20-gage stretcher auto steel on the exterior. It is mounted on a Dodge LE30, 112-in. chassis. All hardware of the truck body is of the best quality. Door hinges are continuous or piano type, enhancing general appearance and giving maximum support. Outside hardware is chromium plate. The interior may be specially arranged so that insulation of partition between driver's seat, shelves, insulation of body, etc., is possible. Although this body is standard, larger bodies following the same front end construction are available

#### 40 Per Cent Fords

A total of 1,424,760 Ford truck and commercial car units have been licensed for operation in the United States as of January 1, 1936. The total of all trucks and commercial cars licensed to operate at the outset of the year was 3,535,661, a gain of 7.9 per cent over 1934. More than 40 per cent of the total were Fords.

#### **First-Aid Trained Drivers**

(CONTINUED FROM PAGE 22)

In case you are a little dubious and are probably thinking that the Hamm fleet is a little old two- or three-truck operation, let it be recorded that the Hamm Brewing Co.'s St. Paul fleet is composed of 104 units and that there are 24 branches where 71 other trucks are in active service.

[Ed. note]

Paul Schuler has been in Hamm service for a long time and he has been particularly well trained for the double title he now enjoys—director of safety and director of transportation. He served 14 years in pharmacy; he had charge of St. Paul's first ambulance; he spent a year in the Navy hospital service during the war; he has been expertly and thoroughly trained in first aid work; he is well versed in medicine and surgery.

#### New Truck Registrations by Makes by Months

	Autocar	Brockway	Chevrolet	Diamond T	Dodge	Federal	Ford	G. M. C.	International	Mack	Reo	Sterling	Stewart	Studebaker	White-Indiana	Miscellaneous	Total
January         1936           January         1935		94 86	15,124 9,867	495 550		223 152		428 858	4,743 3,513		339 380	8 10	85 42	143 127	493 308	607 280	43,760 34,759
February         1936           February         1935		88 54	14,978 11,701				12, 226 14, 330	758 570	4,365 3,174		217 292	4 10	62 34	134 107	408 217	661 321	40,301 34,797
March* 1936 March* 1935		121 66	19,332 13,607		6,669 4,216		15,969 16,603		5,314 3,620		256 377	17 14	73 60	221 135	466 252	756 407	51,817 40,994
Three Months†		303 206			18,432 12,628					374 274				498 369		2,024 1,008	
% Change Three Months	+31	+47	+40	+3	+46	+50	-3	+21	+40	+36	-22	-15	+62	+35	+76	+102	+23

<sup>\*</sup> Does not include returns from Connecticu t.

† Connecticut not included for March.

COMMERCIAL CAR JOURNAL

Edi

wor maj ate apr You Spo

now

JUNE.



YOURSELF OUT...if you don't get the full facts about





... EDISON ... a name known since the days of the first automobile . . .

Edison is a time-honored name that everybody knows. Identified not with one success but with many it is associated in the minds of millions with praiseworthy, progressive developments of major importance. Do you fully appreciate the value of the name Edison as applied to spark plugs? If you do you'll get the full facts about Edison Spark Plugs and enjoy the service and savings so many other fleet owners now profit by.

Here's what one user says:

"We have previously installed many

different types of plugs in one particular 20°C motor used in a 10°B6 which runs regularly from Baltimore to Florida, without success. Using an ordinary standard make spark plug, the truck would run only from 250 to 500 miles without trouble. However, since the Edison plugs were installed this same truck has run approximately 12,000 miles without any spark plug trouble whatsoever."

Don't put yourself out by failing to get the full facts about Edison Spark Plugs. Act today—and save every day!

EDISON-Splitdorf Corporation • West Orange, N. J.



JUNE, 1936

icks

serpeen uble ifety He

had nce; pital been

first icine

Total

43,760

34,759

40,301

34,797

51,817

40,994

135,878

+23

URNAL



#### SHOP MECHANICS ARE FAITHFUL HANDS

(Continued from Page 17)

	201 hyl Gas	- A M				Date  Meter Reading - A.M.  Purchased  Meter Reading - P.M.  Used								
Be	rchased lance -				=									
	Car No.	No. Fore- He man's er Time Ti Hours Ho		Help- er Time Hours	Help- er Time Hours	Ethyl Gas	Gala. Gas	Qts.	Lbs. Cup Grease	Lbs. Fibre Grease	Lbs. Trans. Grease	Water Check Only		
	1													
_	2											7		
-	3					1	1	T		-	-	41		
24	T	T	1	-	+	+	+	1				-		
25	1	1_	1	-	-	+	1	1				-		
26	1			-	-	+	+	1			-	-		
_	+			-	-	+	1	1			-	-		
_	1			1	-	+	1	1				-		
71	-4				-	+	+	1			-	-		
Cabi	net			-	-	+	-	1			-	-		
Gar	age			-	-	-	-	1		-	-			
Pla	nt			_	-	-+	-	1						
For	al													
					M	ONTHLY	CAR CHE	ck				-		
					=			-		ate				
	Car	Genera	. 0	1	Drain	_				are_				
	#	Greasi		rings	Case	Water	in Bat	ttery	Air in	Tires	Speedome End of	ter		
	1.													
	2.													
	3.													

Above left—The job-help file serves as the mechanics library. Above—some of the forms that simplify the keeping of garage reports and monthly service records

Mounted onto the end of the desk a large file holds service helps and data regarding every car in the fleet.

For example, let us open the file to No. 22, an Autocar, here we find a greasing chart, car instruction book, brake booster instruction book, cards for tires in use and a service record sheet. Another file is used for all tires—new, old, spares and stock.

When information comes our way regarding an accessory on one of our cars or the car itself we put it in this file. Then if we need information on a given subject, reference to the file shows instantly if we have it.

Suppose knee-action service information is needed for car No. 10, a Chevrolet. Open the file to No. 10, and there it is. You can't beat this silent professor for answering service questions.

A CHART, second in value to the service file, hangs near one of the air towers. It contains identification of every car under company care, tire sizes on the cars, and approved inflation pressures. It is drawn in five columns: our number, factory model and serial, engine number, tire sizes front and rear, air pressure.

For a truck with broken axle (away from the plant) you note the serial and motor numbers on the chart, pick up an axle at the agency and keep going, thus saving steps. If it's a tire, note the size on the chart before starting; no guess work about it; saves time.

For ordering parts for any truck, no matter where it is, we just take identifications off the chart. Listing for license plates too is more convenient—just copy it.

A VOID tool losses. Proper care of tools and shop equipment is no small part of operating profitably. Besides keeping them clean and orderly you want to know where things are if they are not in their places. As mentioned previously, our shop renders a dual ser-

vice—fleet and plant. The latter, often by outsiders or employees not connected with the shop.

After shorter hours were instituted and the business expanded, tool losses increased because some men left them where they were when they got through, forgot them, or carried them off.

To meet this angle a pad for listing items taken from the shop was set up near the stock room.

Listing is signed by the fellow receiving tools and scratched when tools are returned.

This has saved many steps and reduced losses to the absolute point of knowing what became of those missing. Tools and time saved is money earned. That's profit.

Terse notes cure driving weakness. Faulty driving should not be shielded. Bumping the curb when maneuvering will snap off king pins; curb polishing scuffs tire side walls; clutch riding makes extra adjustments; running on a flat with a good spare in the rack is a crime; and all faulty driving contributes to undue wear on other parts. Six

hai

for

Fiv

are

Th

by

sho

the

the

an

Th

roa

18

job

Ti

Ye

to

do

br

Jui

For example: it costs \$12.50, labor included to renew king pins on a certain job. Which is better: inform the driver so that he can correct his bad ways or let him do it again? In every case a terse note on the subject stopped the trouble. The note idea seems far more effective than a private conversation with the driver.

The squawk sheet. We have reached the stage where trucks do not require daily repairs and driver contact with shop is much less than formerly. For this reason daily reports by drivers have been abolished and instead a shop job

(Turn to Page 40, Please)

COMMERCIAL CAR JOURNAL

# HAULS 600 TONS DAI



Truck being loaded at mine of Industrial Coal and Iron Co. in Southern Ohio

## COAL MINE TRUCK CARRIES 31-TON LOADS

Six hundred tons of coal hauled is just a day's work for one of these big trucks. Five such semi-trailer units are constantly on the go. They're loaded in a hurry by big, powerful electric shovels. Then, after leaving the stripping operation, they drive through mud and water-over stones. They never see a paved road. And the gross load is over 31 tons. What a job for tires!

ng

ng

is

on-

ts.

or

er-

the

ad

ery

red

far

sa-

ned

ire rith For ave job

NAL

Tires Triple Protected Yet Triple Protected Silvertowns take the trucks through with never a letdown. Not one sidewall break is chalked up against them in over a year!

It's that kind of service that leads truckers to choose Triple Protected Silvertowns for their toughest hauling jobs. And if they stand up under the brutal, grinding service of a strip mine, they'll save money on your trucks, too.

Here's the secret of Goodrich performance. Every Silvertown is built with a new invention in the sidewall. This development-Triple Protection-provides a 3-way safeguard against sidewall breaksthe cause of 80% of premature failures! When you get this protection, you've

gone a long way toward getting tire costs down Protection when you buy.

chances. Insist on Triple to bed rock. Don't take It costs you nothing extra.

#### TRIPLE PROTECTION WORKS

PLYFLEX-a new, tough, sturdy rubber material with greater resistance to stretch. A layer of Plyflex in the sidewall prevents ply separation—distributes stresses —checks local weakness.

2 PLY-LOCK-the new Goodrich way of locking the plies about the bead. Anchoring them in place. Positive protection against

80% of Premature Truck Tire Failures Occur in the Sidewall the "Failure Zor

the short plies tearing loose above the bead.

3 100% FULL-FLOATING CORD

-Each cord is surrounded by rubber. With ordinary crosswoven fabric, when the cordstouch each other, they rubget hot-break. In Silvertowns, there are no cross cords. No friction.



@ 1986. The B. F. Goodrich Co., Akron, Ohio

(CONTINUED FROM PAGE 38)

sheet is used. Drivers or anyone connected with the shop may write a job on this sheet. When completed a red line is passed through the job—uncompleted work is carried over in order of importance on the next day's job list.

Simple and effective—no mind reading notions about it—talking time is reduced—many otherwise idle moments are allocated to usefulness.

Now that we've listed a job let us compare the cost in our shop with the cost of the same job if sent out, and see what we make and when not to do the job. A valve grind on one truck if sent out costs \$10,50. In our shop one man does the job in 6 hr. The difference is plain. Another truck has brakes relined outside for \$8.50 labor plus material. In our shop one man does the job in 5 hr. Complete motor over-haul is but a larger job.

Our advertising department needed some lugs welded onto 150 side-walk signs. The price outside was \$1 apiece, plus handling. We knocked 'em over in a week with our welding outfit. These are samples on the golden stairs to profit via the fleet shop.

With profit in sight there is still

room for failure unless work is divided. A simple, sure way to do this is to see that each man is occupied at least 5 hr. out of eight on pay-work. Five hours clears his keep—above that is profit for the shop. By pay-work I mean jobs that would cost you prices outside. One to two hours daily should be devoted to shop adjustment. Drills, jacks, wrenches, tool drawers, racks, light cords, errands for supplies, and various other items are just a few of the things to keep in mind if you would always be ready to service efficiently.

Profit that is not a direct return for shop service may come through a company customer. To illustrate: a customer hands a broken ice cream dipper to one of our drivers who brings it to us and we repair it. Next day on delivery the driver collects a cost charge. In this way the line of shop interests helps to hold customers.

AST but not least watch the discount steps. Spark plugs, for instance, are offered in lots of 50 with a rather generous discount but appear to be much more costly when bought in smaller numbers.

Water hose, fan belts, battery wires, and any number of things carry good discount figures in certain lot sizes. But don't be tempted to buy in lot sizes unless you really have turn-over for the things you buy, for after all, investment in things not needed is a poor investment indeed.

Overtime work is a rarety with us mostly because our service arrangement really distributes and avoids bunching of work at any given period—saves men

So let us keep our dates with our trucks and our men and the records will show that we are Fidelia's Children—Faithful Hands.

#### White Display at Exposition

The largest display of trucks, tractors and buses ever exhibited in one show by one company will be on display by the White Motor Co. at the Great Lakes Exposition this summer. At least 25 types will be included.


#### Campbell Promoted by Johns-Manville

George J. Campbell has been promoted to the position of fleet sales manager for the Johns-Manville Automotive Commodities Department.

#### Federal Receives Army Order

Federal Motor Truck Co. has received an order from the government for 278 trucks with cab, cargo bodies and special equipment. The order amounts to \$350,000 and brings the amount of government business received so far this year by Federal to 491 trucks valued to \$650,000.





are required for operating conditions of today, AND WHY after FOUR years of actual road service these top quality lubricants are becoming adopted by a steadily growing number of large motor fleets of outstanding reputation for economical maintenance.

Change to "STURACO" for 90 days and see the difference.

IT'S YOUR LOWEST COST INSURANCE POLICY!







June, 1936

T

be

in

od

ut

n-

st-

us

ent

en

our vill

by the Expes

ille ted for nod-

> 278 cial 50,ient by

00.

NAL

#### **New Products On Parade**

(CONTINUED FROM PAGE 32)

#### **Spicer Power Take-Off**

SPICER MFG. CORP., Toledo, Ohio, announces a new Brown-Lipe two-speed power take-off, Model 001523. This unit can be assembled to any make or model truck including Ford, without interference with any part of the chassis.

This new model differs from other models in that it turns counter engine-wise instead of engine-wise. It is of the push rod type and is equipped with poppets and springs for holding gears in mesh. It is designed for either intermittent or continuous operation, with an output torque of approximately 140 ft. lb. and may be furnished with any pitch of gear to fit any transmission.

#### "Semi"-Safety Device

DEVELOPMENT of a new automatic semitrailer device known as the Mack Coincidental Safety Lock, is announced by Mack Trucks, Inc.

The entire action of the Coincidental Safety Lock is automatically controlled by the normal functioning of the support wheel mechanism.

Prime component of the new device is an auxiliary fifth wheel lock comprising two heavy locking pins working vertically through holes in the upper fifth wheel plate. Except when the support wheels are fully down, these pins overlap the edge of the fifth wheel lower half, forming a secondary lock which effectively prevents accidental uncoupling even though the driver forgets to set the king-pin latch.

#### Fleet-Delivery Tire

A NEW tire designed, engineered, and built specifically for city delivery operation where constant starting and stopping causes more rapid tread wear than in any other type of service, has been announced



by the tire division of United States Rubber Products, Inc.

This new tire, the U. S. Royal Fleet-Delivery, is built of extra deep, flat contour tread of tough, tempered rubber which averages 32 per cent greater non-skid depth than standard dimension tires of corresponding size. Zigzag center grooves with sharp edged projections for gripping, and sharp edged cog-wheel shoulder blocks provide maximum traction.

#### Arc Welder is \$29.50

Commonwealth Mfg. Corp., Cincinnati. has so simplified the construction of a new electric arc welder, called the "Aladdin,"



that it can be sold for only \$29.50, and can be operated from any ordinary light socket.

The "Aladdin" is a full-size, heavy-duty machine, weighing 100 lb., and is equipped with a variable resistance that permits its use to any heat within the limits of its capacity. Its maximum output is 80 amp. at 40 volts.


(TURN TO PAGE 44, PLEASE)

GUARANTEED FOR Life!

THE

TIMKEN Tubulae

TRAILER AXLE



mounting flanges are welded on, or forged as parts of the spindles—also for keeps.

▼ Not a single part to get loose, or rattle, or fall off; WELD-BILT means "better built".

Let's get the straight of this—we guarantee for life the butt-weld which makes one integral powerful unit of a seamless tube center of tempered steel, and two


▼ It's the best trailer axle ever built; not just our opinion—we know.

▼ You'll save money when you recognize these simple facts; and specify Timken Tubular Trailer Axles.

the world's largest axle builders



THE TIMKEN-DETROIT AXLE COMPANY
DETROIT, MICHIGAN



XOU'RE likely to hear a statement like that whenever hearty slice from its operating overhead-that sort of bus and truck men talk shop. For when any fleet cuts

JOUR truck and bus motors can look good, hum like tops without major complaint . . . and still give your accounting department a headache. There trol combustion economy and are 16 parts of a motor that con-

operating efficiency. When they're right the motor turns up maximum mileage per gallon. When some of them are just a little wrong nothing much happens except that you waste fuel.

That's where Standard can turn a trick for you. Let the Standard Oil Company (Indiana) combustion engineers make a free combustion analysis of your fleet.

These trained engineers, using special instruments, check and measure every factor of power efficiency or loss in a gasoline engine. They recommend the slight adjustments needed to coordinate all sixteen factors for the engine's most efficient

Hundreds of mid-west fleets have called in Standard's engineers, followed their recommendations and have carved from 8 to 20% off their gasoline and oil expenses.

Call your nearest Standard Oil (Indiana) office-ask for the free combustion analysis-and join the growing list of bus and truck operators who can prove that Standard Oil products cost, less because they go farther. STANDARD OIL COMPANY (INDIANA) 910 SOUTH MICHIGAN AVENUE • CHICAGO, ILL.

STANDARD OIL PRODUCTS: ISO.VIS "D" • Standard Heavy Duty Gear Grease • Standard Wheel Bearing Grease (Medium and Heavy) • Standard Fibre Grease (for Universals) Standard Pressure Gun (Medium and Heavy) • Standard Water Pump Grease • Standard Steering Gear Lubricant. Fransmission Oil (Summer and Winter Grades) • Standard

Copr. 1936, Standard Oil Co.

STANDARD OIL SERVICE

(CONTINUED FROM PAGE 42)

#### Filterpure Unit


FILTERPURE is a self-contained unit which may be quickly installed in refrigerated trucks for purifying the air. A small motor in the unit forces all the air in the truck through a bed of activated carbon and air is thus completely purified as it circulates. The manufacturers claim its action maintains color and firmness of meats, lowers temperatures, eliminates taste transfer, stops sweating of cases, permits trucking of mixed fish and meat loads, etc. The unit is built of aluminum, weighs but 6 lb., is 20 in. long. Betz Corp., Hammond, Ind.

#### Power Brake Hook-Up

THE Vacuum Power Equipment Co. offers a power unit which installs substantially as here illustrated. With this method of installation it is no longer necessary to replace the barrel type compensator with one of the box type in order to get the booster unit in place.

The sequence of operation is very simple indeed. When the pedal is depressed slightly the valve opens. This causes the power cylinder to

push open the lever which in turn exerts pressure upon the hydraulic plunger. The line pressure in the hydraulic system is "boosted" from two to three times over what is possible otherwise. There is prac-



tically no manual effort required on the part of the driver as the power cylinder does the work and the foot merely guides the valve opening.

#### Wheel Balancer

THE Harley C. Loney Co., Detroit, Mich., is marketing a balancing stand that fastens to the wall, post or bench and will handle any type of automobile wheel. Features include two heavy-duty ball bear-



ings, with dust proof casings, balanced steel cones hardened and ground and a chrome plated gauge for checking wheel wabble and radial run out. This device indicates when a wheel is out of balance, and suitable weights can be added to correct the condition.

#### Feralun Safety Tread

FERALUN is an anti-slip safety tread which eliminates slipping and tripping hazards. It is a cast iron metal matrix, in the surface of which, at the time of casting, hard, irregular abrasive grains are firmly imbedded by a patented process. These grains projecting slightly above the wearing surface, grip the shoe sole, preventing slipping. Trucks so equipped assure greater safety to the driver. American Abrasive Metals Co., Irvington, N. J.

#### Chrome-Plated Pins and Pistons

THE Toledo Steel Products Co. has added a new line of pistons and chrome-plated pins to its line. The new line is factory duplicate type cast-iron and aluminum-alloy pistons, including the Invar strut type. They are featured in the new Toledo general catalog.

#### [Other Products Page 104]

COMMERCIAL CAR JOURNAL



TEOPLE used to think it was the driver—when they thought at all. Now they figure differently. And they are discovering a lot of interesting things. Among them this:

#### Most of the idle time of a truck is due to other factors than the driver.

Perhaps they make a little change in the order department, or some trifling change in office routine, and as a result several expensive trucks increase their running time an hour a day! ... What starts them doing this? ... When they find out when the delays occur, and for how long, then they can't help

going after the cause.... The Servis Recorder automatically shows up all delays on a graphic chart—like pointing a finger at them.

Today more than 100,000 Servis Recorders are looking after more than 100,000 trucks, and those trucks are keeping busy. . . . Have you investigated it yet?

Write for Bulletin! — Ten Ways of Getting More Work Out of Motor Trucks

The Service Recorder Company 1422 Euclid Ave., Cleveland, O.

#### The Servis Recorder Tells Every Move Your Truck Makes

#### FRUEHAUFS Sverywhere Leading the Fruehauf line of standard all-purpose Trailers is the new Type "F" Van. This unit combines strength, light weight, and streamlined appear-ance—at an unusually low price. Colonial Colonial Bakery Produ BREAD CAKES TODAY MEN ARE DEMANDING something more than low haulage cost. That "something" is class! Take a look at any of the new Fruehaufs on the road—on city streets. You'll find Fruehauf Trailers have "class" that counts -appearance that attracts. Here is dollarsand-cents advertising value, modern, prestige-gaining style. And, in a Fruehauf, body and chassis are built together. Streamlining is matched with engineering, capacity, and weight distribution. Net result: Fruehauf gives you peak performance, attractive appearance, and cost-cutting economy. REFRIGERATED EXPRESS Oldest and Largest Manufacturers of Trailers FRUEHAUF TRAILER CO. 10957 Harper Ave. Detroit Sales and Service In All Principal Cities TRUE BREWERY FLAVOR SEALED IN BEV. CO Delicious Pabst Export Beer Sealed in non-refillable KEGLINED Tapa Can BENSON BEVERAGE CO. PHONE - 47101 DES MOINES, IA.

#### **Expander Type Rings**

(CONTINUED FROM PAGE 13)

was 60,000 miles, which is not surprising when you consider that trucks in all kinds of service are in this survey.

Conventional rings maintain adequate oil control for an average of 30,300 miles, the average being taken from the mileages given by 55 fleet operators as the useful life of conventional rings in new or reconditioned cylinders. The range of individual figures in this case was from 7500 miles to 80,000 miles. If these averages are a

fair index of piston ring performance they provide evidence that the expander type rings give about 2000 more miles of satisfactory life than do conventional rings when installed in new or reconditioned cylinders. This is near 6.2/3%.

If at this point an interpretation of these figures may be in order it may be pointed out that quite possibly the 20 fleet operators who install expander type rings in new or reconditioned cylinders do so to combat a chronic engine or operating condition that has been resulting in excessive oil consumption. If this be true and the 55 operators who use conventional rings in new and re-

conditioned cylinders are reporting on average conditions, then the expander type rings suffer from the previous comparison which would give them a larger advantage if the conditions were more nearly comparable. In partial support of this suggestion it may be argued that while the average mileage of the expander rings is higher than that of the conventional rings the highest individual mileage given is 60,000 miles while 80,000 miles is mentioned several times as the limit for conventional rings.

Passing on to the characteristic of expander rings and conventional rings in worn cylinders we find that expander type rings have an average satisfactory life of 19,300 miles when installed in worn cylinders. The lowest figure mentioned in connection with expander type ring life in a worn cylinder is 6000 miles and the highest is 50,000 miles. Fifty-four fleet operators contributed figures which make up the average.

The conventional ring shows a sharp drop in useful life when used in a worn cylinder. The figure is 12,800 miles and even this is an unfair comparison so far as the expander rings are concerned because three operators refused to give a useful life for conventional rings in a worn cylinder by simply saying "impractical to install conventional rings in a worn cylinder." While they would probably rate the useful life of a conventional ring in a worn cylinder very short, any figure that they gave would lower the average but since they gave no figure it was impossible to use their opinions in determining the aver-

To determine just what use the fleet operators who do not install expander type rings in new or reconditioned cylinders make of them the questionnaire contained the question, "At what cylinder taper do you install expander type rings?" Two fleet operators answered by saying, "no standard—to stop oil pumping." Two more operators specified, "at first ring change."

It seems hard to believe but the range of wear which is given as the point when individual operators install expander type rings varies from .001 in. to .030 in. Eight operators indicate that they install expander type rings when the cylinder taper is over .010 in, which certainly puts piston rings to a test.

Omitting these eight operators from the computation the average wear point at which expander rings are installed is .0065 in. Thirty-two operators gave their individual practices in order for us to obtain this average. The wear point given most often is .006 in. which is the standard for nine operators. Ten one thousandths is a point at which five operators install expander rings and five favor it at .008 in.

In comparing the rate of cylinder

A SAFETY FLEET



MAJOR ACCIDENTS are almost always the result of high, ungoverned speed.

To prevent such accidents, automotive transportation, to the extent of more than a million and a quarter vehicles, uses Handy Governors.

Records prove that Handy-Governed cars and trucks almost never CAUSE major accidents and are very seldom involved in them.

Since 1921, Handy Governors designed by A. A. Bull and manufactured under his direction as President of this Company, have been preventing major accidents, and promoting safe traffic on the highways of the world.

This Company also manufactures the famous high-efficiency Handy Perfection Air Cleaner and the new Handy Oil Conditioner which keeps motor oil forever fresh.

HANDY GOVERNOR CORPORATION DETROIT

HANDY GOVERNORS

COMMERCIAL CAR JOURNAL

#### **EVERY FREIGHT HAULER KNOWS**

# WALUE goes deeper than price

It is a common error to confuse the words "price" and "value." Actually, "value" is what you get for the price you pay.

Ford believes "value," as applied to trucks and commercial cars, should be a combination of high quality at low price with superior performance at low cost... that it should include low operating cost, low-cost maintenance and long-lasting, brilliant performance. The experiences of truck and commercial car owners indicate that they agree with Ford's idea of value.

Further evidence comes from the cost records of owners. These records prove that V-8 Economy is OVER-ALL ECONOMY . . . that it includes savings in fuel and oil, tires, taxes, license

fees, insurance, interest, wages, depreciation, capital investment and repairs.

Ford V-8 Truck and Commercial Car "VALUE" goes deeper than price. True appreciation of V-8 Value comes only after tens of thousands of miles of reliable, economical service. But your Ford dealer invites you to "sample" V-8 Performance... a vital element of V-8 Value... under your own operating conditions. Call your Ford dealer today and set a date for an "on-the-job" test.

Any new 112-inch wheelbase Ford V-8 Commercial Car can be purchased for \$25 a month, with usual low down-payment. Any new 131½-inch or 157-inch wheelbase Ford V-8 Truck can be purchased with the usual low down-payment on the new UCC ½% per month Finance Plans.

# FORD V-8 TRUCKS

AND COMMERCIAL CARS

e

et

r

le

1-

d

il

i-

;e

n

er

10

y

1e

r-

nt

ed ve

or ar ch

ıd

(CONTINUED FROM PAGE 46)

wear with expander type rings against conventional rings, 46 operators find that the expander type rings are responsible for the greater wear. Twenty-eight operators do not agree that the expander type ring causes any more wear than the conventional type.

The specific information dealing with how much greater wear was caused by the expander disclosed chiefly that operators do not know how much faster the wear is with expander type rings. Three operators ventured the opinion that 10 per cent was correct and two qualified their opinion by saying "slightly."

On no other rate of wear did any two operators agree.

Sixty operators have noticed a difference in engine performance when expander rings have been installed and only nine operators have not. Most of these comments record the difference as a favorable one. With each operator describing the difference with his individual expressions it would be hard to get the concensus from a quick reading so the various phrases have been reduced as faithfully as possible to a standard nomenclature which is more readily understandable. The number of mentions has nothing to do with the

number of fleet operators contributing since one fleet operator may describe several ways in which he notices the difference. The seanswers are: more power, 19; less oil consumption, 14; better ompression, 10; sluggish, 10; less gasoline consumption, 8; quieter engine, 7; smoother running engine, 7; better acceleration, 3; lower top speed, 3; overheating, 3; hard to break in, 3; loss of power, 2; better, 2; blow-by, 1; no blow-by, 1.

If all of the comments that might be construed as favorable are added the sum is 73 while the sum of the unfavorable comments is 20. In the face of this majority and the other results of this survey, there is only one conclusion to be drawn. Fleet operators believe that expander type piston rings are an economical and necessary part of fleet maintenance but while the favorable bloc is large, their views are not accepted by all fleet operators.

#### AFTER HOURS

(CONTINUED FROM PAGE 24)

unable to give vital aid to engineers in keeping watch on signals. The facts brought out by E. E. Vail, fireman of the Pennsylvania's crack trains, the Broadway Limited and the Liberty Limited, were typical. Because the smoke is always on one side of the cab or the other, the fireman and engineer must depend on each other to catch signals. The fireman must interrupt his look-out over 1000 times, he said, because by actual count that is the number of times on a run that he must open the firedoor and stoke the boiler. Because of the blinding glare this activity further interferes with the fireman's efficiency as a lookout. G. C. Van Horn, "Big Four" fireman, described a test on a 133-mile run from Cleveland to Columbus, which proved that he was fireblind more than 8 per cent of the time, yet on that run there are 74 signals and 175 crossings he is supposed to see.

This testimony, put into the Commission's record over repeated objections by railroad attorneys, certainly indicates that when accidents occur at grade-crossings the railroads cannot conscientiously wash their hands of the blood that is shed.

The true safety record of the railroads therefore is that, with all the highly touted automatic devices, 4889 persons were killed and 16,591 injured.

Which would make the cleverlyphrased, self-praising, highway transportation-smearing safety advertisement another typical instance of what, in the vernacular, has come to be designated by too-long-suffering highway interests as "a dirty, low-down, railroad trick."



▼ a double-reduction drive; the kind

of axle available before only in heavy duty, finest quality trucks selling up to \$5000


▼ full "man-sized" gears in both ratios; all the rugged strength and efficiency for which Wisconsin Double-Reduction Drive is famous

- ▼ only three additional working parts give you an extra ratio
- ▼ perfect accessibility—an easily removable carrier
- a sensible way to increase average vehicle speed, and cut operating costs
- a better 2-speed axle; the fine quality of design and workmanship you expect of Timken

the world's largest axle builder

THE TIMKEN-DETROIT AXLE COMPANY
DETROIT, MICHIGAN

WISCONSIN AXLE DIVISION
OSHKOSH, WISCONSIN



# TRUCK SPECIFICATIONS TABLE COMMERCIAL CAR JOURNAL'S

g e ; ; r ; l, ; ; e e e v of fu-

in ts of ne ty ne ab er ch nis en ne ity n's rn, on Co-

re-

m-ec-ly at

ot he

he 89 ed. ly-ns-se-at, ig-

The Specifications Table is brought up to date in each issue from data supplied monthly by truck manufacturers

# KEY TO ABBREVIATIONS AND REFERENCE MARKS

underfation ackept where our and maked.

Med. um Brake Htp. at Given R. P. M. — Is actual dynamometer read-ling without accessories, and in the Bratio Range in High—Battoo within the range given are available at no out starte cost. Exceptions are noted.

Tractoor—Unless given the designation of a manufacture of the strength of the stratton, all strattons are noted.

Tractoor—Unless given the designation of a manufacture models may be assumed to be available as tractors.

(N)—Notes of quipped.

(N)—Notes of quipped.

(T)—Specifically designed for tractor use only a manufacture of the strattors.

use only.

- c.o.e.—Cab-over-engine design.

- c.b.e.—Cab-over-engine design.

- c.b.e.—Engine-beween-ead design.

- c.d.e. for form of the cast of th

with a range of axles, wheehbases, engines, transmissions, etc., and prices will genes. Call of the animal as Call of Secrept Bess as Call occept, less rear gringle teaves. Model Call 2, 4, ton same default of the wheehbase and price of \$1695, 33 hame as 3H except, 166 h. wheelbase and price of \$1695, 38 same as 3H except, 165 in. wheelbase and price of \$2155. 3N same as 3H except 205 in. wheelbase and price of \$2155. 3N same as 3H except 205 in. wheelbase and price of \$2155. 3N same as 3H except 205 in. wheelbase. (s) Stewart—46H and 47H availabe with two-speed rear axie. (s) White—Exam model shown is furilished with different speedifications for different tonings arhings. (\*)—Factory governed speed 2400 p.p.m.
(a) Mite—Exam produce on the complete artiflation. Treat axis are agreeded when tiers of 3. All thics—Include auxiliary axie complete, are so to brake liming and drum area do not include auxiliary axie complete, area of brake liming and drum area do not include auxiliary axie complete, area of brake liming and drum area do not include auxiliary axie complete, area of brake liming and drum of the available as cab-over-engine models.

(d) Models intended for dump or trackor service only.

(e) Millys—Price includes body and complete articles. Whillys—Brakes and Solf the articles and All and of Solf and All and different will influence and additional charge. (iii) Maker—Frame lengths may be changed, within limits to suit individual requirements, at no additional cost.

(iii) Maker—Frame lengths may be changed, within limits to suit individual requirements. At no additional cost.

(iv) Walker—Frame lengths and somplete requirements at no additional cost.

(iv) Maker—Frame lengths only upon additional charge of additional charge of additional charge of a suit additional charge of suits and additional charge of suits.

application.

(a) Mack—Weights in Chassis Weight column are shipping weights which include weight of a chassis of medium standard wheelbase, can prevailing the size and spare the, ready for the road.

(b) Sterifug—Available with Diesel engine.
(c) Sterling—Available with Hessel-

Material

A LaF—American I.a France.
B—Bendix. BL—Brown-Lipe.
Bu or Bud—Buds.
Bu or Bud—Buds.
Bw—Borg warner
Cor Col—Columbis.
Cot—Cotta Gear.
Cot—Cotta Gear.
Cot—Countin-Dies.
Du—Detroit Gear and Machine.
Ext—Extron.
Ext—Extron.
Cut—Cutta Gear.
Cut—Cutta Gear.
Cut—Cutta Gear.
Cutta—Cutta Gear.
Cutta—Cu

Li-Lipe, W. C.
Li-Lipe, W. C.
Liwith and front, Own reaf
LW-Lockhed front, Wisconsin reaf,
Ly - Lockhed front, Wisconsin for Cyc Owcoyen.
Op or Opt-Optional.
Stu-Shile:
Sta or St-Sterling.
To Tim Timken.
TWH-Timken Wisconsin
TWH-Timken Wisconsin
WG-Warner Gear.
Wi-Case. Wan keep Heeselman.
Wan-Wankeeba.
Wor Was Wisconsin.
Was-Westinghouse.

BRAKES—SERVICE

2—Two Wheels rear only.

24—Two wheels rear only.

74—Two wheel through driveshaft.

46—Brakes on four rear wheels effective on all wheels through driveshaft.

74—Brake on transmission effective on all four wheels through driveshaft.

4—Four Wheels, front and rear.

4—Four Wheels, front and rear.

6—Six Wheels, front and rear.

9—Jackbalt.

P. Propeller shaft. Location

Operation Type I-Internal. X-External.

A—Air.

—Bydraulic and mechanical.

—Bydraulic.

M—Mcchanical.

V—Vacuum.

BRAKES—HAND Location

C—Center of double propeller shaft.

2—Center of double propeller shaft.

4—Four wheels.

R—Worm or bevel gearshaft.

F—Driveshaft.

BRAKE DRUMS D-Tru-Stop disk.

A—American Car Fury,
A—American Car Fury,
A—Contribue.
B—Dayvon.
B—Ernalite.
G—Gunite.
H—Huut Spiller.
B—Freesed steel.
B—Freesed steel.
A—Cast steel.
A—Cast steel.
B—Treesed s

C. 1 Josan.
T. Channel tapered front and rear.
T. Channel tapered front and rear.
E. Channel tenforced with liner and fishibate.
P. Channel tenforced with plate.
T. Channel tapered front and rear reinforced with liner.
D. Drop Center.
T. T. Tapered front.
X. Z. Braved.

GOVERNOR STANDARD

REAR AXLE

C\_Chain.
P\_Chain.
P\_Pull-floating.
P\_Pull-floating.
S\_Double Reduction.
S\_Orom.
W\_Wrorm.
W\_A\_Chain or Double Reduction
S\_A\_Burl-floating.
M\_Batios other floating. Final Drive and Type

Drive and Torque

(\*\*) Only one ratio.

A—Radius Rods and Torque Arm.
B—Radius Rod and Torque Tube
H—Hotchkiss. (springs)
F—Radius Rods
T—Torque Arm.
U—Torque Tube.

2F—Forward unit of Rear Axie Group.
2R—Rear Unit of Rear Axie Group.
Axie and Forward unit of Rear Axie Group. WHEELS DRIVEN

FORMULAS

(For Transportation Engineering)

Miles Per Hour

R.P.M. x D.

M.P.H.=Miles per hour. R.P.M.=Revolutions per minute. D.=Effective tire diameter. F.G.R.=Final gear ratio. 336 x F.G.R.

Grade Ability

OA = TE-RR. OA = Grade ability. TE=Tractive effort. RR = Road resistance—.012 for hard surfaced roads. Tractive Effort

in. lb. torque x F.G.R. x EFF.

EFF.=EMclency—.90 for all rear axles except worm, then .85.
R.=Rolling radius
O.V.W.=Gross vehicle weight. G.V.W.=Gross vehicle weight. G.V.W. x R.

Torque=:.65 x cu. in. displacement. (This is approximate and should be used only when actual torque is not known.) When actual torque is not Cu. in. Displacement

D=B x B x 77854 x S x No. of Cyl. Torque in LB. FT.

AMA H.P. B x B x No. of Cyl. AMA Horsepower Rating 2.5 D=Cu. In. displacement. B=Cylinder bore. S=Cylinder stroke.

TIRE TABLE

(Tire and Rim Association, Inc.)

Balloon Tires

1	-	əd	LAL											
WE			-				HHH4HHH 4 44	++++++ *	-	12/2/2/2/2			-	HEMHERE
FRA		d. W. B.) e Rail	PIS	68.33 77.83	Talalala latate	2222222 20000000 20000000000000000000	25 9 x 3 x 3 x 4 x 5 2 x 3 x 4 x 5 2 x 3 x 4 x 5 2 x 3 x 4 x 5 2 x 3 x 4 x 5 2	10/2 8x3xxx 8x3xxx 8x3xxx xxxxxx xxxxxxxxxx	24444444444444444444444444444444444444	8x2 10x2 10x2 10x2 12x2 12x2 14x3 14x3 14x3 14x3 14x3 14x3 14x3 14x3	7x3x 7x3x 7x3xx 7x3xx 7x3xx 8x3xx 9x3xx 9x3xx 10x3x <del>4</del>	7 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	30 30 30 30 30 30 30	00 00 00 00 00 00 00 00 00 00 00 00 00
_	8	oisnensio	C-1	00000000	80008080 4004040	102 102 102 119 119	8891 12021 1299 151 151	0 8 8 L 8 0 24 4 0 4 0	41.02 1.02 1.02 1.02 1.02 1.03 1.03 1.03 1.03 1.03 1.03 1.03 1.03	####### 00000000	822 105 105 103 103	65 71 77 83 83 83 83 83 83 83	833 103 103 103 103 103 103 103 103 103 1	60 888 888 888 888 888 888 888 888 888 8
	u	terial   nd Locatio	EM.	2222222	RANANAN	222555	<u>EEEEEEE</u>	DISSISSI	ESSESSES	XXXXXX55	XXXXXXXX	KKKK888	8888888	8888888
AKES		E3	Dri	380 527 527 559 768 768 768 768 768 768 768 768 768	00000000000000000000000000000000000000	8322 931 931 931 832 832 832	931 c 931 c 931 c 931 c 931 c	051 c 693 c 693 c 931 c 931 c	931 931 931 931 931 931 931	3366 3366 3376 5822 5822 5822 7680 7680 7680	2556 2556 2556 2556 2556 2556 2556 2556	3380 380 380 4456 2528 2528 38 38 38 38 38 38 38 38 38 38 38 38 38 3	5575 55778 57788 5778 57788 57	578 8 663 8 663 8 663 8 7772 8 7772 8
BRA		a guit		2002 2002 2002 2002 2002 2002 2002 200	V 4440 V 4440 V 4440 V 519	519 7519 7519 7519 7519 7519	7543 5022 70403 70403 6593 6593	659 659 659 659 6513 6519	7543 7543 7543 7543 7543	250 250 2330 3330 44 4626	223888899999999999999999999999999999999	244 200 200 200 200 200 200 200 200 200	20000000000000000000000000000000000000	365 407 365 500 707 500 700 700 700 700 700 700 70
-		sation pe erat'n serat'n	Loc	1.41H 1.41HV 1.41HV 1.41HV 1.41HV 1.41HV 1.41HV	1041DV 1041DV 1041DV 1041DV 1041DV 1041DV	1041DV 1041DV 1041DV 1041DV 1041DV 1041DV 1041DV	1041DV 021MV 1041A 1041A 1041A 1041A	TO4IA LO4IDV LO4IDV LO4IDV LO4IDV	LO4IDV LO4IDV LO4IDV LO4IDV B4IMV TO4IA TO4IA LO4IA	22222 22222 2222 2222 2222 2222 2222 2222	141H 141H 141H 141H 141H W841A	141H 141HV 141HV 141HV 141HV	14 HV 14 HV 14 HV 14 HV 14 HV 14 HV	LAIHV LAIHV LAIHV LAIHV AIHV
FN		Japa	ow		23000 23000 23000 22000 22000 22000	33000 35000 35000 35000 35000 35000	200020 20000 200020 20000 200020 200020 200020 200020 200020 200020 200020 200020 20000 200020 200000 200000 200000 200000 200000 200000 200000 200000 200000 200000 200000 200000 200000 200000 200000 200000 200000 200000 20000	7450 5000 5000 6450 6450 5000	2022222000	00000H 10000H 12502H 55000H 5000H		H0000 H0000 H0000 H0000 H0000 H0000	0000H 5000H 5005H 5005H 5005H	505H   1685B1   1685B
FRONT	-	ke and	s.M	Trim Shu Shu Shu Shu Shu	HEATTT HE	HEHERE	Tim 264 Own SC Tim 264 Tim 264 Tim 274 Tim 274	111111	Tim 264 Tim 264 Tim 264 Tim 264 Tim 264 Tim 264	Tim 300 Tim 310 Tim 310 Tim 350 Tim 350	Cla F212 Cla F212 Cla F308 Cla F308 Cla F308 Cla F318 Tim 35100	Tim 3000 Tim 3000 Tim 3100 Tim 3100 Tim 3100	TIM 3100 TIM 3250 TIM 3250 TIM 3250 TIM 3250 TIM 3250	Tim 3256 Shu 1568 Shu 1568 Shu 1568 Shu 1568 Shu 1568 Shu 1568
	L	13iH ni egn	Ка	6-5.14 8-5.83 8-5.14 94-7.14 94-7.14	20000000000000000000000000000000000000	7.88 -101-10-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-	-8.52 -8.68 -8.68 -8.52 -10.1	7.88 10.88 10.4	444444888688	00001-1-8 00004-800	44440040	&&&&&&-& &&&&&& &&&&&&	0077770 0044448	88.50 88.50 88.50 8.50 8.50 8.50 8.50 8.
еń		ar Ratio		####### #############################	04.44.44.44.44.44.44.44.44.44.44.44.44.4	7. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1. 1.	7.20 7.20 7.20 7.90 7.90 7.90	7.56 6.45 7.26 7.20 7.20	24.65.77 24.65.77 24.65.77 26.65 26.65	*******	2200000000	88.2.866 83.3.3.888 83.668	6.16 6.16 1.07 1.07 1.07 1.07 1.07 1.07 1.07 1.07	85 00 00 00 00 00 00 00 00 00 00 00 00 00
R AXLE	-	at and Typi		SSSSBBBB SSSSBBBB SSSSBBBB SSSSBBBB SSSSBBB SSSSBBB SSSSBBB SSSBBB SSSSBBB SSBBB SSBBB SSBBB SSBBB SSBBB SSBBB SSB SSBB SSB SSBB SSB SSBB SSB SSBB SSB S SSB SSB S SSB S SSB S SSB S SB S SB S S S S S S S S S S S S S S		FEFFFF	SSSSSSS SSSSSSSS SSSSSSSS SSSSSS SSSSS SSSS	222222 222222 222222 222222	######################################	HERRRRR	BBF RRRRRRRRRRRRRRRRRRRRRRRRRRRRRRRRRRR		<b>アアアアアアア</b>	我我我我我
REAR						************************************			7 4	001 001 001 000 001 001 001 001 001 001		11H SFF 77H SF	SET	HH-CONTRACTOR
		he and del	B.M.	4 Tim 5 Tim 5 Tim 5 Own 5 Own 5 Own 5 Own 5 Own 5 Own	5 Own DF 5 Own DF 5 Own DF 5 Own DF 5 Own DF 5 Own DF	Own DF Own TF Own TF	Own CGA Own TG Own TG Own CG 79733W	000000	OWD C&N OWD TF OWD TF OWD TG OWD TG OWD TG	Tim 53508 Tim 53300 Tim 54411 Tim 54411 Tim 56410 Tim 58205	Cla B373 Cla B373 Cla B373 Cla B613 Cla B805 Cla B805 Wis 1237	Tim 53521 Tim 53307 Tim 53307 Tim 54411 Tim 56410 Tim 58307		Wis 5000L Wis 72000 Tim 56200H Tim 58205H Wis 72000L Wis 1337BH
RANS-	-	'bqe brawn			200000000 000000000	######################################	4404040	2000000	សិស៊ីលិសិង្ហិលិងល លេលលេងលេងលេល	290 290 290 380 380 300 530 530 530 530 530 530 530 530 53	2000000 444000000	या या या या या या या	जनननन ७	4400040
FE		ike and ike and labe	BM	N BL 35 Y Fu 5-A-38 Y Fu 5-A-38 Y Fu 5-A-38 Y Fu 5-A-53 Y Fu 5-A-53 Y Fu 5-A-53		Own DF5 Own DF5 Own DF5 Own TF5 Own TF4	Own TF4 Own TF5 Own TF5 Own TF5 Own TF5	BL 7351 Own DF Own DF Own DF Own DF	Own DE Own TE Own TE Own TE Own TE Own TE	WG T9 WG T9 WG T9 Fu 5-A-290 Fu 5-A-390 Fu 5-A-390	War T9 War T9 Fu 5-A-29 Fu 5-A-29 Fu 5-A-38 Fu 5-A-38	WG T9 WG T9 WG T9 WG T9 WG T9 BL B341	BL B341 BL B341 BL B341 BL B341 BL 3241 Fu 5-A-38 BL 314	BL 314 BL 314 Fu5-A-38 Fu 5A38 Fu 5A38 Fu 6A53
- P	1	ngth ig	год	00000 27474	**************************************	***************************************	**************************************	五人人人人人人人人	*********	KKKKKK	<b>及及及及及及及</b>	ZZZZZZZ	ZKKZZZZ	** **
	Main		Big	777777 33338888 333388888 333388888 3333888888	77-33 77-33	7-3x12 7-3x14 7-3x14 7-3x14 7-3x14	44 ×4 × × × × × × × × × × × × × × × × ×	47-7-7-7-7-7-7-7-7-7-7-7-7-7-7-7-7-7-7-	44444444444444444444444444444444444444	4	7-7-7-7-7-7-7-7-7-7-7-7-7-7-7-7-7-7-7-	4-234x6 4-235x104 7-235x104 4-235x104 4-235x635 7-235x635 7-235x635	7-25 % X I I I I I I I I I I I I I I I I I I	7-22-2-2-2-2-2-2-2-2-2-2-2-2-2-2-2-2-2-
s	-1	ıx. Brake P. at R.P.M ven	LH	76-2809 78-2400 78-2400 78-2400 78-2400 85-2400 93-2200 113-2200	85-2300 85-2300 85-2300 85-2300 85-2300	85-2300 85-2300 97-2200 97-2200 108-2200 108-2200	08-2200 08-2200 08-2200 08-2200 23-2200 23-2200 25-1800	85-2300 85-2300 85-2300 85-2300 85-2300 85-2300	97-2200 97-2200 108-2200 97-2200 123-2200 108-2200 108-2200 108-2200	71-3100 73-3000 73-3000 73-3000 85-3200 110-2800 25-2600	70-2800 75-2800 75-2800 84-2800 88-2600 98-2500 10-2200	71-3100 78-3100 84-3250 78-3100 84-3250 78-2650	78-2650 86-2600 78-2650 86-2600 86-2600 95-2500 85-2500	85-2500 85-2500 78-2650 95-2600 95-2500 18-2600 18-2600
DETAILS		rdue lb. ft.	-	33222220 33222222 33222222 553222222	00000000000000000000000000000000000000	55250 5520 5520	55 333 3 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	488888 1000000 1	23222222 23222222 232222222 2322222222 23222222	154 155 155 155 155 155 155 155 155 155	325255 2555 3305 3305 3305 3305 3305 330	154 170 170 171 171 192 192	2021 2021 2022 2022 2022 2022 2022 2022	203 203 203 203 203 203 203 203 203 203
	-	placement		2323232 2323333 2223333 2233333 244444444		2358 258 4404 404 4533555 5335555 53555555555555	50115555555555555555555555555555555555	\$20,000,000 \$20,000,000 \$20,000,000 \$20,000,000 \$20,000,000	404 404 4504 4503 4503 4503 5003 5003 50	2000 2000 2000 2000 2000 2000 2000 200	215 4 5 5 4 5 5 4 5 5 4 5 5 4 5 5 5 5 5 5	244488 244488 244488 27.7.7.7.7.7.7.7.7.7.7.7.7.7.7.7.7.7.7.	8000000000 6000000000 40040440	ままららまらま
ENGINE		roke roke	Boi	% 76/4/4	alalalalala	#\@\@\@\@\@\@\@\@\@\@\@\@\@\@\@\@\@\@\@	4404000	44444	444446464	**************************************	44444446 4272777	********* ***************************	444444 2222224 2222222 3322223 3352 3352	10/0/4/0/4
	-	of linders,	63	2.2.6 6.00.00 8.00.00 9.00 9.00 9.00.00 9.00 9.00 9.00 9.00 9.00 9.00 9.00 9.0	99999999999999999999999999999999999999	0000000 4444444 444444444	4444440	6-5-4-4-6-6-6-6-6-6-6-6-6-6-6-6-6-6-6-6-	000000000 444444444 55555555	00000000000000000000000000000000000000	66000000 600004444	60000000000000000000000000000000000000	# # # # # # # # # # # # # # # # # # #	00000000000000000000000000000000000000
		ike and	PW PW	Con 20C Her WXC Her WXC Her WXC Her YXC Her YXC Her YXC3		Own 358 Own 404 Own 404 Own 453 Own 453		Wau 6RB Own 358 Own 358 Own 358 Own 358	Own 404 Own 453 Own 453 Own 404 Own 501 Own 501 Own 551	Con F6209 Wau BL Wau BK Wau BK Wau BK Wau 6-110	Con 25A Wau 6BL Wau 6BL Wau 6BK Con 1601 Con 1602 Herwc3 Her RXB	Con 25B Con 25B Con 25B Con 25B Con 25B Con 25B	Con 29B Con 31B Con 29B Con 31B Con 32B Con 32B	Con 30B Con 29-B Con 32B Con 32B Con 32B Con 32B
SIZES	lual rear	mumixi Size bədsin	T.it	7.00/20 8.25/20 9.00/20 9.75/20 9.75/20 9.75/20 9.75/20	9.75/20 9.00/22 9.00/20 9.75/20 9.00/22 10.50/20	9.00/20 9.75/20 10.50/24 9.75/22 10.50/24	10.50/22 36x78* 11.25/24 10.50/24 10.50/24 11.25/24	11.25/24 9.75/20 9.00/22 9.75/20 10.50/20 9.75/22	10.50/20 9.75/22 10.50/24 10.50/20 10.50/24 10.50/24 10.50/24	7.50/20 8.25/20 8.25/20 9.05/20 9.75/20	8.25/208 8.25/20 9.00/20 9.00/20 9.00/20 10.50/20	32x6 7.50/20 34x7 8.25/20 8.25/20 8.25/20	8.25/20 9.00/20 9.00/20 9.00/20 8.25/20	9.00/20 9.75/22 9.00/20 9.75/22 10.50/22
TIRE	D-dua	38	Sta Fro Res	6.50/20D 8.25/20D 9.00/20D 9.75/20D 9.75/20D 9.00/20D 9.75/20D	8.25/20D 8.25/20D 8.25/20D 8.25/20D 8.25/20D 9.00/20D 9.00/20D	8.25/20D 9.00/20D 9.75/20D 9.75/20D 9.75/22D 10.50/20D	9.75/22D 36x74D 10.50/22D 10.50/24D 9.75/20D 10.50/24D	10.50/24D 8.25/20D 8.25/20D 9.00/20D 9.00/20D	9.00/22D 9.00/20D 9.00/20D 10.50/20D 10.50/20D 10.50/24D 10.50/24D 10.50/24D 9.00/20D 9.00/20D	26/20D 26/20D 26/20D 25/20D 25/20D 26/20D 75/20D	7.00/208 7.00/20D 7.50/20D 8.25/20D 8.25/20D 9.00/20D 9.75/20D	20/20D 20/20D 20/20D 20/20D 20/20D 20/20D	50/20D 25/20D 25/20D 25/20D 25/20D 25/20D 50/20D	25/20D 00/20D 4x7D 4x7D 00/20D 75/20D 00/20D
		.sw sissa (baqqin		4850 5450 5750 6600 7100 7226 7326	6893 6746 6619 7055 7719 7728	6891 7804 8731 8639 9190 10000 8905	10016 10300 9979 10823 10823 11375 12053	11537 7629 7629 8525 8357 8262 8262	9259 98665 9986 9986 9986 9986 9986 9986 9	3600 44800 4880 7000 8200 8200 8200 8200 8200	3100 3800 5500 6800 7100 8500 1530 8500	3965 6 4435 6 4500 6 4635 7 4700 7 5050 7	5490 7. 55570 7. 6390 8. 6520 8. 6550 8.	63855 74550 62250 77350 81550 9999
Keynote)		oss Vehicle sight with ax. Tires	D We	11500 15300 19500 23000 35000 35000 45000						11500 12500 14000 19000 21700 26500	10000 111400 15000 16000 220000 30000			
(See	-	neelbase xx. W. B. rnished	W.	156 195 146 213 146 227 146 227 148 174 148 174	74 192 50 174 192 74 192 50 174 192 59 177	50 160 145 159 78 213 87 158 87 158 87 158 87 158	25 165 203 203 204 204 204 204 25 165 25 165	55 177 99 145 90 109 100 100 11 109	88888888888888888888888888888888888888	0000000	222222222222222222222222222222222222222	8 164 0 176 0 176 0 178 0 188 6 188	881188 2006 8206 1886 1886	00000000000000000000000000000000000000
GENERAL	-	essis Price	ns .	1295 2185 20695 1437 2050 14435 1435 1459 1459 1459 1459 1459	3250 174 3250 150 3250 150 3550 174 3550 174 3875 150 3875 135	3725 150 4050 145 4650 178 4575 137 4900 178 5600 208	5850 165 6000 172 5900 178 6600 204 6150 137 6800 165 7500 236	7500 155 3750 109 3750 109 4650 100 4075 109 4250 91	4875 109 4600 98 5000 98 5600 145 6600 128 6600 145 6100 109 5700 120	1125 Op 1370 Op 1780 Op 1890 Op 2175 Op 3025 Op 4125 Op	1095 145 1295 157 1560 166 1750 180 2205 180 2750 180 3600 157 4200 187	895 138 1240 144 1290 150 1470 150 1560 150 1850 156 1740 156	1900 156 2075 164 2245 164 2285 176 2680 176 2710 176	2850 156 2355 170 2325 164 3295 163 3640 153 3795 153 4290 153
OEN		agenn gnis	Ra	2420	672	4781.07 4781.07 50 70 70 70 70 70 70 70 70 70 70 70 70 70	10	22000		e 70	11110004	67276 e	144	
_		-2000	-4	11H 174 21Ha 274 41Ha 474 61Ha 6-7 TRD 10 RDA 12 RDA 12	RHHT162% DT74-9 DF77-7-8	DHP3X NNFSTATA	Trong Trong	UDDE SESSION OF THE S	UNF 65% UNF 65% UNF 87% UNF 87	75.70 To 1000	2005 2005 2005 2005 2005 2005 2005 2005	90X 2222 90X 22222 90X 222222	mmmmmmm	403-37 4137-4137-4137-4137-4137-4137-4137-4137-
		MAKE AND MODEL		(T) TRT (T)	SEESESE	992E22E	<del>9</del> 222692	636936 F-5555	26262226 <del>0</del>	X3 <sup>88</sup> 888	8		125X 130 130 150X 150X 150X 150X	140 141 130-PS 160X 170X 176X
		MAN		Armleder.	Autocar (7)			e.u.s.		Available	Mederman	Brockway		
		se Number	Lin		00-02-00	16 20 20 21 22 22	24232333 2450520	00000000000000000000000000000000000000	8288894444		255477777 255477777 255477777		7770882	477 755 F

HHE

0-49x44,3814 4376106-28007-22xx134 YEU 6A53 6 Wm 1397BH 2F R15 63-8 59 Shu 15685B1 1.41HV 600 772 a CD 834 8.5428x4 6 -49x25, 501 6334 135-22007 -22xx134 YEU 6A53 6 Wm 1375BH 2F R15 65-8 59 Shu 15685B1 1.41HV 600 772 a CD 834 8.5428x4 6 -49x25, 501 6304 135-22007 -22xx134 YEU 6A53 6 Wm 1375BH 13

195 X [6-7] 195 X [6-7] 195 X [7-10] 220 X [7-10] 220 X [7-10] 220 X [7-10] 230 X [7-10] 230

10000

PHEER ODOODO HEHHEE	H HHAHAAA		0000000		ы	00000000	D0000000	0000	XXXXX	DODEHHHHHH	gg
***** ********	N N -in N -en-in-in	14 %	nie.	**************************************	×	4545 454545	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX				44 44
10000000000000000000000000000000000000	12x3 7-4x2 10x2 10	0 0 0 0 0 0 0 0 0 0 0 0 0 0	10000000000000000000000000000000000000	2 4 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	12x2 }	**************************************	10000001111111111111111111111111111111	7x // x /	6x3x 6x3x 6x3x 6x3x 6x3x 6x3x	00000000000000000000000000000000000000	XXX XXX
88882121 88882221 48882688 88882677 88888888 88888888888888	0.000000000000000000000000000000000000	00000 138 00000 138	77 801 108 811 82 83 84 84 84 84 84 84 84 84 84 84 84 84 84	2000222222222000	77 1/4	\$5555555 \$555555 \$55555 \$5555		888.00	75.5 82 107 107	777777777777777777777777777777777777777	100/00
999999 HHHHHHH XXXXX999	8 KKKKKKK	XXXXXX	DODAKKK	FXXXX555555555	FD	XXXXXXXX	SHAHAHAH	5555	XXXXX	1999944444	22
782787878787878787878787878787878787878		380 380 380 578 660 922 8922 8922 8922 8922	80000000000000000000000000000000000000	20020202020202020202020202020202020202	501 a	251 310 a 310 a 310 a 310 a 406 a 406 a	8655228 B B B B B B B B B B B B B B B B B B	485 6055 8666 888 888	438 578 859 859 8659	00000000000000000000000000000000000000	
2550000 2550000 25500000 2550000000000		22 22 23 23 23 24 24 24 24 24 25 25 25 25 25 25 25 25 25 25 25 25 25	29888840 60888888 60888888 60888848	944444444000 00000000000000000000000000		250 262 262 262 262 262 262 262 262 262 26	244884448 66699999999 2499999999	399 504 554 554	33333 333333 333333	01000000000000000000000000000000000000	
Marian   M		LAIH LAIH LAIHV LAIHV WS4IA	[41H   [41H   [41H   41H   4	######################################	L4IHV	90000000000000000000000000000000000000	041H 041H 041HV 041HV 041HV 041HV	141HV 141HV 141HV	1414141 1414141 1414141	44444444444444444444444444444444444444	LAIHV LAIHV
1885581 1885581 1865581 1865581 1865581 1865581 1866581 1866681 1866681 1866681 1866681 18668	27450 F266 F266 31000 31000	14F 34F 33000H 33000H 5000TW 7450TW	30000H 31000H 33000H 33000H 35000H 26450H	88888888888888888888888888888888888888	33000H			5572 5572 5572 637	F264 F308 F320 F320	000001 000001 002001 002001 002001 002001 002001	H0000
Shu	T SSESSION TO SESSION	THE SECTION OF THE SE			Tim		O O O O O O O O O O O O O O O O O O O	Shu 55 Shu 55 Shu 55 Shu 55 Shu 63	CC B FE		88
24 25 25 25 25 25 25 25 25 25 25 25 25 25	0 00001-1- 0 000000400	14-6.6 8-6.8 28-7.4 56-7.8 85-9.41 90-11.1	56-6.6 12-6.8 12-6.8 444-7.4 55-7.8 64-10.3	6666633 6666633 6666633 6666633 6666633 6666633 6666633 6666633 666666	-	65.55.55.87 65.55.55.87 84.55.87 84.	22-6 22-6 33333 1-8-7-6 1-8-7-6 57	&&&& 4.4.6163	62-6.28 42-7.16 42-7.16 42-7.16 42-7.16	00004040404	ගත
RESERVED COCCOCC RESERVED	<b>К</b> ППППППП - 0444440	1010101010100 F-00	生生生生生らら		6	<u> </u>		HRRH 6.60.00	200000 04454	######################################	00
PETETE SEPTEMENT REPETE			BET WELL	00000000000000000000000000000000000000	BF	www.www.ww Zrirrirrir	<u> </u>	W/2F W/2F W/2F	000000 FFFFF	BET BET WE	88
18278.H 18378.H 17378.H 17378.H 1810.W 1850 1850 1850 1850 1850 1850 1850 1850	76733W B373 53300 54411 55411 56410	54400H 54400H 56200H 58205H 65720H 66725TW 68725W	53300H 54410H 56200H 58205H 65720H	R650 R750 R950 R950 R950 B616 B616 B645 B645 B645 B645 B645	58200			65200 75733 76733	B8001 B642 B642 B805 B805	53200H 54411H 56411H 56410H 56410H 56210H 65725H 65725H	6725H 6725H
5 Wisser	WI SHIFTEL	444 444 444 444 444 444 444 444 444 44	A44444 EEEEEEE	55 CCB H H H CCB	THE	000000 0000000 00000000 00000000000000	Own Own Own Own Own Own		200000	44444444444444444444444444444444444444	EE E
5453 5453 5453 5453 MHUU MHUU 7351 7351 7351 7351 7351 7351 7351 7351	779 T9 T9 185F 200V 200V	G T-9 A B-116 5A380 5A380 5A530 5A530	000000		_		4.	513332			
	20000€€€ 2	₹2555€	WG T9 WG T9 WG T9 Fu MCU Fu MGU Fu MGU	WWWGGTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTTT	BL 31	000000000000000000000000000000000000000		BL 235 BL 335 BL 335 BL 535	Cla 200V7 Cla 270V Cla 270V Fu 5A53 Fu 5A53	WG T9 BL 234 WG T9 BL 3341 BL 3341 WG T9 WG T9 BL 5241 BL 5341	BL 534 BL 534
CACACA NNNNNN ACACAC	14/4/4/4	ZZZZZZZ	**************************************	KKKKKKKNNNN KYKKTTTTTTTTTTTTTTTTTTTTTTTT	¥ 8/4	ZZZXXZZZ	<b>まままままた</b>	KKKK No.22	ZXZXZ ******	KKKKNNNK K	>2
	# AAAAAAAA	2000000 00000000 000000000000000000000	STANKE STANKE	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	8x9	4444444 999999999 88888888 88888888	44444	3x1175 3x1175 3x1175 3x1175	SANA NA		24
000000 000000 0000000 000000 000000 000000	220000000000000000000000000000000000000	2252222 2252222 22525222 22525222 22525222	000000000000000000000000000000000000000	000000000000000000000000000000000000000	2800	000000000	000000000	77-2100 7-105-2400 7-105-2400 7-111-2200 7-111	24000 24000 24000 24000 24000 24000	25000000000000000000000000000000000000	
3378 11.0 3388 11.0	25 25 25 25 25 25 25 25 25 25 25 25 25 2	165 72- 185 85- 220 73- 240 85- 274 90- 330 110- 330 110-	142 164 176 176 176 176 176 178 178 178 178 178 178 178 178 178 178	130 1488 633 1488 633 1488 633 1764 688 1764 688 1776 733 1776 733 188 188 188 188		358758888 358758888	150 170 160 170 170 170 170 170 170 185 170 185 185 185 185 185 185 185 185 185 185	213 77 280 105 280 105 336 111	2550 95- 2550 95- 308 118- 284 112-	182 82 28 82 28 82 28 82 28 82 28 82 28 82 28 82 28 28	40 108 40 108
8407077 22 22 22 22 22 22 22 22 22 22 22 22 2		222225 232225 232225 2404 2400 2440 2440 2440 2440 2440	44444444	02322222222 0232222222222 0232222222222	4.9	20000000000000000000000000000000000000	<b>あ</b> 4544770	4444	R04444 05-00	-8-44-80	10.44 64.10
ままれまる スススススス メメスススープ みかららら ますもすもます はままます かんりょう	MA MANAMANA		444×4448 444×4448 444 ×44		1 10	**************************************	######################################	444 444 444 444 444 444 444 444 444 44	xx x4 % 248 x4 % 383 x4 % 4 28	## # # # # # # # # # # # # # # # # # #	10/10
44444 000000000 00000044	4 00000000	<b></b>	00000000	@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@@	6-3%	100/00/01/01/01/01/00	/4 /00/4 /00/00/00/00/ta	63/00/00/edge	00400 04444 %%%%%	* * * * * * * * * * * * * * * * * * *	44
338 358 358 358 358 358 358 47 V12 14LD196 DJXB DJXB CLD275 (CLD275	XBKH XBKH XBKH KBKH 6BKH 6BKH 6BKH	6BL 6BK 6MS 6MZ 6MZ 6MZ 6SRK 6SRK	JXA JXC JXC WXC WXC WXC WXC WXC WXC	OXA3 JXAA JXAA JXAB JXCB JXCC JXCC JXCC WXLCS WXLCS	ASD			K325 K428 K428 L525	20C E603 20R-0 21R-0	688K 6890 688K 6MK 6MK 6-110 6-110 6-110 6-110	au 6-125 au 68RK Specificatio
Bulleter OOOOOO ACCOUNT BURNESS OOOOOOOOOOOOOOOOOOOOOOOOOOOOOOOOOOO	**************************************	WW WW W W W W W W W W W W W W W W W W	ненене	Here Here Here Here Here Here Here Here	Lyc			Budded	00000	Wau Wau Wau Wau Wau Wau Wau	Wau Wau
110.26/24 111.25/24 111.25/24 111.25/24 111.25/24 111.25/24 125/26 125/20 125/2	8.25/20 34x7 8.25/20 34x7 9.75/20 10.50/20	7.50/20 8.25/20 9.00/20 9.75/22 10.50/22	7.00/20 7.50/20 8.25/20 9.00/20 9.75/22 10.50/22	7.00/16 7.00/26 7.00/26 7.50/26 8.25/26 9.00/26 9.75/26 10.50/26	9.00/20	6.00/168 7.00/208 32x68 6.50/208 7.00/208 32x6 7.50/20	7.50/20 7.50/20 7.50/20 8.25/20 8.25/20 9.75/20 10.50/20	9.00 10.50 11.25 11.25	7.00/20 8.25/20 9.00/20 9.00/20	99999999999999999999999999999999999999	10.50/20 10.50/20
100 200 200 200 200 200 200 200 200 200	10.50/20D 6.00/20S 6.00/20S 6.00/20S 6.00/20D 7.00/20D	0/20D 0/20D 0/20D 5/20D 15/20D 10D	00/20D 00/20D 00/20D 00/20D 00/20D 50/20D	00/168 00/208 00/208 00/208 00/209 00/20	0/20D	00/168 00/2048 00/2048 00/208 00/2048 00/2048	6.00/2048 6.00/2048 6.00/2018 6.50/20D 7.00/20D 8.25/20D 9.75/20D	5/20D 5/20D 50/20D 50/20D	20000 20000 20000 20000 20000	0000000000	20D 20D 4els o
2000 200 200 200 200 200 200 200 200 20	3300 6.0 3350 6.0 3900 6.0 3900 6.0 4100 6.5 5450 7.0	200 7.5 870 8.2 870 9.0 100 9.0 100 9.0 40.0	900 6.5 300 7.5 500 9.0 500 10.0	22750 60 23750 60 23750 60 23750 60 24300 60 24200 60 25300 70 25300 70 27300 8.25	0	2015 2885 2885 2885 2985 3985 3985 3985 3985 3985 3985 3985 3	3210 8.0 33210 8.0 33300 6.0 33700 6.0 5550 8.2 7975 8.2	6800 8.2 7900 9.7 8550 10. 9000 10.	3350 6.5 5900 8.2 6300 8.2 7700 9.0	4400 6.50 5200 7.50 5100 8.25 6400 8.25 550 9.00 7850 9.00 8350 9.00 8350 9.00	000 >
	00000000000000000000000000000000000000		111200 113200 119500 255300 255300 255300 255300	20000000000000000000000000000000000000		6200 6200 9500 9500 1500 8			00000	9999999999	000 000 enst
25555555555555555555555555555555555555	82 0000000	25.22.20 22.22.20 22.22.20 23.20 20 20 20 20 20 20 20 20 20 20 20 20 2	20222 2044 2344 2344	28822222222222222222222222222222222222	1 091 0	200 200 200 200 200 200 200 200 200 200	88888888888888888888888888888888888888	0000	180011801180118011801180118011801180118	00000000000000000000000000000000000000	000 +
27.95   140	8925 145 1565 136 1635 136 1850 136 2525 136 2955 136 3175 136	1095 16 1665 16 1740 17 100 17 115 19 160 19	945 1245 135 1495 156 22495 165 2945 165 4095 165	525 119 119 155 119 119 155 119 119 119 11	200 16	370 5055 112 5555 122 5055 123 545 125 570 125 570 125	25000000000000000000000000000000000000	3860 166 4800 172 5200 172 5650 172	1100 145 2860 165 3200 165 3450 190 3700 190	88577885	800 182 300 182
2000 ******* * ******** * ******** * ******	74.74	440 5 40 V		~~~	60	no 222	22424008 66 4 22	64100	222 222	fee.	-
	250 260 260 260 260 260 260 260 260 260 26		20111186 10111186 10111111111111111111111	222-80 222-80 222-80 2222-80 2322-80 2022-80 2	E-131 215		CKEA-235 CKE	BAC SAK	1.1.1	LODGE STATE OF STATE	Rear 3
Very Masser Mass	PACW BOW CCW CCW CDW CDW	Series 18 Series 22 Series 27 Series 27 Series 35 Series 40	7-Elder 76 1 1 1 2 1 1 2 1 1 1 2 2 1 1 1 2 2 1 1 1 5 2 2 1 1 5 2 1 1 5 1 5	212 AS 212 AS 212 BS 22 BS 22 BS 22 BS 313 320 313 320 412 B 412 B 412 B	-	Bros. LC 5 LE15 9 LE20 1 LF28 1 LF29 1 LE30 1 LE30 1 LE30 1 LE30 1	LF35 LT 35 LT 35 LT 35 LT 35 LE45 K600 G80	0.00	33. 13.	106BK 135HF 2135BK 250MK 250MK 250MK 260 300RA 300RA 300RA 300RA 300RA	370
Chevrolet Mas. 1. (13) Master B. (14) Master B. (15) Mas. Sp. R (17) Master B. (16) Master B. (17) Mas. Sp. R (17) Master B. (17) Mas. Sp. R (17) Mas. Sp. R (17) Mas. Sp. R (17) Master B. (17) Mas. Sp. R (17) Master B. (17) Mas. Sp. R (17) Master B. (17) Mass. Sp. R (17) Master B. (17) Master B	9 g	Corbitt	Day-Elder		Differential	Dodge B		uplex.	Eaco	<b>Fage</b> 60	نها نب
######################################			120 120 120 120 120 120 120 120 120 120	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		800012544 00012544 0	1144 1150 150 150 150 150 150	155 155 156 157	158 159 160 161 162		6
June, 1936											

AL

		Type	DODDOD OFFICE	ı
	1	Side Rai	SOCIOLE ASSOCIATION ASSOCIATION OF THE ASSOCIATION OF THE PROPERTY OF THE PROP	ě
	Tolegan	240-	80000000	8x3x34
	1	Materis Hand L Type	GUEDEE KAKKAKUE ESTIETEET 224 2774445 KAKKAKKA KAKKAKAKAKAKAKAKAKAKAKAKAKAKA	100
	RAKES	Drum	SECTION OF THE PRODUCT OF THE PRODUC	社
	E E	Operat Lining Area	25.50.50.50.50.50.50.50.50.50.50.50.50.50	578 8 8 8 8 8
	uo	Make Locati	######################################	342
1	AXLE AXLE	Make	日本日本日本日本日本日本日本日本日本日本日本日本日本日本日本日本日本日本日	LAIH
	daiH ni s		2000 000 000 000 000 000 000 000 000 00	F308
	oita	Dear	本名の	37 Cla
11	A Suprof &		FEFFICE CHARACTER CHARACTER CHARACTER CHARACTER CANADA CONS	5 10 6
	XEAR.		OSCORDA HINTHIN HINTHIN A STREET SOCIETA STREET STREET SOCIETA STREET SOCIETA STREET STREE	HHH HHH
	pue a	pla.M.	25-5558 8628888288	
-SS	s'bq2 bray	rio-l	444444 44444600 004460000 440 044444444 000444600 00001111111 FEFFERENCE 4888 4888818 8888	Cla B642 Cla B377 Cla B470
TRANS.	Pus a	Jam S	ななない。	একক
p.	ernor Standar	voD S		Fu 5B290 Cla B363 Cla B363
	mber, earings meter geh	Bid 2	AKK AKKKXXXX KAXX X KAXXXXXX AKXXXXXX AXXXXXXXX	****
	.M.4.N.S	2800 Z	200000 00000000 0000000000000000000000	2000
DETAILS	rque lb. ft.	EM 155	252255	30000
	mp. Ratio	00 00	77 4	65555
ENGINE	roke splacement	20 70	2000 - 0.000 -	0000 0000 0000
	o, of linders, ore and	N T	PRODUCT TITITITIES CONCORDANCE	222 222
	ske sud	6-125 6-125	THE PRODUCT OF THE PR	2000
SIZES	mumixel size size bedeintu	50/20 W	Name	Wau 6BL Wau 6BL Wau 6BL
-dua	ba l	5/20D	0000 0000 0000 0000 0000 0000 0000 0000 0000	34x7 34x7 34x7
-	Chassis Wt. Stripped)	0.00	00000000000000000000000000000000000000	2000
Ney note)	Gross Vehicle Weight with Max. Tires	2000	(1) (1) (1) (1) (1) (1) (1) (1) (1) (1)	4100 6. 4880 7.
1 200 K	Wheelbase Max, W. B. Furnished	2000	282 4 11-11-11 4 20 20 20 20 20 20 20 20 20 20 20 20 20	11500 20000 18000
GENERAL	Chassis Price Standard	200	###   ################################	118 130 130 150 136 156
	Tounage		100   100	1355 1355 1620
			and the second of the second o	3300
	MAKE AND MODEL	. 200	THE REPORT OF THE COLUMN TO SEE STATE OF THE PROPERTY OF THE P	15T 19A 19A 2
	¥ ,¥	(D) co	Technol (D) (C) (C) (C) (C) (C) (C) (C) (C) (C) (C	
4	Line Mumber	Tie .		
			######################################	10000

Jun

ı											31
ı			-	-	-		+++++++++++00	00000	コリコココココ	00000000	00000
ı		×		*******	MON Months in in in	44%		*******	XXXXXXX		-0-0
ı	THE PRESENT	8888889788888 88888888888 8888888888 88888888	2202 + 22 1 2	**************************************	STANKANA MAHAH	K K K K A A A COCO	**************************************	Sassassa XXXXXXX	XXXXXXX	******	XXXXX 332223 XXXXX XXXXX
ı	S NOON WENT THE WAY WAS AND WA	80000010000000000000000000000000000000	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	00 00 00 00 00 00 00 00 00 00 00 00 00	22222222	F 8 8 8 9 9 5 5 5	00000000000000000000000000000000000000	2011110 2011110	10x3 10x3 10x3 10x3 12x3 12x3	6x3x 6x3x 6x3x 9x4x 9x4x 9x4x	2-6-6-20
I		22 2 22 2522222 2522223 252223 252223 2523 25223 25223 25223 25223 25223 25223 25223 25223 25223 25223 2523 25223 25223 25223 25223 25223 25223 25223 25223 25223 25223 25	899999999	\$5000000000000000000000000000000000000	2000 - 2000 2000 - 2000 2000 - 2000	03					#222
l							886885555558 <b>33</b>		99999999	20000000000	25 57 60 75
ı	HHHHHHH	888888888	564444444	88888888	MANAN NAME OF THE PROPERTY OF	<b>EXXXXXX</b>	XXEXESSESSESSES	5555555	XXXXXXX	XXX55555	XXXXX
I	*********	ಡವಾ ಮಾ ಪಡೆ ಪಡೆ ಪಡೆ ಪಡೆ	0000000000	00000000		00000000	ನನನನ ನನನನನನನ	0000000	ಪೆ ಮೆ ಮೆ ಮೆ ಮೆ ಮ ಮ		
ı	244420 2524420 25252 252	894 4680 4444 660 660 660 660 660 660 660 660 6	44444444444444444444444444444444444444	659 768 843 768 891 891 817	4488888444 4488888444	412 478 478 678 678 961 961	20000000000000000000000000000000000000	8645548 84558 84558 8458 8458 8458 8458	616 672 754 770 990 930	::::::::	2864 28664 238664 00000
ı	20000000000000000000000000000000000000	865056000000000000000000000000000000000	44000000000000000000000000000000000000	2845468 28468 28468 2868 2886 2886 2886 2886	191 191 201 201 201 201 201 201 201 201 201 20	291 3339 377 477 720 720	888888444884448444444444484848484888888	845548 845548 845548 8458 8458 8458 845		000000000	
ı						>>	555		010000044	00000000000000000000000000000000000000	172 295 295 350 350
ł		AHHV HHHV HHHV 22IM 22IM 22IM AA 22IM		LAIHU WAIA WAIA WAIA	HEHHHHH	HEHHHHH	141H 141H 141H 141H 141H 141HV 141HV 141HV 141HV 141HV 141HV 141HV 141HV 141HV 141HV	L41H L41HV L41HV W84IA W84IA	田田田田田田	AIRV AIRV AIRV V84IA	HHHH
ı	22222222	7777788848	333333333	22≥222≥≥	84448 8444 8444 8444 8444 8444 8444 84	BUREALER	<u>3333333333333888</u>	<u>222228</u> 8	2222222 HFFFFFFFF	22222222	33333
ı		5 27 27 27 27	0020H 0020H 0020H 1020H 1020H 1020H 1020H 1020H 1020H	KARBBBBBB	12. H 12. H 13. H 13. H 10. S 10. S	HHH 088 HHH	HHHHHHHHWNNN	00000H 110000H 3020H 5120W 6450W	HHHHHHH	HHHHHHH	
ı	F3208 F3208 F3208 F3208 F3208 F3208 F320 F320	632-5 F320 632 632 5550 610-10 633-11 655-27		15582B 15582B 15582B 15582B 15592B 16533W	F-50 15 H-50 15 102 15 H-103 H-103	H-108 H-108 251H 300H 503	330000 330000 330000 330000 330000 330000 330000 330000 330000 330000 330000 30000 30000 30000		3300 33000 33000 35100 35100	30000F 31000F 33000F 33000F 33000F 32500F 2605T	
ŀ		Shu u	Shudson of the state of the sta	Sepan and a			8888888888888	8888888	88888888	88888888888888888888888888888888888888	R20 R30 R40
ı	16 000000000000000000000000000000000000	95 125 125 135 135 135 135 135 135 135 135 135 13	828684886 83732	1-000000000000000000000000000000000000	81283888	98898989	FEFEFFFFFFF	FFFFFF	-	FFFFFFF	ZZZZZ
ı	10-1-1-1000001	20*8 00*7 00*7 00*8 00*8 00*8 00*8 00*8 0	24-1888-14-14-15-14-15-14-15-15-15-15-15-15-15-15-15-15-15-15-15-	77070000	4:04:000 81-15			0040000	000-1-000	17777788	40000
ı	4200044404	×0000000000000000000000000000000000000		446666		1000000	00000000000000000000000000000000000000	417773	88772538	88444400	0101010101 0101010101
I		FEETEREEE	HHHHHHHH	我我我我我我		HHHHHHHH	HHHHHHHHHH		我我我我我我	######## 900000	<b>田田田田田</b>
۱	***********		KKARKKEEKK	4444444	NANONONAN NATET FFF	E E E E E E E E E E	TEFESSMETFFFFF	THE PERMENT	FFFFFF	ARREST EN	ZFFFF
		1237B 3805 72000L 72000L 1337BH 1337BH 1337BQI 1737BQI 1737KW			6H 6H R-60 H H 125H 35H	lest III	<u>напапапа</u>		her had hed hed . best hed		00.00.00.00.00
l	B642 B642 B6470 B642 B642 B642 B642 B642 B642	2371 805 2000 2000 2000 3371 7371 7371	5330 5330 54413 54413 56411 56411 5620 7200 5820	72000L 1337H 1337H 1337BH 1627KH 1910W	R-56H H-56H 708H 708H H-725 730H H-735	30 1 1541 301 301	56200H 56200H 56200H 56200H 58206H 58206H 58206H 58206H 76736 76736	53200H 54200H 56200H 75733H 76733W	53300F 54410F 56200F 58205F 72000L 75733F	53300H 54410H 56200H 58205H 58205H 58205H 65720H	
ŀ	ನವನನೆ ಮನೆ ಮನೆ ಮನೆ ಮೆ	2 2 2 2 2 2 2 2 2 2 2	TIMES STATES OF THE STATES OF		OWD TOWN TOWN TOWN TOWN TOWN TOWN TOWN TOWN	THE GOLDE	25 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	BBBBBB 8554 87558 87558	10 10 10 10 10 10 10 10 10 10 10 10 10 1	85588888888888888888888888888888888888	135
ı	22222222222	808888888	HULLUL SHSL	#4454460 \$XXXXXX	00000000	5 0 wn 5 0 wn 5 0 wn 5 0 wn 5 0 wn 5 0 wn		<u> </u>	てていい はいいい	FFFFFFFF	MANAM
ı	2000.00	200000 00						444444	はななららなる	के के के के के के के क	034444
ı	68290 8363 8363 8363 8363 8363 68290 68290 68290 68290	MRUAY 54380 54380 54530 54530 5341 5341 5341 54530	2353 2354 2353 2341 2354 2341 2341	3341 5241 5341 534 7351 7351	OCCUPANTA TO	H5 H5 H7 H7	7.775.88.85.89.88.89.89.89.89.89.89.89.89.89.89.89.	4444404	6	bo444424	
l	Fu Sola Sola Sola Sola Sola Sola Sola Sola	Fundanta Spirato	WG W	BEL 55 BEL 55 BE	0000000 000000000000000000000000000000			BL 224 BL 324 BL 324 BL 324 BL 524 BL 535 BL 734	WG 1	WG T9 WG T9 BL 234 BL 3341 BL 3341 BL 3341 BL 5351 BL 5351	RS R1B R1D R2B R2B
ŀ	九人人人人人人人人人人人		P P P P P P P P P P P P P P P P P P P			KKKKKZZZ	KKKZZKKZZZZZZZ	NXXXXXX	0000000 KKKKKK	MARKAZZZZZ	ZZZZZ
ı	0000000	tatakakatatatatak	2000000mm	Z war-	prior/Marie prioritarios	Standards and and the forest	551 27171 X51 251 X X X X X X X X X X X X X X X X X X X	工工士士士 工	747474	74747474 74	-0-10-10
ŀ	SAKKKKKKKKKKKKKKKKKKKKKKKKKKKKKKKKKKKK	SXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	AKNXKNXXX4	446400XX	04000000000000000000000000000000000000	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	XXXXXIIXIXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	1 X X X X X X X X X X X X X X X X X X X	333XXXXX 333XXXXXX	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	XXXXX 2000 1000
	2000000000000		200000000000000000000000000000000000000	000000000	404000444	00000000000	22222222222222222222222222222222222222	20000000	SANGER SANGER	NONNING OF	SICHOLOGY STATES
l	\$2000000000000000000000000000000000000	000000000000000000000000000000000000000	24-6000000000000000000000000000000000000	80000000000000000000000000000000000000	83400 83400 83400 83400 83400 83400	22500 22500 22500 22500 22500 22500 22500 22500	999999999999999999999999999999999999999	8888888	3200 3200 3200 3200 2500 2400 7400	25000 25000	30000 30000 30000 4477
l	888888888888888888888888888888888888888	107- 107- 107- 107- 107- 107- 111- 111-	00000000000000000000000000000000000000	94-2-2-2-2-2-2-2-2-2-2-2-2-2-2-2-2-2-2-2	6.60444777 8060440000	8777888888	83 20 20 20 20 20 20 20 20 20 20 20 20 20	68-28 70-30 80-27 90-27 118-25 125-180	500000000	73 30 855 32 855 32 10 28 25 26 27 20	88888
l		23000000000000000000000000000000000000	135 1644 1644 176 176 176 176 176 176 176 176 176 176	282833 28283 28283 2828 2828 2838 2838	8864 864 125 125 160 160 160	160 160 160 171 181 181 181 181 181 181 181 181 181	88480048080086	4440000 0rected	2555555 25555 25555 2555 2555 2555 255		FF-0000
H	444444000	00 00 00 00 00 00 00 00 00 00	र विवास सम्म स्वास	44 400	幸工すりのううかき	生生なでででる	7447708 988044 19828 988044 19828 98808 19828 9880 19828 9880 1982	44922 · · · · · · · · · · · · · · · · · ·	2441130 8322228 8323233	1165 1165 1165 1165 1165 1165 1165 1165	44144 44144 175 175
l	44440000000000000000000000000000000000	400440444400 0000000000000000000000000		444440000 8234820000 44.4440000 44.4441	21221232 22222222 22222222 222222222222	88880 8 808 € 1000 4 100 4 4	2882 2882 2882 2882 2882 2882 2882 288	8888788 8644477	50000040	10101041010104	10101010101
	44444444444444444444444444444444444444	14.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.	7474747474 74	444444	2 20000	9999999999	22 222 2 222 2222222222222222	777 % 8988 4440 888 887 847	222222 222222 2222222 2222222	7777 7 2222888446 44886845 5523-8855	2000 2000 2000 2000 2000 2000
	********	**************************************	44444444 XXXXXXX	A 4 C 4 C C C C	*******	できてきるようならる	母母 百年日本 百日日	生 生 生 く も よ り り	*****	4444/4/0/4	***** ******
ı	22222222222	744444444	4000000000	4444444	64644666 666666666666	00000000000000000000000000000000000000	00000000000000000000000000000000000000	80004444	00004444	000044440 744444	
		00 00 00 00 00 00 10 10				882 882	72.72.24 . 0	6.6	6666666	<u> </u>	00000
	68888888888888888888888888888888888888	K428 K369 K369 K428 K428 K428 K428 L525	Her JXB Her JXB Her JXC Her JXC Her JXC Her WXC Her WXC Her WXC	SAN	PARA BOAR	FAI FAI FBI FBI FBI FBI	Her JXCM Her WXCM Her WXCM Her WXCZ Her WXCZ Bud M6+15 Bud D6+15 Bud D6+15 Bud M733 Her X333 Her RXB Her RXB	HE RESKY	PER MER BRANCH	6BL 6BL 6BK 6MK 6-110 6-125 6RB	0.000000
	Wau Wau Wau Wau Wau Sud Sud	Bud H		e de de de de de	WD Vau Vau Vau WD WD	WD GWD	ass in a second	er J	na n		R209 R228 R228 R268 R268
	9 000 0	000000400	<b>МИМИМИМИМ</b>	2 2000	0>0>0>000	00000000		##000000	8888888	**************************************	ZZZZZ
į	5777775 9 9 9 9 9 9 9 9	00/2/20/20/20/20/20/20/20/20/20/20/20/20	7.50/20 8.25/20 17.50/20 17.50/20 17.50/20 17.50/20 19.00/20 19.00/20 19.00/20	25/50/20/20/20/20/20/20/20/20/20/20/20/20/20	00/200	25/22	8888888888888888	00000000	8888888	8 88888	50/168 50/20 50/20 25/20 25/20
	34444499999999	000000000000000000000000000000000000000		9.0	000000000	344 364 364 364 1100 1100 1100 1100 1100 1100 1100 11	9.00/20 9.00/20 9.00/20 9.75/20 9.75/20 9.75/20 9.75/20 9.75/20 10.50/20 10.50/20	7.56 9.00 10.10	8.26 8.26 9.75 9.75 10.5	32×6 8.25/20 34×7 9.75/20 9.75/20 9.75/20 10.50/20	8.255
	2222222222	/20D /20D /20D /20D /20D /20D /20D /20D	6.00/208 6.00/208 6.00/208 6.50/20D 8.25/20D 7.25/20D 8.25/20D	2222222	00000000000000000000000000000000000000	30x518 6.50/20D 6.50/20D 32x6D 34x7D 9.75/20D	32x6D 7.56/20D 7.56/20D 9.00/20D 9.00/20D 9.00/20D 9.00/20D 9.00/20D 9.75/20D 9.75/20D 9.75/20D	2000 2000 2000 2000 2000 2000 2000 200	6999999	88888888	7168 72015 72015 72010 72010
	22222222	9.75/ 9.000/ 9.75/ 11.25/ 11.25/	888888888888888888888888888888888888888	25/25/2000/2 25/2/2 25/2/2 25/2/2	00/1 000/1 000/1 000/2 00/2 00/2 00/2	00000000000000000000000000000000000000	20202020202 2020202020202 2020202020202	7000000 7000000 7000000000000000000000	\$555555 \$2000 \$2000 \$2000		88888
į	220000000000000000000000000000000000000	000000000000000000000000000000000000000	50000000000000000000000000000000000000	2222222	<ul><li>おりある後の数4</li><li>のなどのなるなるなる</li></ul>	00000000000000000000000000000000000000	000000000000000000000000000000000000000	0000000	777.80000 777.80000	00000000000000000000000000000000000000	
ı	44444444000	58852222883	3250 3350 3350 3550 4400 6550 6550 6550 8550 8550 8550 8550 85	80 23 20 20 20 20 20 20 20 20 20 20 20 20 20	STANGER STANGER	877 444 666 666 666 1159	4400 55490 55500 66000 7500 6890 6890 6890 9500 9500 9500 9500	395 440 515 650 760 950	8688 8688	02000000	433555 4055 4055 4055 4055 4055 4055 405
1	20000 20000	18165 22000 32000 26000 38000 18000 18000 24500 38105 35620			4400 4400 6500 7100 11500 11500	000000000	113400 1153000 1153000 1195000 1195000 1195000 1195000 1195000 1195000 1195000 1195000 1195000 1195000 1195000 1195000	11200 113400 22000 22000 22000 26000	8888888	8888888 :	:::::
1	120 120 120 120 120 120 120 120 120 120	8-000000000000000000000000000000000000	00100000000		2500× 5200	24401172	000000000000000000000000000000000000000	28888	822222	13200 15000 17000 19500 19500 24000	11111
1	2000000	28 125 25 25 25 25 25 25 25 25 25 25 25 25 2	31 180 31 195 31 195 31 195 31 195 41 186 41 200 56 212 70 224	888999999 888999999	533335533 53355555	66175 66175	00400000000000000000000000000000000000	100000000	2255777 22557777	20000000 20000000000000000000000000000	:0000
1	0000000000	2070 158 22955 137 23855 166 33540 137 4770 128 645 128 6645 128	20004 00000 EEEEE 44000		55 113 55 113 55 113 55 1133 55 1133 56 1133 57 1133	64444490	440400000000000000000000000000000000000	0000000 000000000000000000000000000000	177777777777777777777777777777777777777	\$555555 \$65555 \$65555 \$65555 \$65555 \$65555 \$65555 \$65555 \$65	86838
1	200000000000000000000000000000000000000	000 000 000 000 000 000 000 000 000 00	0.000 0.000		414 5415 585 585 585 705 705 705 705 705 705 705 705 705 70	0.420.000 0.420.000 0.000.000	20220202020202020202020202020202020202	22900 22900 32900 4877 5750	1905 2055 2305 2915 3175 5225 5225	1275 1385 1385 1385 2500 2500 3250 6500	535 665 825 1035 1475
	222 222		700 E E E	25 2 25 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	_ 0	0 4 6	ú 44	2 7 7.	/400 44 /4	3 75	
	**************************************		17 2 2 2000		The Think	2004 200-70	2x 4444 xx00	-9999440 740 7400		2400000 0gT	101/00000
	121 154 155 197 197 197 238 238 238	418 427 437 437 437 877 877 870 870 870 870 870 870 870 87	86.78 86.78 88.88 87.78 77.88 77.88 77.88 77.88	MANAMAN MANAMA	200 N 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	AA7000000	88 192 192 198 146 146 166 166 166 166 166 166 166 166	8086060	MXH 4400	2006 2006 2006 2006 2006 2006 2006 2006	ZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZZ
			86 1 86 1 87 2 88 2 95 D5 2 95 D7 17 A	17DR 20DR 22DDR 43DB 45DR 47DR	3.0000	CS35 CS40 CS50 CS50 CS50 CS50 CS50 CS50 CS50 CS5	4000001244		olic.	1000000	100 200 300 300 300 400 500 500 500 500 500 500 500 500 5
					(3)		g :: : : : : : : : : : : : : : : : : :		ebm	0.0	
	4		ana	ê ê	ernational		86 80	Elber.	A .	8888 : 88	(e.b
	The state of the s		pu		£	111111111	Ken (69)	*	3	3	Mac
۱	900000000000000000000000000000000000000	200000000000000000000000000000000000000	100000000000000000000000000000000000000	284000-88	2222222	128 133 133 133 133 133 133 133 133 133	136 136 137 137 137 137 137 137 137 137 137 137	150 150 150 150 150 150 150	622266	1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	172 N 174 175 175
	June, 19		*******	******	*****	*****					**

DOLL

DX 68 8x3x4 TD Opt 8x3x4 TD Opt 8x3x4 TD Opt 8x3x4

3.000 [00225] [1000] 6.55/20 [0.50/200] 9.55/20 [0.50/24] (0.50/24 [0.50/24] (0.50/24 [0.50/24] (0.50/24 [0.50/24] (0.50/24 [0.50/24 [0.50/24] (0.50/24 [0.50/24 [0.50/24] (0.50/24 [0.50/24 [0.50/24 [0.50/24] (0.50/24 [0

1		Type		ala latare e e e e									
AMP			**************************************	- HHHHHHH	H ODRORA	4444444 A	H-H-H-H-H-H-H-B-C-C-C-C-C-C-C-C-C-C-C-C-	F 000000	ರ ರರ್ಧರ್ಧರ ಸಮ-೧-೫	000000	0000004		re 5255
A da	1	(Std. W. B. Side Rail Dimension	222222	WWW.WWW.WW.	55/83/13 6822/83/13 6822/83/13 8838/41 1082/88/14	00000000000000000000000000000000000000	9 14 x3 14 x y y y y x x 3 14 x x y y y x x 3 14 x x y y y x x 3 11 x 3 14 x y y y y x x 3 11 x 3 14 x x y y y x x 3 11 x 3 14 x x 3 14 x x y y y x x 3 14 x	11x3 to x to	A MXXXX	74/4-10/4/4	KSXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	44.44.44.44.44.44.44.44.44.44.44.44.44.	SENSON SE
	anoist	C-A Dimer	425000000000000000000000000000000000000	000000000000000000000000000000000000000	688 688 885 72 865 865 865 865 865 865 865 865 865 865	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	100 141.41/00/00/00/00/00	-24	MAR / (2) - (2) - (2) - (3) - (4) - (4)	688 688 688 688 688 688 688 688 688 688	00.00.00.00.00.00		
	noiti	Material   Hand Loca Type	XXXXXXXX	X XX XXXX	KEEEEE	S EXECUTED IN	9 0000000	000000			NXXXXX		מאאא ספ
RAKES	CE	Drum Area mund	686 7048 920 920 920 920 976 976	194 194 194 194 704 709		00000000000000000000000000000000000000	2002020 20020 2002020 20020	£ 000000	000000		0000000	D MMOOMM	H Lase
BR	SERVIC	Operat'n Lining Area	244477 2564477 26623 2643 2643 2643 2643 2643 2643 264			9 0100000000000000000000000000000000000	pres p	300 300 300 300 300 300 300 300 300 300		44449999999999999999999999999999999999		- 1-1-0:001-1-	
_		Make Location Type	1 L41HV 04IMV 04IMV 04IMV 04IMV 04IMV		041MV 141HV 141HV 141HV 141HV 141HV	144 144 144 144 144 144 144 144 144 144	141H 141HV 141HV WAB WAB WAB	L/IHV L/IHV L/IHV L/IHV WS41A WS41A	141H 141H 141H 141H 141H	141HV 141HV 141HV 141HV			244202030
FRONT		Make and Model	Tim 52502H Own BG Own AB Own AB Own BM Own BM	WD B	7 D C C C C C C C C C C C C C C C C C C	2000 2000 2000 2000 2000 2000 2000 200	m 31000 n 35000 n 35000 n 25450 n 25450	30020H 31000H 33000H 35000H 35000H					33000H 33000H 33000H 33000H
	цзіН	Gear Ratining in	23-13-10 54-8-92 54-8-92 54-8-92 64-8-92 60-9-67 67-8-92 67	88.921 10.0 10.0 10.0 10.0 10.0 10.0 10.0 10	20 00000000000000000000000000000000000	5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	2 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	6.83 77.77 77.75 7	900000	6.6 Own 8.21 Own 7.17 Own 8.5 Own 8.5 Own	866 866 87 87 87 87 87 87 87 87 87 87 87 87 87	2422244 8888888	Shu TTTT
AXLE	ordne	Drive & 7	44900HH		は は は は は は は は は は は は は は	44400000000000000000000000000000000000	400000 6 8000000 8 80000000 8000000000000	98.50 98.75 98.50 98.50 98.50	222222	HH5.28-662-86-68-68-68-68-68-68-68-68-68-68-68-68-	HH 6.6-5.1 HF 5.83-6.8 R7.83-6.8 R7.4-5.7 R7.4-5.7	24-05-44 88-05-44	722-7-7-7-86-6
REAR	Type	Gear and	TANA CAR	K KACCCKK K		NEW BRANKER	monuscionos Frirrrrrr	SSS WEEK		FFFFF			See Section to a
_	p	Make and	Tim 564111 Own BG Own BF Own AB Own AB Own BM Own BX	OWD A OWD B	Cla B373 Wis 6617 Wis 8817 Tim 58206H Wis 8817 Wis 1458 Wis 8D210	m 5341 m 5441 m 5441 m 5640 m 5640 m 7573 m 7573	EEEEEEE	Tim 54200H Tim 56300H Tim 58200H Tim 65720H Tim 76730 Tim 78720	Spi Own Own Own Own	47 47 47 47 47 47 47			
NS.	e,pdg	Forward	00044000	444440044	5 4440444	य या वा वा वा वा वा वा वा	444444	444444	<u>waaaaa</u> <u>wooooo</u>	4 Own 5 Own 5 Own 5 Own 5 Own	4400000 EEEEEEE	5 Own 5 Own 5 Wis 5 Wis 5 Own 5 Own	5 Own
TRANS-		Governo	Y Fu 5433 Y Own BF Y Own AB Y Own AB Y Own AB Y Own BX Y Own BX Y Own BX	O O O O O O O O O O O O O O O O O O O	Fu MK BL 234 BL 524 BL 528 BL 528 BL 724 BL 724	W S S S S S S S S S S S S S S S S S S S	Spi 224 Spi 224 Spi 224 Spi 5241 Spi 5241	BL 224 BL 3341 BL 334 BL 534 BL 534 BL 724	WG T83 Own Own Own Own	Own Own Cia Own Cia BL	WG T9 Own Fu 5A29 Fu 5A29 Fu 5A38	Fu 5-A-38 Fu 5-A-53 Fu 5-A-53 Fu 5-A-53 Fu 5-A-53	20000
	rings	Length	1001 4449 1001 4449	40,40,400,400	10 0000	ZXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX		**************************************	A:::::	KKK:::	KKKKKKK	*	NNNA POOOO
	5 6 4	Number	23222222222222222222222222222222222222	www.www.www	NONDONO NONDONO NONDONO NO	annanananan	5000000044 XXXXXX	7-25%X 7-25%X 7-25%X 7-25%X 7-25%X	4/4/2/2/2/2/2 4/4/2/2/2/2/2		22222 2222 2222 2222 2222 2222 2222 2222	28,8x13 3x15 3x15 3x15 3x15 3x15	STANKA ST
ILS	ake	Max. Br. H.P. at I	2 90-3000 2 90-3000 100-2800 65-2100 1108-2400 118-2400	4524-252 800000 80000000000000000000000000000	2550055	79-2900 79-2900 85-2900 95-2900 107-2800 107-2800 1107-2800 110-2200	74-2600 74-2600 125-2200 125-2200 125-2200 176-1800 125-1800	73-3200 84-3200 85-2500 90-2400 20-2800 10-2300	282	25800 25800 25800 2600 2600	68-2800 7 73-2800 7 84-2800 7 85-2400 7 66-2800 7 66-2800 7 66-2800 7 66-2800 7 7 7 66-2800 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	85-2400 7 93-2200 7 93-2200 7 15-2200 7 93-2200 7 83-2200 7	32500 32500 255000 255000
E DETAILS	oitas	Comp. L	00 444554 44554 44554 4455 6550 6550 655	0.40444000000 0.000004400	048883-1	24444444444444444444444444444444444444	180 17. 420 17. 420	0.0165 0.0180 0.0274 0.0274 0.0335	444445 0001445 000149 178	2204 204 204 204 204 204 204 204 204	4-7-3-35-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-	7 4 4 2 2 3 8 8 8 8 9 8 9 8 9 9 9 9 9 9 9 9 9 9 9	2022222 2022222 20222222
ENGINE	р	Cylinde Bore an Stroke Displace	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	× × ×	4 /4 /4 /4 ToTA	**************************************	224444 004444 0774 0774 0774 0774 0774 0	245 255 255 255 255 255 255 255 255 255	25222 2522 252 2522 2522 2522 2522 2522 2522 2522 2522 2522 2522 2522 2522 252 2522 2522 2522 2522 2522 2522 2522 2522 2522 2522 2522 2522 252 2522 2522 2522 252 2	200 200 200 200 200 200 200 200 200 200	7474 74 892588888 88250008 88200008	23,22,23,23,23,23,23,23,23,23,23,23,23,2	933555 838888 888888 888888
		10.0N	005440000 000444444 00004444444	404000 0440400044 08404400044 084044 084044	<u></u>	<u></u>	6-6-6-6-6-6-6-6-6-6-6-6-6-6-6-6-6-6-6-	030344034	manana d	000000	6-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4	0000000 444444444444444444444444444444	ECCETA ************************************
			00000000	Own AC Own BQ Own BQ Own BQ Own AP Own AP Own CU Own CU	Was W	Her JXBM Her JXCM Her JXCM Her JXCM Her JXDM Her WXC3 Her WXC3	Her DJXB Her DJXB Her DRXB Her DRXB Her DRXB Her DRXB Cum HB	Wau BL Wau BK Wau MK Wau MZ Lyc AEC Wau SRK	Own Own Own Own Own	wn wn wn uda	er JXB	WXC2	au 6BK au 6BK au 6BK au 6MK au 6MK
SIZES	E win	Maximi Tire Siz	9.00/20 34x7 9.75/20 9.75/20 9.75/22 10.50/24 9.75/24	10.50/24 11.25/24 13.50/24 13.50/24 13.50/24 9.00/20 9.75/22	7.00/208 7.50/208 8.25/20 8.25/20 8.25/20 8.25/20	7.50/20 32x6 32x6 34x7 9.00/20 36x8 9.75/20	32x6 34x7 36x8 9.75/20 42x9 44x10 9.75/20	7.50/20 9.00/20 9.75/20 9.75/20 10.50/24		288888		9.75/20 H 9.75/20 H 10.50/20 H 10.50/20 H 9.00/20 H 9.75/20 H	
TIRE S	S ba	Standa Front a Rear	7.00/20D 32x6D 8.25/20D 34x7D 34x7D 9.00/20D 9.75/22D 10.50/24D	36x5D 10.50/24D 36x6+D 10.50/24D 36x7+†D 32x6 8.25/20D 9.00/20D 9.75/22D	2000 2000 2000 2000 2000 2000 2000 200	222222222222222222222222222222222222222	.00/20D .50/20D .00/20D .75/20D .75/20D .75/20D .75/20D	7,20000	220+8 220+8 220+8 200+8 200-8	000000	0.000 000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.	9.75/20D 9.7 9.75/20D 9.7 10.50/20D 10 10.50/24D 10 9.00/20D 9.7 9.75/20D 9.7 9.75/20D 9.7	2000 2000 2000 2000 2000 2000 2000 200
E .	.1W	Chassis (Stripp	6000 6500 8100 8050 8450 8450 11200 12500	11100 12700 13425 14200 14500 17200 10225 10225 10750 9.	3750 7 5760 7 6200 8 7035 8 6800 8 7200 9	000000000	5800 7.0 6100 7.5 7750 9.0 8250 9.0 9900 9.7 12800 9.7 11000 9.7	6500 7.5 6500 8.2 7300 9.0 8100 9.7 9200 10.8	<b>自自自自合合の</b>	8.250	4500 32x61 4500 32x61 4500 32x61 5400 8.25/ 5750 8.25/ 6600 9.00/2	7400 9.75/ 7600 9.75/ 7750 10.50 9820 10.50 7226 9.75/ 7326 9.75/	900 7.00/ 150 7.00/ 475 7.50/ 525 8.25/ 175 9.00/
Keynote)	ehicle daiw	Furnisi Weight T.xsM			8750 13760 15200 15035 16800 20200 28600	1250 1400 1400 1500 1750 1750 1750 1750 1750 1750 17	15000 17500 222000 22000 30000 42000 42000					24000 25500 25500 72500 735000 735000 7250	3000 5000 7000 2000 54 2000 54 2000 71
AL (See	rd sase . B.	Standa Wheeld	158 158 178 178 178 178 178 178 178 178 178 17	174 228 186 240 192 228 186 240 191 216 126 162 126 180 126 180	144 160 156 175 156 175 165 185 165 185 165 185 165 185	80 180 80 180 80 180 80 202 80 202 80 202	168 180 168 180 168 180 180 202 196 202 222 220 224 220 224 220	57 190 60 200 157 200 157 212 57 212 57 212 58 212	339 166 339 166 339 166 42 166 6 166	66 166 442 166 53 205 56 205 56 205	172 172 175 199 199	46 227 24 56 239 25 56 239 25 54 251 35 50 174 35 50 174 35	2007
GENERAL		Zuman .		0 %	1485 2850 3275 3275 3775 3715 5800	1450 1550 1550 1550 1550 1550 1550 1550	22890 3090 3090 5520 5045 8040	2800 2800 3400 44600 4900 44600	695 695 695 775 925 1075	-	of these hand these three head .		1905 177 2055 177 2305 177 2915 177 3175 177
	•2	Tonna		P0000 4 1 4 4 4	Zie Zi	25242004490 252420210 252420210 252420110	22-31 24-31 24-31 27-31 10 10	7-10 6-9 7-10	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	2 40 x 40 x	24 400 V	-100	New 4 8
	MAKE AND MODEL		(a) BG (b) BG (b) BG AB AB AB AB AB AB AB AB AB AB AB AB AB	AK (AK) (AK) (AK) (AK) (AK) (AK) (AK) (A	DN-C	R-1420 R-175 R-175 R-200 E-220 E-250 H-300		A K L E C B	1A4-1C4 1A4H-1C4H 1B4-1D4 1B4H-1D4H 2B4-2D4 2	2.D4MH 2.15-215 5(315-3K5) 86(318-3K85) 5(415-4K5) 10B	2888 2888 2888 2888 2888	AOH 5- 100 B 7- 100 B 7- 100 B 12 100 B 15- 15 B 15 B 15- 15 B 15 B 15- 15 B 15 B 15 B 15 B 15- 15 B 15 B	) FB50 De L 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
	Jeq um				2		2	4 6		Sch			9 8
		1 4		*						+ +	00000000000000000000000000000000000000	7377798	75 8 77 7 78 7 78 7

TX 107 12x3 4x4 L

CD R 8 56-10 8 Tim 33000H L4HRV 370 794 8 27 R 6 85-9 4 Tim 35100H L4HRV 487 990 8

(c) FC90|4-6 (b) FD116|6-7 (c) FC100|5-6

- XXXX

										59
777777 FF				HAHHHHHHH	FFFFF	HERHERHE	HHHHOO : HHO	2 	XX	PEFF
40 /00 1	· 四・四・四・四・四 ・ 四・四・四・四・四・四	~C~C		74 TATATATATATATA		XX XX	44 4	CONTROL OF THE PROPERTY OF THE	네르니트	
NKKNZZ NK		OC STANKA	HANNANANANANANANANANANANANANANANANANANA	KARRERERE	NNNNN	AND	4-4-XX-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-4-	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	72	14/4/4/4
CC PERMAN	24 24 24 24 24 24 24 24 24 25 26 26 26 26 26	==39999	PARTICULAR DE LA COMPANSION DE LA COMPAN	CHARACACAC	22222±	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	SON	OTTENNA TOTAL	M M	8 X 3 X 9 X 3 X 9 X 3 X
222200 000	00000000000000000000000000000000000000	001-100	********	Anna nama	totototo	P-200-000000	කුතුක කතුතුක කතුතුක දෙකුක කතුතුක කතුතුක	₩ 30 30 30 30 30 30 30 30 30 30 30	60.60	2266
100	32774444	888888	000000000000000000000000000000000000000	100 115 115 115 100 100 100 100			25000000000000000000000000000000000000	82526: 08278	2007	2 × × × × × × × × × × × × × × × × × × ×
	SUSSISISISISISIS		00000000					H A		
EXERN DE	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX		555555555	<b>EEEEEEEEEE</b>	EEEEE	14999944 1	222255555	*525555555	11	21212121
ದಿಯಕಾರು ವರ್	人名人名马马巴巴巴巴	DODODS	<b>ದವ</b> ರದವರದನ್ನ	ದವಹದವಹದನ್ನ	ಪಪನನನ	ದೆದೆದೆದೆ ಇದೆದೆ ದೆದೆ	ಷೆ ಹೆ ಹ ಹ ಹ ಹ ಪ ಪ ಪ ಪ ಹ ಹ	ದೆ ಮೆಮೆ ಮೆ ನನೆ ನ ಮಹ ಮಹ	0.0.	0000
388 388 388 388 388	4722 6778 6778 6778 8898 8898 1004 1004	378 378 480 647 647	\$558 \$558 \$558 \$558 \$558 \$767 \$767	2528677 8888 8888 8888 8888 8888 8888 8888	570	57 50 57 50 57 50 57 50 57 50 57 50 50 50 50 50 50 50 50 50 50 50 50 50		866 866 866 866 866 866 866 866 866 866		976
F0804 00.	446000000000	000000	282 283 333 64 460 617 617	01-00-00-1-	00 00 4 00 44	4444466666	#=#=##################################	00000000000000		
	0.000 800 000 4 4 4 4 4 4 4 4 4 4 4 4 4 4	9000044	988888888440 88888888884440	460 617 560 560 691 470 746 691 691 691	88888	844446444 858888	6333300032 6333300035 6333300035 6333300035	85555555555555555555555555555555555555	134	568 648 648
SINV SINV SINV SINV	P>>>>>	× × × × ×	22222224	242242444	5555	5455H5555	22 25	> >		>>>>
CAIR CAIR CAIR CAIR	141H 141H 141H 141H 141H 141HV 161HV	44444	44444444	L4IHV WS41A L4IHV WS41A WS41A WS41A WS41A WS41A WS41A WS41A	L41HV 1.41HV 1.41HV 1.41HV 1.41HV	1241HV 1241HV 1241HV 1241HV 041HV 041HV 1241HV	HHCACACHHCAC	HACACHACA	N	1444 MI14 MIN
		mamama			サイフプラ	77770077	00000000000000000000000000000000000000	70000000000	200	<u> </u>
15100H 15000N 26450N 27452N	EESTE DE	00000	33000H 33000H 35000H 35000H 35000H 35000H 35000H	HE TOTAL						EHHH
25000 25000 264 264 274		256 310 310 310	3300 3300 3300 3300 3300 3300 3300 330	7731 274 274 510 63 745 745 745	222222	2222222	241000 241000 241000 241000 241000 241000	95555555	77	F201H1 F213H F313H F313H
BEBBE 55	24448888888	# # # # # # # # # # # # # # # # # # #	668686685	BEBERERS S	GERRA				pt pt	8888
EFFEE SS	000000000ddd	DOFFFF	EEEEEEE	SEFEFFEFF	O O O O O O O O O O O O O O O O O O O	000000000				
NOODOCH -	PP. xxxx44666	∞ ∞ ∞ ∞ ∞ 4·∞		02000-00	86	14-11-01-0 16-11-14-16-16-16	222-7-14 222-6-22 222-6-22 222-6-22 223-7-14 223-8-73 76-10-0 76-10-0 76-10-0	500000000000000000000000000000000000000	60	500
9-1-10-1-10-1-10-1-10-1	100000000000000000000000000000000000000	4-65-6	94000000	4644466466	00-00-00-00-00-00-00-00-00-00-00-00-00-	L0LLLL88	22222222222222222222222222222222222222	77777988	44	00 00 00 00
5 00 00 00 00 min -44 min	manage of the fatal at a 10	のころからのの	ale ale monto monto monto mo	115 115 115 115 115 00 00 115 115 115	RO FO FO FO FO	roso roso roso lo	たらららららし アア	101010000000000000000000000000000000000		24.00 000.00
机械技术员 田田	HIMMERKER	HHHHH	KKKKKKKK	我我我我我我我我	PEEEE	HKHHKKKK	我我我我我我我我我	REEREREER	EH	have been been been also also print pain
2000 BA	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	THE THE PAR	FEFF FFFF	**************************************	FFFFF	阿拉萨西西西西西	#############		2020	E Se Se Se
0000 ww						WWW.WW.WW.	@@@@@@@@@@@	ณผลผลผลผลผล	20.00	20000 20000
		00000	30000000000000000000000000000000000000	66725H 66720W 66720W 66720W 68702D 68702D 68720W 76733W		`		2		5002 TM 72000M 1337T
		R750 R750 54410 54410 56410 58200	54200E 56200E 58205E 65200E 65200E 65720E 65720E	672 672 672 673 673 673 673 673 673 673 673 673 673	000000	000000000	000000000000000000000000000000000000000	0000000000000	i-i-	337700
22 4444 22 4444	22222222222 22222222222	BEBBB	888888888	855555555	EEEEE	BEBEEFER	EEEEEEEEEE	EEEEEEEEE	66	5888
50000 88	00000000000000000000000000000000000000	DOGETE	FFFFFFFF	FEFFFFFFF	00000	000000000		000000000000	55	FFFF
						44000444000	*********	40004400004	000	0C 0C 0C 0C
33333 55555		T79 779 200V 270V	A380 A380 A380 A380 A530 A530 A530	5A530 5A530 7241 7241 7241 7341 7351	28BBBBBB 28BB 28BBBBBBBBBBBBBBBBBBBBBBB	28B 38B 38B 38B 44B 44B 39B 39B	THE STREET	24B 24BA 24BA 26B 36B 36B 10B 10B 4B		DF4 DF4 TF4
00000 """	THE PROPERTY AND AND ADDRESS OF THE PARTY AND	HHH-82	55555555	33333555A	20000	248844488	447199988444	40122222014	77	DOFF
MA COCOC	ELECT GOODO	CCVVV	22222222	PEL BELL BELL BELL BELL BELL BELL BELL B	00000	WCCCCCCC WCCCCCCCCCCCCCCCCCCCCCCCCCCCC			IWC	0000
XX 4444	*****			<b>まままままままま</b>	***	えんえんんんんんん	えんんんんんんんんん	**************************************		****
Maria maria Maria	2000000000000	x5+ x100x x100x x100x	2222 2	00	PP-P-P-			W 2442 7	-0.00	
SKOOK KX	3K 3K KKKKKK	SXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	MAXX CONTR	EXXXXXXXXXX	00000	XXXXXXXX	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	KOOKKKKOOK	10.0	्राप्ता कर कर क
ROMEN WITH	เลดเลดเลดเลดเลด	ondivide andivide	00000000000000000000000000000000000000	NX XXXXXXXX	SHORE	0000000000000	addeddiddddd	SERVICES	ALC: NO.	2000 2000 2000 2000 2000 2000 2000 200
000000 000000 000000000000000000000000	4777777	444444	PARTON PARTON	10104101010441010	PARTIE .	PARTY PARTY PARTY				lototot
999999 44440 90000 00000	655-7500 70-12800 70-12800 70-12800 880-12800 880-12800 130-12800 130-12800 130-12800 130-12800 130-12800 130-12800	828828	00000000000000000000000000000000000000	2222222 2222222 22222222 22222222 222222	9000000	0000000000	107-2400 130-2300 143-2300 143-2300 143-2800 112-2400 107-2400 107-2400	488888488884 00000000000000000000000000	200	2222
225	222222222222	10100040	880 1022 1022 1022 1022 1022 1022 1022 1	100 100 100 100 100 100 100 100 100 100			55000000000000000000000000000000000000	F000000000000	80.00	
44000 80	000000000000000000000000000000000000000		888888888	202220220	00 00 00 00 00	#5000000044	000000000000000000000000000000000000000	C000444500000	44	7686
2004 62	88888888888888888888888888888888888888	2577776	2244400408	2008488884444 200888884444 20088888988	195 195 195 195 195	022228888888	83888888888888888888888888888888888888	01000000000000000000000000000000000000	50	73300 73300 73300
DOWNER DO	POR POLOGO CO	8000000	80000 H + 80 + H	44404444000	STORES OF STORES	ちょうちゅうようち	######################################	生きゃのひちりまままま	ICIO	10101010
133 170 170 170	90000000000000000000000000000000000000	252 252 253 258 258 258	3358 3358 3462 517 517	6777 6777 6777 6777 6777 6777	22222	270 4534 303 303 4534 4534 318	4443000000444 44000000004444	400000000000	134	454
2000	ZAZZZZZZZZZ	10/2/2/2/2	44/2/2/2/2	120 1000	Tanadala	#844466644 #84466644	22 2 20 00 2 2 2 2 2 2 2 2 2 2 2 2 2 2	700000000000000000000000000000000000000	22	4444
NXXXIII AN	KXKXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	KXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	A A A A C C A C C	A X W X X X W X X X X X X X X X X X X X	XXXXX	KXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	EXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	NX K X X X X X X X X X X X X X X X X X X	XX 44	***
44440 800	00000000000000000000000000000000000000	2000000	111111111	4404440044 ****************************	888888	640044400	0000-100000 4444904444 444490668444	444 44444	1 10 to	444
11		000000	000000000	<<	00000	Eccoccocc		- <b>6</b> 000000	44	0000
NZ NZ SRI SRI RB	Wau Wau Wau Wau Wau Wau Wau Wau Wau Lye Wau	ANN T	HUKKERKE	ALL BELLEVIEW	00000	040044400	440000000444	40000000000		-
\$5555 55555 5		\$ \$ \$ \$ \$ \$ \$	20000000	DOWN WE WOOD HOLD	22222	72488844488	444 448 450 450 450 450 450 450 450 450 450 450	484 505 505 505 505 505 580 580 580 580 580	77	404
WWWW		Wa Wa Wa		CONTRACTOR	MACCO	JWC JWC JWC JWC JWC JWC JWC JWC JWC JWC	00000000000000000000000000000000000000		UM(	OOO O
4 444	7.50/20 7.50/20 7.50/20 7.50/20 8.25/20 9.00/20 10.50/22 10.50/22	000000	22222899	80444 4444	00000	00000000	0 0 000044	00000000000	88	0000
2000/2/	200000000000000000000000000000000000000	2000000	22222222222	20000000000000000000000000000000000000	22222	8888888888	9.75/20 10.50/20 9.75/20 10.50/20 10.50/20 10.50/22 10.50/22 10.50/22 10.50/22	666666666666666666666666666666666666666	71/12	9.00/20 10.50/20 10.50/20
13.00.7	000000000000000000000000000000000000000	F-88000	100.77725	10000001001	08080	0000000000	0.000	000-01-0-1	666	0.00
annag ww	6.500 200 200 200 200 200 200 200 200 200	\$\$0000	99999999	80888 8888	m0000	00000000	9.00/20D 9.00/20D 9.00/20D 9.00/20D 10.50/20D 9.00/20D 9.75/20D 9.75/20D 9.75/20D	9009590099		9.00/20D 9.75/20D 9.75/20D
00222	-20000000000000000000000000000000000000	2000000	2222222222	24222 04222 24222 04222	000000	888888888	88888888888	900000000000000000000000000000000000000	178	2020
0.555	38888888888	888888	222888822	20000000000000000000000000000000000000	88888	300003888	277500250000	200000000000000000000000000000000000000	25.5	722/
25 55 55 55 55 55 55 55 55 55 55 55 55 5	000000000000000000000000000000000000000	00505050	22222222	8388888888	20000	20000000000000000000000000000000000000	0000000000000		4 rcra	9,00
1000044 HG	2222 2222 2222 23225 2225 62225 62225 7600 7600 7600	00048000	9242772829	98200003842	442344	38851266556	889 100 100 100 100 100 100 100 100 100 10	226200000000000000000000000000000000000	158	9004 10485 11500
30-200 M			888888888	250000 250000 250000 250000 250000	:::::		* * * * * * * * * * * * * * * * * * * *		: 88	
000000 :			4777770000	200000000000000000000000000000000000000	1::::	:::::::::			. 88	111
32000 34000 34000 44000		111222		447444446666666						
2225 32000 2225 26000 228 34000 228 44000 113		157 125 175 183 183	62555555555555555555555555555555555555	222222222222222222222222222222222222222	82178	-60000==00	244480 5255555	82448 92448 92448 92448	88	0.000
2255 32000 2225 34000 2219 34000 2218 44000	25000000000000000000000000000000000000	25 157 33 175 01 155 01 157 41 183	22 22 20 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	023222225 023222225 002322225 002322225	22178	20020000000000000000000000000000000000	688 6880 880 880 880 880 880 880 880 880	280 44 88 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9 9	
195 225 32000 195 225 26000 189 219 36000 199 228 44000	25000000000000000000000000000000000000	25 157 33 175 01 155 01 157 41 183	22 22 20 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	27 162 205 224 205 224 205 224 205 224 210 231 211 231	36 178 36 214 36 214 36 214 36 214	87000000000000000000000000000000000000	8888448888	2224464888	000	150
195 225 32000 195 225 26000 189 219 36000 199 228 44000	25000000000000000000000000000000000000	565 125 155 595 101 125 945 133 175 945 101 157 1475 141 183	22 22 20 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8	023222225 023222225 002322225 002322225	1240 136 178 1350 136 214 1850 136 160 1425 136 214 1940 136 214	87000000000000000000000000000000000000	8800448866 88004448866	2224464888	000	165
6225 185 225 5200 4800 195 225 3500 6030 189 219 36000 7175 199 228 44000 495 113 113	2 (955 128 128 128 128 128 128 128 128 128 128	2 565 125 157 595 101 125 945 133 175 945 101 157 845 101 153	200 196 208 2050 196 208 3340 196 208 3825 197 226 3825 197 226 4430 196 226 4450 196 226 4450 196 226	6100 127 162 5450 205 224 6350 210 231 6150 203 224 5150 203 224 5150 203 2173 7200 210 231 6250 210 231 6260 144 09	1240 136 178 1350 136 214 1850 136 160 1425 136 214 1940 136 214	25040 25000	5200 168 5200 168 6300 180 6850 184 4175 134 5750 168 5350 168	6550 156 6650 180 6650 180 6650 180 7700 144 7700 180 6950 180 7250 180	8. 395 100 8. 415 100	165
62225 185 225 2000 62225 185 225 2000 6905 185 225 34000 6030 189 225 34000 7175 199 228 44000 495 113 113	2 (955 128 128 128 128 128 128 128 128 128 128	2 565 125 157 595 101 125 945 133 175 945 101 157 845 101 153	200 196 208 2050 196 208 3340 196 208 3825 197 226 3825 197 226 4430 196 226 4450 196 226 4450 196 226	6100 127 162 5450 205 224 6350 210 231 6150 203 224 5150 203 224 5150 203 2173 7200 210 231 6250 210 231 6260 144 09	1240 136 178 1350 136 214 1850 136 160 1425 136 214 1940 136 214	25040 25000	5200 168 5200 168 6300 180 6850 184 4175 134 5750 168 5350 168	6550 156 6650 180 6650 180 6650 180 7700 144 7700 180 6950 180 7250 180	8. 395 100 8. 415 100	5000 159 6000 165 6750 165
2525 1155 225 325000 -6 4480 185 225 32600 -6 4030 185 225 34600 -8 5030 189 228 44000 -10 7175 199 228 44000	200 100 235 100 245 100 100 245 100 100 245 100 100 100 100 100 100 100 100 100 10	74-2 565 125 157 5-2 595 101 125 945 133 175 945 101 157 945 101 157 845 141 183	2740 196 208 2950 197 208 2950 197 228 3550 197 228 3825 197 228 3820 196 228 3850 196 228 3850 196 228 3850 196 228	6100 127 162 5450 205 224 5450 205 224 5150 205 224 75 150 205 224 75 10 173 6750 210 231 6750 210 231 6750 210 231 6750 210 231 6750 210 231	2 1240 136 178 178 178 178 1850 136 1178 1850 136 214 1425 136 214 1425 136 214 1425 136 214	250 130 130 130 130 130 130 130 130 130 13	44 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	550 180 550 180 550 180 550 180 550 180 550 180 550 180 550 180 550 180 550 180	750 lbs. 415 100	5000 159 159 159 159 159 159 159 159 159 159
2525 1155 225 325000 -6 4480 185 225 32600 -6 4030 185 225 34600 -8 5030 189 228 44000 -10 7175 199 228 44000	200 100 235 100 245 100 100 245 100 100 245 100 100 100 100 100 100 100 100 100 10	74-2 565 125 157 5-2 595 101 125 945 133 175 945 101 157 945 101 157 845 141 183	2740 196 208 2950 197 208 2950 197 228 3550 197 228 3825 197 228 3820 196 228 3850 196 228 3850 196 228	6100 127 162 5450 205 224 5450 205 224 5150 205 224 75 150 205 224 75 10 173 6750 210 231 6750 210 231 6750 210 231 6750 210 231 6750 210 231	2 1240 136 178 178 178 178 1850 136 1178 1850 136 214 1425 136 214 1425 136 214 1425 136 214	250 130 130 130 130 130 130 130 130 130 13	44 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	550 180 550 180 550 180 550 180 550 180 550 180 550 180 550 180 550 180 550 180	V. y 750 lbs. 415 100	Drive 5000 159 14 15 6000 165 165 165 165 165 165 165 165 165 165
2525 1155 225 325000 -6 4480 185 225 32600 -6 4030 185 225 34600 -8 5030 189 228 44000 -10 7175 199 228 44000	200 100 235 100 245 100 100 245 100 100 245 100 100 100 100 100 100 100 100 100 10	74-2 565 125 157 5-2 595 101 125 945 133 175 945 101 157 945 101 157 845 141 183	2740 196 208 2950 197 208 2950 197 228 3550 197 228 3825 197 228 3820 196 228 3850 196 228 3850 196 228	6100 127 162 5450 205 224 5450 205 224 5150 205 224 75 150 205 224 75 10 173 6750 210 231 6750 210 231 6750 210 231 6750 210 231 6750 210 231	2 1240 136 178 178 178 178 1850 136 118 1850 136 214 1425 136 214 1425 136 214 1425 136 214	250 130 130 130 130 130 130 130 130 130 13	44 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	200 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	V. y 750 lbs. 415 100	DF   5000 158 AN 4 15 6000 165 NF 4 15 6750 165
	200 100 235 100 245 100 100 245 100 100 245 100 100 100 100 100 100 100 100 100 10	74-2 565 125 157 5-2 595 101 125 945 133 175 945 101 157 945 101 157 845 141 183	2740 196 208 2950 197 208 2950 197 228 3550 197 228 3825 197 228 3820 196 228 3850 196 228 3850 196 228	6100 127 162 5450 205 224 5450 205 224 5150 205 224 75 150 205 224 75 10 173 6750 210 231 6750 210 231 6750 210 231 6750 210 231 6750 210 231	2 1240 136 178 178 178 178 1850 136 118 1850 136 214 1425 136 214 1425 136 214 1425 136 214	250 130 130 130 130 130 130 130 130 130 13	44 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	200 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	V. y 750 lbs. 415 100	/heel-Drive
2525 1155 225 325000 -6 4480 185 225 32600 -6 4030 185 225 34600 -8 5030 189 228 44000 -10 7175 199 228 44000	200 100 235 100 245 100 100 245 100 100 245 100 100 100 100 100 100 100 100 100 10	74-2 565 125 157 5-2 595 101 125 945 133 175 945 101 157 945 101 157 845 141 183	2740 196 208 2950 197 208 2950 197 228 3550 197 228 3825 197 228 3820 196 228 3850 196 228 3850 196 228	6100 127 162 5450 205 224 5450 205 224 5150 205 224 75 150 205 224 75 10 173 6750 210 231 6750 210 231 6750 210 231 6750 210 231 6750 210 231	2 1240 136 178 178 178 178 1850 136 118 1850 136 214 1425 136 214 1425 136 214 1425 136 214	25040 25000	44.75.75.158.95.95.95.95.95.95.95.95.95.95.95.95.95.	200 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	V. y 750 lbs. 415 100	/heel-Drive
(b) F0107 67 6 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	(5) 461 134 555 128 128 165 165 165 165 165 165 165 165 165 165	udebaker Ace 1 1/4-2 565 125 157 (c.o.e.) Ace 1 1/4-2 595 101 125 (c.o.e.) Boss 2-8 945 101 157 (c.o.e.) Boss 2-8 1475 141 183 (c.o.e.) Chief 3-4 141 183	ard La Fr. 278114 27 2740 196 2208 2208 2208 2208 2208 2208 2208 220	(C.O.e.) L 835RW 57 835RW 57 65RH 74 65RH 74 65RH 75 65DD 75 65DD 75 100RW 10 7750 205 224 100RW 10 7750 210 231 756RW 51 756RW 51 7	2 1240 136 178 178 178 178 1850 136 118 1850 136 214 1425 136 214 1425 136 214 1425 136 214	250 130 130 130 130 130 130 130 130 130 13	44 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	550 180 550 180 550 180 550 180 550 180 550 180 550 180 550 180 550 180 550 180	77 Panel Delly 7750 lbs. 415 100	/heel-Drive
0	(5) 461 134 555 128 128 165 165 165 165 165 165 165 165 165 165	Studebaker. Ace 11%—2 565 125 157 (c.o.e.) Ace 11%—2 565 101 125 (c.o.e.) Boss 2–3 945 101 157 (c.o.e.) Boss 2–3 1475 101 157 (c.o.e.) Boss 2–3 1475 141 183	Ward La F. 25R 14 2 3 2740 195 208 208 208 208 208 208 208 208 208 208	(CO.E.) L. 9 35RW 574 5450 205 204 55RH 74 6450 205 204 55RH 74 6150 203 204 55RH 87 5150 203 204 500 15 150 121 100RW 10 75RW 10 75RW 10 75CW 7 10 600 164 Op	White. 703 1–2 1240 138 178 704 18–2 3, 1350 136 178 704 18–2 3, 1350 136 136 160 704 8 –10 1850 136 140 706 2, 4 1940 136 214	250 130 130 130 130 130 130 130 130 130 13	6.63 3 4 4 5 600 688 600 688 600 688 600 640 640 640 640 640 640 640 640 640	200 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	(9)77 Panel Delly 7700 lbs. 415 100	DF   5000 159 AN 4 15 6000 165 NF 4 15 6750 165

SF R 5.72-7.8 TIM 33000H L41HV 370 794 TX 91 10x34x4 L

78 17 (0) FEBU 198 (3) 4-4 (2016) 177 (207) (22000) 7175 (9.00/20D) 9.75/20 (Wau 6MK 6-44x4% 3816,1258 85-25007-254x12½ Y.Own UCH 5.Own TT 186 (1.1258 85-25007-254x12½ Y.Own TT 186 (1.1258 85-25007-254x12½ Y.Own TT 186 (1.1258 85-25007-254x12½ Y.Own TT 186 (1.1258 85-25

	1	Type	MANAGANA HEFFEF DODDDDDDDDDDDDDDDDDDDDDDDDDDDDDDDD
		Side Rail Dimension	THEFTER DODODODODOLODOLO FOUNDEFIELD FUNDER STATES OF THE
_	noise	C-A Dimer	111 000000 paragegegerioiiiiinaaa 50000 aasagagagari 5111111111111111111111111111111111111
	noiti	Material   Bood, busH	
KEG	E	Drum Area Drum	2000000 000000000000000000000000000000
RDAKES	(1)	Zuining Area	5333333 PF0464 63545 63545 88884488 4444886F00000000000 PF0FF0F0F0FFF 888845000
	,	Make Location Type Operat'n	WARE   WARREN   WAR
FRONT	VALE	Make and Model	CF1225  CF1225
<u> </u>	0	Gear Rati Range in	2886-2886 - 466781 - 100-100-100-100-100-100-100-100-100-
REAR AXLE		Dear and Drive & T	PARTICULAR ON CONTROL DE LA CO
RE		Make and	WWIS CRES   WWIS C
ISSION		Make an Model	©©©©©©©©©©©©©©©©©©©©©©©©©©©©©©©©©©©©©
PII PII		Оочегпо	ACACACACACACACACACACACACACACACACACACAC
	Main Bearings	Number Diamete and Length	Seed of the control o
s,	ake R.P.M.	Max. Br. H.P. at Given	20000000000000000000000000000000000000
E DETAILS	oijas	Comp. I	28.28222222222222222222222222222222222
ENGINE	p	Cylinde Bore an Stroke Displace	######################################
		10.0N	
		Makea	Bud Kas Bud Leg Bud Leg Bud Leg Bud Leg Bud Leg Bud Leg Bud Leg Bud Leg Bud Leg Bud Leg Was us be Was us was was was was was was was was was wa
ni rear	m 32	mixsM is ariT isinnuT	9.99.90 11.01.10.10.10.10.10.10.10.10.10.10.10.1
D-dua		Standa Front a	10.25/20/20/20/20/20/20/20/20/20/20/20/20/20/
(6)	.3W e	Chassis (Stripp	20000000000000000000000000000000000000
(anomón a	hed Vehicle Mith	Furnis Gross Weight	180   180
-	oase	Stands Wheel	8888889 1288888 2488888 2688999999 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	23	Rating Rating	2 3 44 0 0 00 44 0 11 00 4 0 000 00 00 00 00 00 00 00 00 00 0
•	MAKE AND MODEL	Coleman F.59 9	W D   H   H   H   H   H   H   H   H   H
3	Numbe		0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0

Six-Wheelers
(a) A'V'Car Wheely Driven

											61
	MM		000000	044044044	0000	DOPPER	MMH		111111111	+++++0000	000
**************************************	x3x 3	10000000000000000000000000000000000000	7x3 7x3 7x3 7x3 9x3 9x3 9x3 10x3 2xx 10x3 xxx 10x3 xxx	6x3x11 8x3x11 8x3x11 8x3x14 15x4xx14 15x4xx4 15x4xxx4 15x4xxx4	10x3x ## 7x3x ## 10x3x ## 7x3x ## 7x3x ##	######### \$	9x4 9x4 8x4 8x4	7 4 x 2 2 x 3 x 4 x 2 2 x x 3 x 2 2 x x 3 x 4 x 3 x 3		**************************************	7223 7223 7223 7223 7223 7223 7223 7223
4444129844 4444129844 60001	125	######################################	77 108 118 149 149	000444444	145 137 137	###### 000000	88834	0004400	2244424250000 24444424500000000000000000	2222222222	1888
222255777722222	88	222222222222	Prepare Country	KEEEEEEEE	<b>414</b> 74	686888	555	XX888888	XXXXXXXXX	XGGGGGGGG	555
0.00 0.00 0.00 0.00 0.00 0.00 0.00 0.0	8 1224 8 1224	382 608 a 6544 936 a 6544 936 a 6544 936 a 6578 a 6	422 606 a 529 930 a 636 1094 a 636 1094 a 636 1194 a	557 929 G 643 1093 G 643 1093 G 5504 1083 H 760 1083 H 760 1083 H 760 1083 H	504 G 864 G 828 1302 G 864 1302 G	575 800 p 575 800 p 700 1055 G 700 1175 G 780 1388 G 788 1388 G	720 868 a 806 1522 a 648 976 a	530 931 G 645 1094 G 645 1094 G 7406 914 G 588 1517 G 588 1517 G	462 648 c 590 816 c 590 816 c 590 816 c 550 816 c 775 1106 c	536 930 a 536 930 a 536 930 a 536 930 a 530 a 53	412 412 G 559 559 G 654 654 G
10041DV 10041DV 10041DV 10041DV 10041DV 10041DV 10041DV 10041DV 10041DV 10041DV			1.61HV 1.61HV 1.61HV 1.61HV 1.61HV	L61HV L61HV L61HV W84rIA W84rIA W84rIA W84rIA W84rIA	B6IMV O61A B6IMV O6IA	L61HV L61HV L61HV W86IA W86IA	L4rIH W86IA 41A	L61HV L61HV L61HV L61HV L41HV W841A W841A	B61H B61H B61HV B61HV B61HV B61HV B61HV	L61HV L61HV L61HV W861A W84rA W84rA W84rA W84rA W84rA	L6IHV L6IHV L6IHV
Tim 33000 Tim 33000 Tim 33000 Tim 35000 Tim 24450	Shu 1569 Shu 1569	Tim 30020H Tim 35000H Wis F211 Wis F211 Wis F211 Wis F311	Tim 30000H Tim 31000H Tim 33000H Tim 33000H Tim 33000H		fo. fo.	Cla F320 Tim 33000H Tim 27450H Tim 27450H Tim 27450W	Shu 715 Shu 1679 Wis F417CW	Tim 31020H Tim 31020H Shu 15582B Shu 15582B Wis F200 Wis F310	Own H108HT Own 251 ½H Own 251 ½H Own 251 ½H Own 350HT Own 350HT	TIM 31000H TIM 33000H TIM 33000H TIM 35000N TIM 36020N	Tim 33020H IIIm 33020H IIIm 33020H
HH755577777777777777777777777777777777	57	6-5-5-5-5-5-5-5-5-5-5-5-5-5-5-5-5-5-5-5		R 444-7 8 R 5.56-7 8 R 6.0-9 25 R 6.0-9 25 R 6.0-9 25 R 6.0-9 50 R 6.0-9 50	H H 5.78-9.35 H 5.17-14.9	H 6.5-7.4 H 6.5-7.4 R **7.16 R **8.6 R **8.6	7.33* 9.11 7.33* 11.7 **-9.15	6.17-7.40 6.2-7.4 6.14-7.80 6.14-9.25 5.90-7.66 7.66-8.44 7.33-9.11	62-7.40 62-7.40 62-7.40 14-8.10 16-12.28 14-7.2 69-11.89 43-7.16	A 6 .16-7.4 A 6 .16-7.4 A 6 .2-7.5 H 7 .37-8 .64 H 6 .0-7.6 H 6 .0-7.6 H 6 .0-7.6	R 5.14-6.6 R 6.17-7.4 R 5.47-7.8
######################################	00 00	XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	BEF BEF WF WF	BE WE	2F BF 2F BF	8888895 FFFFFF	2000 FEE	SYNTAGE	* FFFFFFFFF	NAME OF THE PARTY	7.7.7. 7.7.7.
50wn B 50wn B 50wn B 50wn C 50wn C	Tim 251SB Tim 251SB	20 S S S S S S S S S S S S S S S S S S S	4 TIMSBT75H 4 TI SBT251H 4 TI SBT251H 5 TI SWD251H 5 TI SWD251H	4 Tim SBT151 4 Tim SBT251 4 Tim Own 4 Tim Own 4 Tim Own 4 Tim Own 4 Tim Own 4 Tim Own 4 Tim Own	4 Wis 131TW 5 Own X 4 Wis 131TW 5 Own X	5 Own 1686 5 Own 1686 5 Own 2530 5 Own 2530 5 Eat 44000 7 Eat 44000	5 WIS SD310AH 4 WIS SD420BW 4 WIS 1910 W	Tim SBT151 Tim SW75 Tim SW251 Tim SW251 Wis SFD151 Wis SFD320W Wis SFD320W	Own Own Own 1540 Own 1540 Own Own	4 TIM SBT151 4 TIM SBT251 4 TIM SBT25SW 4 TIM SDT32OSW 4 TIM SDT32OSW 4 TIM SW32OSW 4 TIM SW32OSW 4 TIM SW32OSW 4 TIM SW32OSW 4 TIM SW32OSW 4 TIM SW42OSW	4 Tim SBT75 4 Tim SBT251 4 Tim SBT251
න්ත්ත්ත්ත් විසිත්ත්ත්ත්ත	00.00	•2229999999	PP88			0.00.00.00	-		44		
Y OWN DE Y OWN TE	Fu 5.	N Cla B116 N Fu 5a530 N Fu MHU	Y WG T9 Y WG T9 Y Fu MLU Y Fu MGU Y Fu 5A530 Y Fu 5A530	Y BL 234 Y BL 5341 Y BL 5341 Y BL 7341 Y BL 7341 N BL 7341 X BL 7341 X BL 7341	BL 734 Own U Y BL 7341 Y Own U	Y Fu 5-A-29 X Fu 5-A-38 Y Fu 5-A-38 Y Fu 5-A-53 X Fu 5-A-53 X BL 70-7	Y Fu 5A530 Y Spt 7341-703 Y Spi 7341	Y BL 2353 Y BL 2353 Y BL 5241 Y BL 5241 Y BL 5341 Y BL 5341 Y BL 7341	N Own H4 N Own F5 N Own F5 N Own F5 Y Own H5 Y Own H5 Y Own H5	NN BL 234 NN BL 3341 NN BL 3341 Y BL 5341 Y BL 7341 Y BL 7341 Y BL 7341 Y BL 7341	BL 2241
7-7-7-7-7-7-7-7-7-7-7-7-7-7-7-7-7-7-7-	7-25	7.7.7.7.7.7.7.7.7.7.7.7.7.7.7.7.7.7.7.	7-25-8110H 7-25-81134 7-25-81134 7-25-81134 7-381255	27-7-7-7-7-7-8-2-2-2-2-2-2-2-2-2-2-2-2-2	4-3 2x13 3 7-3x13 3 4-3 3 x11 3 7-3x13 3	7-258x1232 7-258x1233 7-3x1333 4-35x104 4-35x104	7-3x11 15 4-3x10 16 5-3 15 x 14	7-2 1/2 1/2 1/2 1/2 1/2 1/2 1/2 1/2 1/2 1/	44444777 9000000000000000000000000000000	22/5×10 22/5×10 23/11/2 23/11/2 23/11/2 23/2/11/3 23/2/11/2 23/2/11/2 23/2/11/2 23/2/11/2 23/2/11/2 23/2/11/2 23/2/11/2 23/2/11/2 23/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/2/	23,x134
\$5 - 23 00 \$5 - 23 00 \$7 - 2	95-2500 118-2600	80-2500 125-2500 125-2500 125-2500 125-2500 110-2200 110-2200 115-2500 115-	68-2800 73-2800 94-2800 106-2800 114-2200	90-3200 110-2800 125-2600 125-2600 125-2600 125-1800 125-1800	25-2000 25-2500 27-2000 25-2500	85-3200 110-2800 15-2600 25-2600 26-1850	111-2200 126-1850 77-850	73-2800 73-2800 94-2200 94-2200 94-2200 111-2000 148-2000 148-2000	778 877 7788 877 878 878 878 878 878 87	83-2500 03-250	70-3000 90-2700 118-2500 7
20000000000000000000000000000000000000		190 240 250 250 250 250 250 250 250 250 250 25	1764 234 265 350	2452555444 5255544400444001	330 440 324 324	432225 4404 4404 4044 4044 4044 4044 4044	340 410 476	5555888375	00000014444444444444444444444444444444	25.52.52.52.52.52.52.52.52.52.52.52.52.5	164 212 2701
25 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	104	2828 2838 2838 2846 2646 2646 2646 2646 2646 2646 264	2522823 2523 2523 25233 25233 25233 25233 25233 25233 25233 25233	25555 25555 25555 2555 2555 2555 2555	677 5.2 462 5.2 677 4.4 462 5.2	282 5388 5388 462 462 462 462 462 462 462 462 462 462	525 4.8 638 4.3 831 15.4	***	ದಾರಾರಾದ್ಯಾದ ಈದಾರಾರ	282 3361 443361 441 545 545 672 707 707 707 707 707 707 707 707 707	263 339 427 427 427 427
and had a day	75.70	6.44444444446007 XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	33 x x 4 x 4 x 4 x 4 x 4 x 4 x 4 x 4 x 4	84444460 84888888888 848888888888888888888888	5x5% 5x5% 5x5% 498x5%	233 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	4 15x5 15 4 34 x6 -5 34 x8	666444466 4478888888 XXXXXX 4444446 X443444	@@@@@@@@@ ############################	6-4-18-8-8-8-8-8-8-8-8-8-8-8-8-8-8-8-8-8-	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
Own 356 Own 358 Own 358 Own 404 Own 463 Own 501 Own 501 Own 453 Own 610 Own 453 Own 501 Own 453 Own 501	Con 32B Con 34B	Wau 6BK Wau 6SRL Wau 6SRL Wau 6SRL Wau 6MZ Wau 6SRL Wau 6SRK Wau 6SRK Wau 6SRK Wau 6RB Wau 6RB	Her JXB Her WXC Her WXC3 Her WXC3 Her WXC3	Wau 6-90 Wau 6-110 Wau 6-125 Wau 6-125 Wau 6-125 Wau 6BB Wau 6RB	Wau RB Wau 125 Wau RB Wau 125	Wau 6BK Wau 6-110 Wau 6-125 Wau 6-125 Wau 6-125	Bud L525 Bud GF6 Cat D8800	Her JNC Her JNC Her YNC Her RNC Her RNC Her RNC Her RNC Her HNB	Own FAB3 Own FAB3 Own FAB3 Own FAB3 Own FBB Own FBB3 Own FBB3	Her JXCM Her WXC2 Bud K393 Bud K393 Her YXC2 Her YXC2 Her RXB Her RXB Her RXB Her RXB Her RXB	
9 000/20 9 000/20 9 000/20 9 000/22 9 000/22 9 000/22 9 000/22 9 000/22 10 50/24	9.00/22	7.50/20 8.25/20 9.00/20 9.75/20 7.50/20 9.00/20 9.00/20 9.00/20 9.00/20 9.00/20 9.00/20 9.00/20	8.25/20 32x6 8.25/20 9.00/20 9.75/20	8.25/20 9.75/20 10.50/20 10.50/20 10.50/20 10.50/20 10.50/20	13.50/20	3.25/20 3.25/20 3.75/20 1.25/20	0.50/20 0.50/20 8.00/24\$	25/20 50/20 00/20 50/20 25/20 75/20	7.50/20 34x7 34x7 34x7 34x7 9.00/20 9.75/20 9.75/20	9.00/20 9.00/20 9.75/20 10.50/20 10.50/20 10.50/20 10.50/20 10.50/20	
9456 8.25/20D 9758 8.25/20D 9752 8.25/20D 12019 900/22D 12019 900/22D 14667 10.50/20D 12032 9.00/22D 12032 9.00/22D 12032 9.00/22D 13479 9.75/20D 12030 9.00/20D	8.25/20D 8.25/20D	7.50/20D 9.55/20D 9.75/20D 9.75/20D 9.75/20D 9.75/20D 9.75/20D 9.75/20D 9.75/20D 9.8	8.26/20D 8.25/20D 9.00/20D	.50/20D .00/20D .00/20D .75/20D .75/20D .75/20D .75/20D .75/20D	13.50/208 10.50/20D 13.50/20S 10.50/20D	34x7D 325/20D 300/20D 375/20D 375/20D	10.50/20D 10.50/20D 18.00/24S	32x6D 22x6D 22x6D 4x7D 4x7D .00/20D .25/20D .75/20D	20/20D 20/20D 20/20D 20/20D 20/20D 20/20D 20/20D	7350 32x6D 86000 8.25/2010 80000 9.00/2010 10500 9.00/2010 11000 9.00/2010 11000 9.75/2010 13000 9.75/2010 14000 9.75/2010	888
	::		000000000000000000000000000000000000000	23600 31400 42000 131400 42000 131400 58000 13140 131400 1	52400 17 40000 13 52400 17 40000 13	21000 25000 32000 10 38000 11 44000 13	50000 12 64500 15 50000 18	0.000000000	65000 990000 990000 99000 99000 99000 99000 99000 99000 99000 99000 99000 990000 99000 99000 99000 99000 99000 99000 99000 99000 99000 99000 990000 99000 99000 99000 99000 99000 99000 99000 99000 99000 9900000 990000	25500 256000 33000 33000 10 38000 10 40500 14 40500 13 40500 14 40 40 40 40 40 40 40 40 40 40 40 40 40	0000
7 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	350 19 950 19	2000 175 200 2000 175 200 2000 190 225 2000 190 225 2000 190 225 2000 190 225 2000 190 190 190 2000 190 200 200 200 200 200 200 200 200 200 2	895 156 199 350 165 204 350 165 204 360 165 204 895 165 234	150 195 220 850 200 220 850 200 220 950 195 220 900 195 220 000 195 230 200 232 232 202 232 232	255 200 Op 165 170 Op 225 200 Op 165 190 170	100 144 286 300 144 286 300 144 286 300 170 290 300 170 290	550 148 148 3324 148 148 800 131 131	775 168 186 000 168 186 000 188 224 550 188 224 550 188 224 150 188 224 160 200 0D	775 168 186 170 168 186 170 168 186 170 168 204 275 168 204 275 168 204 275 170 224 375 170 224 3	\$86 188 224 98 188 224 98 188 224 21 205 235 21 205 235 21 210 240 21 210 240 21 210 240	00 180 190 200 20 00 200 200 200 200 300 300 310 3
20111122211112221111222211112222111122221112222		20 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	M#IOWE X	000 000 000 000 000 000 000 000 000 00	10-15 10-15 10-15	28 6 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	20%	2000 4 mms	44 FFF	7888000000 0000000	Shange i
Six-Wheel  ""  "  "  "  "  "  "  "  "  "  "  "	Sro'kway180XSB	Corbit, 168B2, 2, 288B2, 2, 288B2, 2, 288B2, 2, 288B2, 4, 188B2, 4, 188B2, 4, 188B2, 4, 188B2, 2, 2, 2, 2, 2, 2, 2, 2, 2, 2, 2, 2, 2	<b>GGGGGGG</b>	(D) 846AL (D) 846AL (D) 846AL (D) 846AL (D) 846AL (D) 846AL (D) 846AL (D) 1046AL (D) 1046AL	4	21DA 41 n(12)25D 41 38D 41 40D 41	LD 41.954F1		2222424	En893BT 2F 1478BT 2F 1478BT 2F 1468BT 2F (D)243BDT 2F (D)243BDT 2F (D) D-346-C 4R 346-C 4R 346-C 4R 346-C 4R 346-C 4R	Der
തെയായായത്തതത്തത്തത്	99 E	01000000000000000000000000000000000000	1116 1118 120 120	1222 1224 1224 1224 1224 1224 1224 1224	332 1332 1333 1333	134 H 135 dr 136 138 139	140 141 +142	2444444463 11	155 155 155 155 155 155 155 155 155 155	165 165 165 165 167 168 168	
June, 1936		****		***				******	******	*** **	+170 +171 +172 + Den

- 07.65 20.00.00 20.00 20.00.00 20.00.00 20.00.00 20.00.00 20.00.00 20.00.00 20.00.00 20.00.00 20.00.00 20.00.0

| 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 | 1000 |

	1	Type	mmmmmm	Estatut at a conse	HALLOOOLALLA				00	0.0
ME			шиниши		for the tre loss	100	HHHH	4% 00	000000	SoSalala
FRAM	S	Side Rail Dimension	9x4xX 9x4xX 9x4xXX 9x4xXX 9x4xXX	9 12 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	00-00-00-00-00-00-00-00-00-00-00-00-00-	10x3 14x 14 10x3 14x 14 9 14x3 14x 3	14x3 ½x ½ 12x3 ½ x ½ 12x3 ½ x ½ 14x3 ½ x ½	88 1/8 x 3 1/2	5x6 5x6 7 ½x2 ½x 7 ½x3x ¼ 8x3x ¼ 8 ¼x3x ¾	4x2x4 4x2x2 5x2x2x2x2x2x2x2x2x2x2x2x2x2x2x2x2x2
	noist (.	C-A Dimer (Std. W. B	108 108 108 108	1066 1066 1066 1066 1066 1066 1066 1066	850852548554885 77777	951 95	284 284 261 274 274 274 274 274 274 274 274 274 274	109 78 109 34	12472	3249304738
	noi3s	Hand Loca	888888	XXXXXXXXX	22,61 22,61 22,61 75,61 75,7 75,7 75,7 75,7 75,7 75,7 75,7 75,	TXX	5555	55	888888	
S		Area Drum Isitetial		1518 a 1518 a 1518 a 1518 a 1626 a 1626 a 1626 a 1626 a	ವೆ ವೆ ಭಾರಾರಾಧ್ರಾಧಾಗಾಗಾಗಾಗಾಗಾಗಾಗಾಗಾಗಾಗಾಗಾಗಾಗಾಗಾಗಾಗಾಗಾಗಾ	दी दी दि ची ची ची	के के के क	d d	ಪಡೆದೆದೆದೆದೆ	ಡಿದೆ ಮಹಿದೆ ಮೆದೆ ಮ
BRAKES	ERVICE	Lining Area Mund	525 6333 9666 9666	974 15 974 15 974 15 974 15 1065 165 1065 165 1065 165 1065 165 1065 165	496 629 496 629 496 629 496 629 559 930 1070 1443 1114 1515 1114 1515 1114 1515 1114 1515 1114 1515 1114 1515	400 944 484 1024 792 1464	1012 1514 1012 1514 651 1088 902 1514	833 1286 833 1286	248 380 248 380 3865 578 407 663 500 772	214 308 214 308 242 344 3396 571 470 678 520 748
	SE	Make Location Type Operat'n	L41HV L41HV W841A W841A W841A W841A	061A 061A 061A 061A 061A 061A 061A	601H 601H 601H 601A 601A 601A 601A 601A 601A	L4rIHV L4rIHV W84rIA	Ws61A Ws61A L61HV Ws61A	Ws6IA	1441 1441 1411 1411 1411 1411 1411 141	BB4IM BB4IM BB4IM BB4IM BB4IM BB4IM BB4IM
AXLE		Make and Model	Im 35000H Im 35000H Im 35000tw Im 26050W Im 26050W	WE BX WE CJ WE CJ WE CJ WE BQ WE BQ WE BQ	OWD OWD OWD OWD OWD-WIS OWD-WIS OWD-WIS OWD-WIS OWD-WIS OWD-WIS OWD-WIS OWD-WIS OWD-WIS OWD-WIS OWD-WIS	Tim 33000N Fim 35000N Fim 27452N	Tim27452TW Tim27452TW Tim 35000H Tim26450TW	Own 6D Own 12D	m 30000H m 30000H m 31000H iu 15685B1 iu 15685B1 iu 15685B1	CCCs CCCs CCCs CCCs CCCs CCCs CCCs CCC
щ	0	Gear Ration In Inc.	6.4-7.4 6.75-7.4 7.25-9.25 7.25-9.25 7.6-9.5	6.54-8.92 6.54-10.0 6.54-10.0 7.43-10.0 7.43-10.0 6.52-10.3 6.52-10.3	6.6 6.6 6.6 6.6 6.6 7.831.0 7.831.0 7.831.0 7.831.0 8.141.0	5.72-7.4 5.72-7.8 10.0-11.7	5.64-10.2 T 5.0-9.25 T 5.4-9.25 T 5.64-10.2 T	6.80-10.20	FFFSSS	
AXLE		T 20 svird	FEFFFF	***********	我我我我我我我就我我	HHH	EE E	mm mm		HHHHHHHH
REAR	POAT	Gear and	888888	6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6 6	55555555555555555555555555555555555555	SF	420w WF 420w WF 251H SF 20tw WF	420W WF	00H SF 00H SF 00H SF 01, 25F 3H 22F	FFFFGGGGG
		Make and	5 T1 63703-97H 5 T1 65703-97H 5 T1m SW 310W 5 T1m SW 310W 5 T1m SW 410W 5 T1m SW 410W	5 Own BX 5 Own BX 4 Own BX 4 Own BX6 4 Own BX6 4 Own AK 4 Own AK 6	Tim Tim Tim SD151 Tim SD251 Tim SD353 Tim SD353 Tim SD253 Tim SD353 Tim SD353 Tim SD353 Tim SD353	Own	Tim SDT420w Tim SDT420w Tim SBT251H Tim SWT320tw	Timsw	Tim 53200H Tim 53200H Tim 54300H Wis 5000L Wis 72000L	Own Own Own Own Own Own
NO	· pu	Forward S	2,2,2,2,2,2	222 4 4 4 4 4 4 4	4444555445544	10104	00000	70-44	::::::	111111111
MISSION		Make and Model	BL 5351 BL 5351 BL 5351 BL 5351 BL 7351 BL 7351	Own BX Own BX Own BX Own BX Own AK Own AK Own AK	WG T9 WG T9 WG T9 WG T9 Fu 5A380 Fu 5A530 Fu 5A530 BL 7341 Fu 5A530 BL 7341 Fu 5A530 BL 7341	Own UC17 Own UC9 Own UC9	BL 7351 BL 7351 BL 5351 BL 5351	Own 4B Own 10B		
bra	Stand	Covernor	<b>正成成成成成</b>	<b>先太天太太太太太太</b> <b>聖皇皇皇</b>	**************************************	KKZ	*****	MM	111111	
	Main	Number, Diameter and Length	7-3x13% 7-3x13% 7-3x13% 7-3x13% 7-3x13% 7-3x13% 7-3x113%	7-3x12 7-3x12 7-3x12 7-3x12 7-3x12 7-3x10 6-3x2 7x10 6-3x2 7x10 6-3x2 7x10 6-3x2 7x10 6-3x2 7x10 6-3x2 7x10 6-3x2 7x10 6-3x2 7x10 7x10 7x10 7x10 7x10 7x10 7x10 7x10	22.55 22.55 22.55 22.55 25.55	25%x10 1/2 27%x12 1/3 2/2 x112 1/3	3 4 x 16 13 3 5 x 11 14 2 5 8 x 12 12 3 x 13 76	23x1534		
50	.M.q	Max. Brall H.P. at R. Given	98-2000 98-2000 98-2000 125-2600 127-2000 125-1800	118-2400 118-2400 118-2400 118-2400 125-2200 125-2200 125-2200 125-2200 125-2200 125-2200 125-2200 125-2200 125-2200 125-2200	80-3800 80-3800 80-3800 1106-2800 1106-2800 114-2200 118-2200 124-2200 176-1800 176-	84-3200 7- 110-2800 7- 125-2000 4-	125-1800 7- 145-2000 4- 85-2500 7- 125-2600 7-	30-2300 7		
DETAILS	-	Torque lb	82000 44200 42000 42000 42000	0 310 0 310	20000000000000000000000000000000000000	185 254 440	420 465 242 324	388		
	-	Displacen	4444641	ろろろろするする	IDIDIDIDIDMMMMM.	70.04 4.17	2 17.0 2 4.6 2 4.6	44	1111111	
NGINE	1000	Stroke	222224 222222 2222222 2222222	2555555 2555555 2555555 25555 25555 25555 25555 25555 25555 255 2555 2555 2555 255 255 255 255 255 255 255 255 255 255 255 255	22222222 22222222222222222222222222222	7 282 358 677	6772 6777 75 462	% 434 % 580 580	111111	
ш		No. of Cylinders, Bore and	99999999 24444734 28878776 XXXX8776	000000000 44444444 77777777777 888888888	œœœœœचचचचचचचचचचचचचचचचचचचचचचचचचचचचचचचचच	6-3%x4 6-4x4% 6-5x5%	6-478x6 6-5x534 6-438x43 6-498x53	6-4%x5		
		Make and	Wau 6SRL Wau 6SRL Wau 6SRL Wau 6AB Wau 6RB	OWN CF OWN CF OWN CF OWN BQ OWN BQ OWN BQ	Ford V8 Ford V8 Ford V8 Ford V8 Ford V8 Ford V8 Her RXC3 Her RXC4 Her HXD Her HXD Her DRXB Her DRXB Her DRXB Her DRXB	Wau 6BK Wau 6-110 Wau 6RB	Cu. Die. HA Wau RB Wau MK Wau 6-125	Own 7A Own 5A	GE Elec GE Elec GE Elec West Elec West Elec	Own Elec. Own Elec. Own Elec. Own Elec. Own Elec. Own Elec.
SIZES	ear	mumixaM Size Size Tire Sise Surnished	8.25/20 9.75/20 40x8 40x8 40x8	9 00/24 9.75/24 9 00/24 9 75/24 9 75/24 10.50/24 10.50/24	32x6 32x6 32x6 32x6 32x6 8.25/22 9.00/22 9.75/22 9.75/22 9.75/22	8.25/20 9.75/20 10.50/24	10.50/20 9.00/20 10.50/20 10.50/20	9.75/20	32x6 32x6 32x6 9.020 9.75/20 10.50/20	
TIRE	S-single r	Standard Front and Rear	8.25/20D 9.00/20D 9.75/20D 9.75/20D 9.75/20D 9.75/20D	8.25/22D 8.25/22D 8.25/22D 9.75/22D 9.75/22D 9.75/22D 9.75/22D 9.75/22D	\$5.50 (\$5.00 (\$5	8.25/20D 9.00/20D 40x8D	9.75/22D 9.75/22D 8.25/20D 9.75/20D	9.00/20D 40x8D	32x68 30x58 8.25/20D 9.75/20D 9.75/20D	32x68 32x68 32x65 32x6D 32x6D 34x7D 36x8D 36x8D 36x8D 10.50/20D
(e)	*3,	Chassis W (Stripped)	8500 9720 12000 12600 14000 14000	13050 14050 13100 13950 15150 15550 16900 17400	5821 5925 5466 5570 8690 11415 11415 118690 118690 118340 118340 118340 118340 118340 118340 118340 118340 118340	7325 9475 14685	14000 13700 9200 13000	14400	244 2855 2855 2850 2850 2850 2850 2850 2850	2350 25000 35000 4700 5300 7000 7000 7000
Keynot	oloi da	Gross Veh Weight wi				26000 32000 55000	44000 44000 28000 40000	::		
See	-1	Wheelbase Max. W. B	7 199 1 203 6 208 6 208 6 208	22322 22322 23325	::::000000000 ::::00000000000000000000	193 207 201	246 246 230 241	202	000000	20000000000
GENERAL (See Keynote)		Chassis Pr	4475 187 5100 187 6775 191 7950 196 8500 196 9750 196	7500 194 7650 194 7650 149 8100 147 8850 199 9350 197 (14) 191 (14) 191	2425 154 2475 179 1945 154 1995 179 11990 173 11000 192 11600 198 11600 198 11600 198 11600 198 11600 198 11600 198	4105 162 4880 177 10545 185	11 000 240 9350 240 4490 204 7100 203	(6a) 193 (6a) 198	1380 91 1500 91 2400 136 3200 146 3650 148 4200 160	1380 95 1450 116 1525 116 1800 116 2400 126 3400 145 3650 160 5650 160
OEN		Tonnage Znita A	5-6 6-7 7-8 8-10 10-12	55555555555	2411271112	7-8 8-10 12-18	115 24 20 115 125 125 125 125 125 125 125 125 125	12-14	1 8405 X	11 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
	MAKE	MODEL	LeMoon700 4R 800 4R 900 4R 11000 4R (1)1200D 4R	Mack. BX 2F BX 4R (e.bs.) CJ 4R (e.bs.) CJ 4R (e.bs.) AB 2F AK 2F AR 2F AR 2F	Mar-Herr. 186-556 15-574 186-5	Ster. (c) FBT130 2F 7 (b) FBT152 2C 2F 8 (c) HCS210 4R 1	Ward (D) 440TC 2R LaFr.440TR 2R L	Wht 6308W 320 W4R g	Brockway50-E-1 1.125-E-2 1.140-E-5 1.170-E-5 1.156-E-5 1.170-E-5 1.156-E-5 1.156-E	Walker 400-LA 1 405-LA 1 405-LA 1 425 2 425 2 430 440 440 440 440 440 440 640 660 660 66
	Ted	Line Num	<b>⊣</b> 000400	F-80013545	80000000000000000000000000000000000000	30	20000	378	8864444	4444440000

Editor's Note: The following White models were received too late for classification.

Sec. Fee.
SX N TF
N N
XXX
8 09
A TD 60 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8 8
44
560 875 632 1032
LAIHV 560 875 A O4IA 632 1032 A
9G 2F R 7.22-8.73 Own 24D LAIHV 560 87. 1C 2F R 6.67-9.50 Own 9D O4IA 632 103
R 7.22-8.73 R 6.67-9.50
ELE NOI
369 5 0 270 112 240 ) 7 2 4 18 4 Y Own 36B 5 Own 29C 460 5 0 320 123 240 ) 7 2 4 18 4 Y Own 36B 5 Own 21C
5B 5B
Own 3
33.33 MM
X XI
2121
2400
212
1028
0.0
369 5
310
4x51
99
396
ПМС
252
0.50/2
000
5/20
0 9.7
980
::
22
34.2
000 1
4.0
-732
20A 5 22A 8
7.7
hite
3

# Trucks or Delivery Units . . . Fleet Owners select CHEVROLET for Power and Economy



CHEVROLET TRUCKS
prove stamina and recordbreaking economy in amazing coast-to-coast run



#### Look at this great record

Location of TestLos Angeles to New York
Distance Traveled
Running Time 129 hours, 24 minutes
Average Speed27.14 miles per hour
Gasoline Used
Gasoline, miles per gallon
Oil Consumption2 quarts
Cost of Fuel
Cost of Oil
Fuel and Oil (cost per mile) \$.016
Average cost per ton mile\$.00328
Water Consumption 1 gallon
No mechanical failures

Entire test conducted under supervision of A. A. A. Contest Board—
Sanction No. 3300.



FOR ECONOMICAL TRANSPORTATION

THE CHARLES E. HIRES CO., nationally prominent manufacturers of famous Hires Root Beer, provides another example of how fleet users have recognized the outstanding economy and the great and dependable power of Chevrolet trucks and delivery units. Quoting from a statement made by this company:

"We selected the Chevrolet Sedan Delivery because it was economical in operating cost, provided ample room for carrying dealer display advertising and samples of our products, and afforded a desirable source of advertising.


"In addition to the Sedan Delivery cars (59), we have ten halfton Panel trucks and six 1½-ton trucks for delivery work a total of 75 Chevrolet units in our fleet.

"Our average cost ran a trifle in excess of 3.6c per mile, including depreciation on a 3½-year basis, licenses, insurance, storage, washing and the ordinary operating expenses."

Chevrolet trucks are the world's thriftiest high-powered trucks—as fleet owners the country over are discovering! So, if you haven't already done so, get the facts on how powerful, dependable and economical 1936 Chevrolet trucks can reduce your haulage and delivery costs. Your Chevrolet dealer will co-operate with a demonstration—on your jobs!

CHEVROLET MOTOR COMPANY, DETROIT, MICHIGAN

GENERAL MOTORS INSTALLMENT PLAN—MONTHLY PAYMENTS TO SUIT YOUR PURSE



#### CHEVROLET TRUCKS

#### Value of Vulcanizing Is In the Method

(CONTINUED FROM PAGE 19)

such a repair job. I placed a cavity in the rubber plug. This cavity allows the plug to flex readily with the casing without undue stress, thus eliminating the possibility of separation with its destructive effects. It proved so successful that I secured a patent on the process. As soon as I found out that it worked satisfactorily, I went back to my original theory of promptly repairing all cuts of any size.

Here is my explanation of this repair job in detail. By "plug" I mean the rubber filler which replaces that portion of the tire which of necessity must be removed in order to put in a section job. Referring to the drawing, Fig. 1 is a fragmentary view of a tire looking at the outside of the tread showing a spot (1) which is a repair with a cavity (2) in the center. Fig. 2 is a view in transverse section of a tire taken on the line "ab" Fig. 1 showing a repair (1) with a cavity (2) in it. Fig. 3 is a matrix or die used for moulding the cavity in the repair job.

To repair a tire, we cut out the injured portion of the tire removing the thread for a distance of about onequarter inch beyond the extremities of the injured portion of the carcass, or cords, making the resultant cavity in the tread and carcass as symmetrical as possible, the sides of the cavity having about a 60 deg. angle. The breaker strip is then removed as shown at (6). The broken ends of the cords of the carcass (4) are then trimmed as shown at (3) cutting as few cords as possible and going no deeper into the carcass (4) than is necessary to remove all discoloration of the cords caused by water and dirt. The cut surfaces are then thoroughly roughened with a power driven roughening tool of my own design and given two coats of cement. Fewer cords are cut by this method than by any other which is in itself a decided advantage.

You will note that the 60 deg. angle of the cavity in the tread (5) changes to perpendicular at (7) slightly below the tread design. The reason is, that if the 60 deg. angle cut was continued to the surface of the tread it would leave a thin edge on the replaced spot exposed to the road surface which is apt to scuff up and allow sand to work in loosening up the spot and causing it to peel out, also the step thus formed leaves more surface for the new rubber to adhere to and breaks up the traction

O build up the repair, the hole or cavity (3) in the carcass is first lined with cushion gum the thickness of the breaker strip as shown at (8). The cavity (1) is then filled with tread gum. A cavity (2) is cut out of the tread gum (1) and the matrix (9), which is preferably made of aluminum, is fitted into it. The cavity formed by the matrix (9) extends as far down through the tread and carcass as possible without exposing the cords. The matrix (9) is designed to leave a cavity which flexes readily and yet leaves as much tread surface as possible and also eject gravel. It may be of any design suitable to the job at hand. The inside of the carcass (4) is reinforced with either a factory made crosspatch or a built-in crosspatch of raw cords as shown at (1). The above method of repairing truck tires has proven exceptionally satisfactory for several years in actual service on our motor freight lines where accurate records of each tire have been

t

I

1

The repair may be cured in any approved manner, although, we secure the best results by curing the spot on a spot press before the reinforcement is built in, except cases where but a four or six-ply factory built crosspatch is sufficient, in which case the patch is



ADDRESS .....

CITY .....STATE .....

# WHITE MAKES BIGGEST SALES GAIN IN THE INDUSTRY!

White and Indiana first quarter registrations\* are up 76% over first quarter 1935 while industry gains only 23%

YES—White is going to town! First quarter registrations just released, show the big swing in 1936 is to the completely modernized White Line.

While the industry as a whole showed a 23% gain in registrations for the first quarter of 1936 over the same period last year, White and Indiana registrations gained 76%—more than three times the industry's average! In March, White and Indiana registrations were up 85% over March, 1935, while the industry gained only 26.5%. White's March business was greater than any single month since March, 1927.

Operators are investing their dollars in White equipment because today's complete White Line has everything truck buyers want and must have for profitable transportation. Modernized inside and out—streamlined—styled to the last minute by Count Alexis de Sakhnoffsky—the new Whites offer unusual advertising value. Beneath their streamlined exteriors, the new Whites have that superior White Quality, all through the truck, that makes for moneyearning miles.

Many of America's foremost names in transportation are replacing their entire fleets with Whites. The records show that where operators buy one or two new Whites, repeat orders quickly follow.

For power, performance, economy, long life, prestige building appearance—in every price and capacity range—you can find no truck that will compare with a White.

Investigate today's White values! Telephone the nearest White Branch or Dealer or write

THE WHITE MOTOR COMPANY, Cleveland

\*R. L. Polk & Co. Figures (Conn. not available)

# White TRUCKS—

June, 1936

inthe ones of , or / in ll as

ving aker (6). the own poscarnove

aces
th a
own
nent.
thod
tself

ngle nges elow that nued rould spot ch is work

rmed ibber

ction

le or lined f the The gum. tread ich is fitted the rough with-

matrix which much eject suitide of either uilt-in wn at airing

where been my ap-

onally

on a nent is a four atch is atch is

URNAL

(CONTINUED FROM PAGE 66) cured-in with the spot. We use an electrically heated sand bag for pressure and internal heat. This saves considerable time and expense. The reinforcement, of eight or more plies, is built in later and cured on an arm. We have to resort to the cavity mould for exceptionally large jobs.

SO successful was this treatment of tires that the management soon observed that many more new tires, in comparison, were put in service on the southern division than on the northern. A survey of the southern division was

made. In this inspection tour we found the tires in a deplorable condition. There were new tires mated with worn out ones, tires ready to blow out on the trucks and new ones on the trailers, many with large pieces of crushed rock imbedded in them and none up to proper inflation. The tire inspection trip became a monthly routine as a result and the original set-up was expanded.

My first concern was to enlist the aid of the drivers and service men and teach them to be tire minded. Most of them at first thought it was a lot of bother and foolishness, but they soon

learned that by keeping the tires properly inflated and mated up that fewer changes on the road were necessary.

The service men along the line begin to remove the tires as soon as they receive the repair list and send them in to the tire shop for repair. The vulcanizer, upon receiving the tires, removes the tubes and thoroughly inspects the carcass. He then makes the necessary repairs. Most of the curing. including four and six-ply reinforcements, are done on spot presses. Repairs requiring eight or more plies of reinforcement are cured either on an arm or in a cavity mould. For reinforcements of four and six-ply, we use semi-cured ready built up crosspatches. We do not as a rule bother with small cuts which extend only to the breaker unless tread separation has started. If a cut goes through the breaker and four or more plies of cords, we reinforce with a cross patch of a corresponding number of plies, unless the cut goes entirely through the tire. We limit the reinforcement to two less than the number in the carcass. That is, if the tire is 12-ply, we put but 10-ply in. That tends to lessen pounding. In exceptionally large repairs where the hole through the carcass is four or more inches in diameter, we sometimes add a six-ply boot.

F a tire is worn smooth and is not too badly cut up with crushed rock, we recap it and put it back in service on the drive wheels of the three-axle trucks. When the recap is worn to the original tread again, they are transferred to the trailers. As yet, we have had no recapped tires wear completely out, so cannot give any definite figures as to the average mileage, but I do know that a recap will add at least 25.-000 more miles to the tire. At first we recapped only the more perfect tires and as recapping proved successful, we became over confident and recapped several tires in which there were section jobs, but a half dozen of the section jobs blew out within 6000 miles. It had me guessing for a while, but I finally devised a way to put the cavity through the recap and our trouble was eliminated.

I believe any truck operator will find it well worth his time to make a scientific study of tire maintenance. A tire saved is equal to an extra pay load hauled.

#### **Chevrolet Has Record Sales**

Chevrolet car and truck sales in April totaled 134,431 units, setting a new all-time mark for any single month in the company's history. Sales for the year to May 1, totaling 406,620, a new all-time record for the first four months of a year.




#### A Signal So GOOD That It Meets Most Exacting State Laws

FIRST Signal To Be APPROVED
As Meeting Massachusetts'
New Requirements

#### DIETZ "PILOT" DIRECTION SIGNAL

### The Type of Signal That Eventually Will Be Required In Many States. The SAFEST Now.



DIETZ No. 350 "Pilot" Direction Signal employs 4
Detached Arrow Lites—located at the four corner
extremities of the vehicle—eliminating uncertainty for
both approaching and following traffic.

The Lites are operated through a Control Box, which attaches to the steering column just below the wheel—reached by the driver's fingers without removing hands from wheel. The Control Box contains Pilot Light, Switch, Fuse and Relay.

The Complete Assembly of the Control Box at the factory saves hours of usual installation time for a signal system—a big item in large fleets.

Sets with Two-Way Lites for front mounting or with Flanged Lite Units for Bus rear flush mounting are obtainable to meet requirements of the Massachusetts Law on certain types of trucks or buses.

Sets for Trailers have additional equipment consisting of a Hencol Heavy Duty Trailer Connection, with extra 56 ft. coil of wire.

Consult Your Dealer or Write for Details and Prices. Our General Catalog of Motor Lites and Accessories may also prove useful.


#### R. E. DIETZ COMPANY, NEW YORK PIONEER MAKERS OF VEHICLE LAMPS, FOUNDED 1840



HEAD LIGHTS • TAIL LIGHTS • MARKER LIGHTS • DITCH, FOG & SPOT LIGHTS • DIRECTION SIGNALS TRUCK FLARES • REAR VISION MIRRORS • FLOOD LIGHTS • CATAPHOTE REFLECTORS • FIRE EXTINGUISHERS



#### A FURTHER ECONOMY



We are pleased to advise that the volume developed by the demand for Purolator Oil Filters . . . especially engineered for Ford V-8s . . . has brought about a substantial saving in manufacturing cost. We are passing this on to the fleet owner, who can now buy *Genuine Purolators* with all the attachments, at a price of

\$3.25 each

If any doubt still exists in your mind concerning the efficiency and economy of Purolator protection, examine your oil after a thousand miles of driving . . . with and without a Purolator. Then you'll be convinced. Motor Improvements, Inc., Newark, New Jersey, makers of

#### **PUROLATOR**

The Oil Filter

LICENSED UNDER SWEETLAND PATENTS

June, 1936

in ein al-

he ig. celeof an in-

es. all ser If and cincerthe We

in. ex-

not
we
on
axle
the
ansnave
etely
ures
do
25.-

25.t we
tires
, we
oped
ction
tion
It
ut I
avity

find cientire load

April
v allcomMav

RNAL

ecord

#### **Keeping Up With Keeshin**

(CONTINUED FROM PAGE 25)

miles which it serves. Of its equipment there have been many estimates made, most of them gross exaggerations. Mr. Keeshin places the number at 1,500 units. But according to the tonnage being contracted for 500 more could readily be pressed into service.

The statement that these figures stand for today but will all be doubled inside of two years is not a writer's idle guess. It is given with authority from the front office.

Right now the parent Keeshin organization is thinking seriously about centralizing its terminal facilities. The construction of what is to be the world's largest motor freight terminal was recently announced. It will cost in excess of half a million dollars. Another terminal is now under construction in New York City, not as big as the Chicago unit but bigger than anything else servicing one line. Branch managers at half a dozen important points are reporting over-crowded conditions, so the next two years may expect to see a dozen new depots being constructed. You may have read details of the Chicago terminal, but for the benefit of those who have not, we will repeat the facts here. The Chicago terminal will be 1,000 ft, in length by 300 ft, in width. The platforms will be under cover. There will be two loading platforms, facing each other 110 ft. apart, with facilities for handling 268 trucks and trailers at one time. Today Keeshin trucks load from five depots in Chicago. One wing of the new building, 190 ft. by 116 ft. and three stories in height, will be given over to offices.

Other features will be a completely equipped shop for repairs and maintenance, and recreation and sleeping rooms and showers are to be provided for drivers. Apart from, but immediately adjacent to, the main building will be a gas station equipped with greasing pits. Gasoline and oil will be brought to this station in tank cars.

The site of the terminal will be at Roosevelt Road and South Clark street. extending south. This is almost in the heart of the freight yards of five of the leading trunk lines serving Chicago— the Baltimore and Ohio, Rock Island Lines, New York Central, Chicago Great Western, and Chicago and Alton.

PROXIMITY of the site to railroad freight activity, and the contacts which Keeshin has made with rail lines for coordinated rail-truck service and his contracts for pickup and delivery to the railroads, have combined to give rise to stories that certain railroad capital was being invesetd in the organization. These stories Mr. Keeshin spikes with emphatic denials.

"There is not one dollar of railroad money interested in this system," he says. "We organized the company to establish an organization to serve the shipping public through the flexibility of the motor truck. While we are primarily equipped for the short haul. we will continue to coordinate our facilities with the facilities of the railroads on long hauls."

On the matter of coordinated railtruck service, he told us that it will be used to a large extent when the run to the West Coast is started. Principal points will be Denver. Salt Lake City and important Texas centers where bulk will be broken. Also, it is now being planned to connect Los Angeles and San Francisco with the coordinated service, breaking bulk at the latter point.

Keeshin's contract with the Baltimore and Ohio, and that road's subsidiaries, which amounts to a joint agreement through their concurrence, has resulted in their publishing joint rates and tariffs. This contract involving a joint railroad service for less-than-carload freight, calls for the picking up of



#### "VEL-VAC POWER BRAKES are O. K. on every count"



- 1. CONTROLLED BRAKING 3. SERVICE
- 2. ECONOMY
- 4. DEPENDABILITY

Says-R. E. Halstead, President of the Detroit, Wyandotte and Trenton Transit Company, experienced operator of interurban buses.

And to continue-"There is nothing more severe than bus service with its numerous passenger pickups, its need to maintain schedules, its demands for smooth, easy "soft" stops. This kind of service requires power brakes that can take it-and stand the gaff . . . give consistent performance—and insure perfect braking action. That's why Vel-Vac

Power Brakes are standard equipment with us."

There is a Vel-Vac distributor in every leading city. Improved ex-clusive Vel-Vac features offer the last word in economical power brak-ing for fleet owners.

Vel-Vac ENGINEERED PACKAGED UNITS

VEL-VAC

Power Brakes

POSTICS

VACUUM POWER EQUIPMENT CO. 1646 W. Lafayette Blvd. Detroit, Michigan



package freight at the shipper's door by motor trucks and hauling it to local depots. There it is classified for destination points and loaded on trailers. Placed on flatcars, the trailers are then hauled by rail to destination cities where they are picked up by motor units for delivery to consignees.

efit

eat

nal

ler

at-

rt.

ks

ee-

in

ng.

elv

in-

ing

ded

edi.

ing

vith

will

ars.

at

eet.

the

the

and

ago

ton.

oad

rich

his

the

rise

ital

ion.

vith

he

to

the

lity

are

aul.

our

ail-

ail.

he

i to

ipal

City

iere

now

eles

ated

tter

ore

ries.

nent

lted

and

oint

load

of

RNAL

THE new service will be performed at rates now in effect for the all-highway haul and covers the entire B & O service, including New York City. In addition to this railroad service furnished by Keeshin and the B & O. the railroad will also have its own pick-up and delivery service in operation May 25.

During our talk he explained that he is working on other plans for other coordinated services. Some of these are still in the formative stages.

(Since this article was written hearings have been held before the I.C.C. on Keeshin's request for permission to acquire the stock of Seaboard Freight Lines, Inc., of Connecticut, and three affiliated companies.)

It was thought transcontinental service would be started in April, but laying the foundation was a bigger job than was at first anticipated, which explains the present delay. This foundation has been just about completed now, so it can be told definitely that the run will be started in a very short time.

Original plans for the run called for an estimated dozen terminals to be established between Kansas City and Los Angeles. It appears now that the number will be nearer 25 than 12. Another thing—original plans called for making Los Angeles the western terminus, while the plans today are to make San Francisco a regular port of call. And it would not be at all surprising if the end of the summer, or next year at the outside, found Keeshin trucks plying up and down the whole Pacific Coast.

That Mr. Keeshin leaves things largely to his department heads does not mean that he is out of touch with everything that goes on. Especially does he keep up contact with the dispatching department, which he considers as one of the biggest problems concerned with for-hire trucking operation. When we called at his office for this interview our's was the first appointment in his busy day. However, he already had learned that the trucks to Michigan were late in getting away during the night. He called the dispatcher's office, asked the reason, listened for a moment and said:

"But the railroads can load and dispatch on time, and we have to; see that it doesn't happen again."

The matter of urgent and emergency

calls, and small package pick-up and delivery are fast becoming a sore spot in trucking operation. With the Keeshin lines and their affiliates this is becoming more and more apparent. But Mr. Keeshin believes that he has discovered the cure. He plans shortly to experiment with motorcycles and sidecars for this work. He believes that they are the answer, and if they prove feasible they will be installed as regular equipment at all terminal points.

A T hearings conducted in Chicago the latter part of May by the Motor Car-

Ford (all models)

Chevrolet (4 cyl.)

rier Division of the I.C.C., financing details of the Keeshin enterprise were made public for the first time.

Through testimony given by Harry M. Wyatt, attorney and accountant, every detail concerning the deal last August between Mr. Keeshin and Lehman Brothers, New York investment house, was revealed. Mr. Wyatt represented both sides in that transaction, and from the witness stand through nearly all day Monday he told voluntarily under direct and cross-examination the facts as to the organization of

(TURN TO PAGE 76, PLEASE)



Name of my company is:

City & State .....

Company address is: St. & No.....

This coupon good only when submitted with a letterbead by a fleet owner who operates his own Repair Shop and must be mailed before midnight August 31. 1938

# NEW STEWARTS ice DELIVERY OVERHEAD

The NEW Low Price Stewart trucks mark a new era of transportation economy... Built with traditional Stewart quality and dependability, these 1936 models are *priced* to cut your original investment, they are *built* for minimum operating expense: to save on gas, oil and tire mileage; fewer repairs and delays.

Compare Stewarts with any low cost truck on the market for ease of handling . . . flexibility of performance . . . ruggedness of construction and quality. You can then understand Stewart dependability and low repair expense.

Get full information on the Stewart model and capacity best suited to your requirements—There is a Stewart for any hauling requirement—capacities ranging from ½ ton to 10 tons. Catalog on request.

STEWART MOTOR CORPORATION
BUFFALO, N. Y.



# LOWER Initial Cost LOWER Operating Cost




NEW 1½ TON



Here's heavy truck dependability with attractively low initial cost. Powerful 6 cylinder engine, rugged clutch, four speed transmission, full floating rear axle, 4 wheel hydraulic brakes, plus many other improved features.

# LOOK 'EM ALL OVER -- and you'll buy one of these Hein-Werner Hydraulic Jacks



### A COMPLETE LINE BUILT RIGHT-PRICED RIGHT

COMPARE any hydraulic jack on the market with a Hein-Werner—and you will quickly convince yourself why you should equip every truck and car in your fleet with a Hein-Werner Hydraulic Jack.

These jacks are exceptionally compact, sturdy, easy to operate and SAFE.... It is impossible for one of these to lower accidentally, because handle must be removed from pump to open release valve. All are tested at 1½ times their rated capacity, and are designed for hard, dependable service.

This line includes the "Bullet" Model, 1½ ton capacity at \$2.80 (West Coast \$3.10) . . . For light trucks, 3 ton models at \$7.95 (West Coast \$8.45) . . . 5 ton models \$9.95 (West Coast \$10.65) . . . For medium heavy trucks, motor coaches and shop use—7 ton models \$13.45 (West Coast \$14.50) . . . For heavy trucks, buses and shop use—12 ton models \$19.95 (West Coast \$21.00) . . . 20 ton models \$30.00 (West Coast \$31.00)—and for modern passenger cars, our new BUMPER-LIFT Model at new low price of \$4.95 (West Coast \$5.65) . . . All prices are net to dealer or fleet owner.

#### New 20 Ton Model . . . \$30.00 Net to Dealer



In response to popular demand, and in keeping with our policy of producing a quality product to sell at a price that leaves no room for argument—we recently introduced our new 20 Ton Hydraulic Jack. It is an exceptional value, and all fleet operators are cordially urged to ask for details on this model, and on all others in this complete line.

HEIN-WERNER MOTOR PARTS CORP.
Waukesha, Wisconsin

HEIN-WERNER
hydraulic\_JACKS

(CONTINUED FROM PAGE 73)

Keeshin Transcontinental after the stock in Keeshin Motor Express had been surrendered. He gave testimony also on the details of the "voting trust" to which both Mr. Keeshin and Lehman Brothers surrendered 1,500 shares of stock each with the further provision that when stock franchises are exercised in the future the shares in the "voting trust" are to be increased to always give an equilibrium of holdings. Mr. Wyatt testified that John Hertz, former Chicago taxicab magnate has no stock personally in the company, "not one single share," he said. On this point attorneys for railroads subjected him to strenuous cross-examination, declaring that they had heard as to John Hertz' extensive holdings. It was put into the records that several of the trust funds which Mr, Hertz, who is a partner in Lehman Brothers, has set aside for members of his family, have purchased approximately \$150,000 worth of stock in the Keeshin Transcontinental Co. from the voting trust at \$100 par value. but that he personally holds more.

Mr. Wyatt related also the details surrounding Mr. Keeshin's surrender of his stock in Keeshin Motor Express and of the blocks of stock which he received in their stead in Keeshin Transcontinental.

Facts as to other companies and lines which are affiliated with the gigantic Keeshin organization were told by C. R. Olson, vice-president in charge of operations of the entire system. Mr. Olson gave one of the most straightforward pieces of testimony that has ever been given before an I.C.C. hearing on trucking affairs. Off the records his testimony was commented on by various persons who had filled the hearing room. He reviewed the acquisitions of various small trucking concerns from time to time and of their mergers and final abolishment as separate identities after being combined with other companies and lines which go to make up the general organization. Without revealing any of Mr. Keeshin's plans for future expansions he let it be made a part of the records that Mr. Keeshin has always been an advocate of federal regulation of the trucking industry, and explained that a number of things which it expected will be done in the near future are being held in abeyance until such time as the motor carrier division can begin to function as it hopes.

Shippers from Iowa who are being served by the national concern testified that the service which they have been getting since February 9, the date that the contract to purchase between the national and Keeshin companies was made subject to I.C.C. approval, has been materially improved.

A Better Valve
Steel for the
Cars of Today
and Tomorrow

## RICH

Combines Two Wonderful

New Materials

to Produce a

The Hardest
Most Heat Resisting
Material
Ever Used in
Motor Valves

# SILCROME

Today's higher motor speeds, higher compressions, and more powerful fuels have set up VALVE PROBLEMS. HERE'S THE ANSWER TO THESE PROBLEMS - SILCROME-X Silcrome-X is the last word in valve steels. It is the answer to engineers' demands for a steel that defies any punishment the engines of today can give it. Silcrome-X sets a new high standard of valve efficiency and long life.

d

d

e

t-

18

ls

y

ns

m nd

m-

ıp

re-

or

ral nd ngs the

dies.

stiave late

een

val,

NAL

STEEL COMPANY

# SUPERVALVE

Wilcox-Rich announces a new Rich Valve made of Silcrome-X, the steel which sets new and higher standards of resistance to red heat and corrosion —and faced with Stellite, the hardest, toughest, most heat-resisting material ever used in valves!

Result: a DOUBLE DUTY VALVE. It offers undreamed-of performance and economy! Designed for the highest powered engines of today, it brings

amazing efficiency and
economy to owners of
motor trucks! Higher in
price, yes. Yet it costs you
far less in the long run!

RICH Double Duty

VALVES

with Stellite Face

Haynes STELLITE

Stellite is the super material for valve facing. Stellite remains practically as hard when intensely hot as when cold. Stellite shows amazing resistance to wear pitting, etching, burning. It offers complete burn-out proof protection. Stellite is completely unaffected by detrimental deposits. It insures 100% valve seat efficiency. It represents the "top" in economy and long life.

HAYNES STELLITE COMPANY

#### Motor Freight Classifications Get the 3rd Degree

(CONTINUED FROM PAGE 23)

part from the words, form, and general scheme of the present railroad classifi-

While I did not expect a different kind of classification merely for the sake of being different, I did look for a truck classification that would be molded to the distinctive needs of the trucking industry, and one that would evoke a trucking rate structure independent of and for the most part un-

There's a GATKE Brake Lin-

ing that affords extra per-

formance on every service

requirement of cars, trucks

or buses. Write for catalog.

HI-POWER

**BRAKE BLOCKS** are

sold on a GUARANTEED

MILEAGE

BASIS

related to railroad rates. Incidentally, this writer's viewpoint may be made a bit clearer by stating that he is strongly of the opinion that the trucker does not have to fix his rates with an eye single to railroad competition. The railroads are the ones on the run. The truck today finds its position in the transportation scheme assured. Thus, I think that trucking rates can be based almost altogether on the cost of operation plus a fair return on the investment, without doing injury to the volume and character of highway traffic. Moreover, in the final analysis truck rates will have to seek this level, whether it be higher or lower than the present one. There is an inexorable economic law that eventually will compel this.

T is natural to expect that one holding these views would object to the NMFC. It is entirely too much like the railroad classification, even to word-for-word descriptions that bear every indication of being at least inspired by the rail publication. However, the real jolt came with the discovery that there are two publications. one of 205 pages for Volume ratings and the other of 178 pages for Less Truck Load shipments. Even though two separate classifications may have seemed necessary because some truckers are interested only in L.T.L. traffic and others only in T.L. business, while still others could not agree to the volume ratings provided, nevertheless different measures could be taken to avoid the issuance of two classifications. For example, one publication could have carried both the T.L. and L.T.L. ratings, with all carriers participating. Then any carrier who desired to limit the extent of participation or avoid being subject to any certain rules, regulations or ratings could make that fact clear in a tariff of exceptions or in the tariff carrying the rates themselves. If one pleads that tariffs of exceptions are confusing it must be remembered that they are inevitable when so many carriers subscribe to one basic publication, such as a classification.

THE objections to two separate publications for L.T.L. and T.L. are obvious. The sheer bulk alone is enough to annoy traffic men already trying to keep their heads above the flood of railroad tariffs. But more important is the fact that traffic men have become so accustomed to the single volume railroad classification, containing both C.L. and L.C.L. ratings, that it is difficult for them to accept the National Motor Classification with any show of enthusiasm. Shippers are not interested in discovering reasons for the two volumes. They simply know that the rail carriers have the entire story in one volume, so why not the trucks? Moreover, shippers have observed with pleasure that the railroad classification during the past few years has been steadily shrinking. About eighty-five pages have been lopped off during the past few years. It seems strange to find the tradition-defying trucking industry lapse momentarily and outdo the railroads in antique tariff ideas.

Another question that occurs to the writer is whether it is really necessary for the National Motor Classification to have three rate territories, East, South and West. Not long ago Coordinator of Transportation Eastman published



five-mile grades.

Year after year Gatke Brake Blocks have met these exacting service requirements and remained standard equipment on Utility Trailers.

Gatke HI-POWER Brake Blocks on your toughest power jobs will open your eyes to greater safety and lower operating cost for the entire fleet.

#### MAIL THIS COUPON

GATKE CORPORATION 228-A N. La Salle St., Chicago

Please send complete information about Gatke HI-POWER Brake Blocks and the Guaranteed Mileage Basis on which they are sold.

Name	 	 	-	-	-	-	-	-	-	-	-	-	-	-	-		-		-	-	-	4	
Address																							_

# We try to Diagram where the BONUS·LOAD comes from



In this photograph of a truck operated under contract by Brown-Elliott, Inc., you will notice that about 60% of the truck body is hidden behind the leaf on which these words appear.

That is the part of the body which would have constituted unnecessary ballast if it had been built of ordinary materials.

Actually, this body is built of Alcoa Aluminum. It weighs only 1700 pounds. A similar body of heavy materials would have weighed 4100 pounds.

Obviously, 2400 pounds, or 58.5%, of that old type of body would have been just plain ballast.

Alcoa Aluminum throws off the ballast and lets you haul income-producing, profitable Bonus-Load, instead.

No operator will long tolerate the wasteful operation of heavy bodies, if he will ask himself this simple question: Which shall it be, ballast or Bonus-Load?

Hundreds of operators have decided that question for once and for all. They specify Alcoa Aluminum. That's simple enough, but if you feel you would like further guidance, address ALUMINUM COMPANY OF AMERICA, 2139 Gulf Building, Pittsburgh, Pa.

This body was built for Brown-Elliott, Inc., by Finn Auto Body Shop, Cincinnati. Aleoa Aluminum makes possible a Bonus-Load of 2400 lbs., nearly 1½ times the whole weight of the body.



ALCOA · ALUMINUM

d

If re at

n.

ıb-

b-

gh

to

of

is

50

L.

ult

ted

volrail

one

re-

ea-

ion

five the

to

do

the ary to

th

(CONTINUED FROM PAGE 78) studies indicating that in so far as railroads were concerned there was not enough difference from region to region to justify the three rate territories in the rail classification. He urged the railroads to abandon the tri-territorial scheme in favor of one classification for the entire nation. Others equally well informed are of the same mind. I know of no reason why the National Motor Classification could not have done the same thing, thereby pleasing shippers, scoring on the railroads, and

serving the ends of simplicity and common sense. Again one has the feeling that the three rate territories and the classification variations from region to region were primarily designed to parallel the rail classification. Certainly they are not the product of independent study of the needs and limitations of highway vehicles.

It is possible, of course, that since I am on the shippers' side of the fence I am overlooking valid reasons for some of the things criticized. For example, I fail to see why the National Motor

Classification has volume ratings with minimum weights often much higher than can be loaded on a single truck. Granted this has been done so that trucks can match their ratings with the railroads, and that provisions had to be made for certain large movements of freight by truck. In the first place, such large movements of freight via truck are so relatively infrequent that adequate provision could have been made for them in a tariff of exceptions or special commodity tariffs. Moreover. if truckers are going to publish rates that will match the railroads rate for rate, minimum weight for minimum weight (I'm speaking now of carload or T.L. traffic), they will have to publish commodity tariffs and exceptions like the railroads. And the railroads have about 500,000 current tariffs and supplements containing 21/2 million pages. On the other hand, if the trucks offer no inducements for much of this rail carload business other than the ratings and minimum weights provided in the volume classification they are doomed to disappointment. They will have to bid much lower than that. For instance, trucks will seldom be able to meet railroad rates on long hauls of steel pipe, cement, brick, structural steel, grain and large steel tanks.

The volume classification carries low ratings on articles that previous to April 1 the great majority of truck operators would not handle except at relatively high rates. Truck operators would be well advised to lose no time in drawing up a list of excepted or prohibited articles, based on what they are reprinted to handle at published rates.

equipped to handle at published rates. No doubt many readers will argue that since numerous volume ratings are allegedly futile they are at least harmless. But this is a short-sighted attitude. In the first place, they are a step in the wrong direction. They are clearly based on the wholly fallacious proposition that trucks can meet the railroads rate for rate, weight for weight, on all commodities, between all points. This is a false and dangerous idea to implant in shippers. It is also paving the highway to impoverishment for an industry now enjoying sound economic health. Moreover, I am certain many of the truck carriers participating in the volume classification have not the least idea of the rates to which they have committed themselves. Surely it will not help them nor the trucking industry in general when they are called upon to live up to the volume ratings. They will be obliged to renege or do the work at substantial losses. If they renege the shipper is likely to make a legal issue of it. Besides, what are they going to do when offered volume traffic of low-rated articles destined to points not located on rail-



PROVED economy, UNIFORM, year around satisfaction, and MAIN-

TENANCE-FREE operation you get with LATHAN-BESLER. Nation-

wide sales and service. Be sure to see the new 1936 LATHAN-BESLER

Catalogue before you buy ANY power brake. Write for your free copy

LATHAN CO., Inc. SAN FRANCISCO—Polk & Pine Sts. (Since 1911)

TODAY.

# OLD MOTORS hum LIKE NEW after a SIOUX Valve Job

You can give your customers NEW CAR performance . . . at a price that makes them happy . . . and still have a bigger profit for yourself . . . when you use SIOUX equipment. Modernize your shop with these two accurate and fast SIOUX Tools.

### SIOUX DUAL ACTION VALVE SEAT GRINDER


grinds any valve seat . . . even the hardest valve seats now in use . . . to perfect mirror finish . . . in almost no time at all. Its speed and accuracy are almost unbelievable . . . saves 75% of the time required by other methods. The Sioux High-Speed Driver operates at 12,000 R.P.M. load speed, transmitting its speed directly to the Grinding Wheel Holder, cutting hardest metal instantly and accurately. Set-up is the same as for reaming, using SIOUX tapered pilots to assure absolutely correct alignment. Priced within reach of every shop.

### SIOUX VALVE FACE GRINDING MACHINE

with the exclusive Sioux Roller Chucking System
which makes it so
easy and fast to reface
valves with precision
accuracy. In many
shops these machines
have been giving
faithful service for
years. Made in
four models...
one to fit
your needs.

#### No. OXU and OOU

SICUN Valve Fees Grinding Machiness for valves of 20°, 85°, 80°, 60° and 75°. No. 620 chucking capacity 1/4 to 1/4 inch, No. 650 1/4 to 1/4 inch diameter, inclusive,



#### No. 664 and 654

for valves of any angle, lackeding Boyle valves and 90° Mack valves. No. 662 checking capacity 1/4 to 13/4 inch, inclusive. No. 682 checking capacity 1/4 in.

Your Jobber STANDARD THE

LBERTSON & CO, INC.



Sells Them
WORLD OVER

SIOUX CITY, IOWA,

U. S. A

ith er ek.

be of ce,

via nat en ons er, tes

for

ım ad

ıb-

ns

ids ind

ion the

ich

an ro-

iev

iat.

ble

of

10

uck

at tors

proare

ites.

are

rm-

atti-

re a

ious

the

for

n all

rous also

ment

ound

cer-

rticihave hich urely

king

are lume enege

ly to what

desrail-

IRNAL

(CONTINUED FROM PAGE 80)

roads? Looks as if they will have to haul it, loss or no loss.

It is hardly possible to set forth these objections briefly since in all fairness they must be qualified and elaborated upon. Otherwise they are meaningless. Dissenting truckers are bound to insist that in many instances they can operate at a profit under the volume ratings. I don't doubt that. But why in such cases must a shipper have two truckloads at one time, from one point to one consignee, in order to obtain a rate comparable to the railroad carload rate? If trucks can meet the rail car-

	% Moving	Railroad Class.		Nati. Mtr. Class.		
<b>Commodity Group</b>	(1933)	Min. Wt.	Class	Min. Wt.	Class	Average Truck Load*
Automotive parts	28.5	30,000	5	30.000	5	11.000
Canned goods	28.0	36,000	5	36,000	5	15,000
Paints, varnishes, gum	27.5	36,000	5	36,000	5	9,000
Beverages and liquor	27.0	30,000	4	36,000	5	15.000
Groceries	27.0	36,000	6	30,000	5	
Rubber, rubber articles	20.5	30,000	ă.	30,000	4	12,000
Barrels, cooper material		36,000	6	36,000	4	16,000
Dry goods, clothing		Usually Fire	at Class		. 01-0	8,000
Dry goods, crotining	10.0			Usually Fire		*****
Boots and above	10.0	Any Quanti		Any Quanti	ty	16,000
Boots and shoes	18.0	24,000	2	24,000	2	19,000
Vegetable oil, meal and cake	17.0	30,000	5	30,000	5	19,000
Furniture and furnishings	14.0	20,000	3	12,000	2	13,000
Cotton, cotton linters		20,000	4	20,000	4	14,000
Paper, paper products	13.5	36,000	5	30,000	5	18.000
Textiles	12.0	Usually Fire	st Class.	Usually Fire	Usually First Class.	
		Any Quantity		Any Quantity		15,000
Leather, leather goods	11.0	30,000	4	30,000	4	19.000
Books and periodicals	10.5	36,000	3	30,000	A	14.000
Plumbing and heating supplies.	7.0	30,000	4	30,000	A	15,000
Timber		36,000	8 .	36,000	- 7	11.000
Chemicals	4.5	30,000	4	30,000	4	
Petroleum	2.5	26,000	6	26,000	4	14,000
Tobacco, tobacco products	5.0	30,000	3	30,000	0	17,000
Machinery		24,000	5		4	13,000
Watermery	4.0	24,000	9	24,000	5	11,000

\* Reported by 40,000 shippers in 1933.



#### **CONVERSION UNIT**

Double payloads and earning ability! Cut operating costs and equipment investment! Simplified design, rugged construction, proper proportion, and painstaking engineering make Timken's 6-Wheel Conversion Unit an integral strengthening chassis member that fits your trucks' power plants.

18 years' experience as pioneers of the 6-wheel idea, and thousands of successful, profitable installations, prove conclusively that Timken's quality methods are the best possible assurance of lowest cost operation, of greatest satisfaction and profit.

An idea worth considering.. Timken 6-Wheel Unit and the Timken

2-Speed Axle, double reduction, for light duty trucks.

6-Wheel Headquarters — the World's Largest Axle Builder
THE TIMKEN-DETROIT AXLE COMPANY, DETROIT, MICHIGAN
WISCONSIN AXLE DIVISION, OSHKOSH, WISCONSIN

The above table shows the relation of truck classification to railroad classification

load rate when handling two or three truckloads why can't they do it with one truckload? If they can do it with one truckload why chance losing the business to the rails by insisting, through the volume classification, that the shipper move two or three truckloads at one time? Shippers are puzzling over these questions.

THE following table will indicate the general grounds upon which this objection to the volume classification is based. It is worth noting that the reports of 40,000 shippers to Coordinator Eastman reveal the average truckload for each of the commodity groups named was less than 20,000 lb. and usually much less. On the other hand, the railroad minimum weights are in every case much higher than the average truckload. Clearly, the rail minima are based on a realistic appreciation of the box car's capacity for the commodity in question. But the volume minima in the National Motor Classification bear no relationship to the capacity of trucks. They are related only to the minima established by the railroads for box cars. The same is true of the class ratings shown in the table. Incidentally, these ratings and minima are averages for each commodity group.

thre

truc

of t

or y

One final remark about the volume classification. It is possible this publication may result for a while in trucks losing business they could handle at a savings. This might result when a shipper with 20,000 lb. of freight turns to the volume classification only to discover a minimum weight of 36,000, the same as via railroad. Of course, this shipper can frequently find in the trucker's exceptions to the classification a table providing for progressively lower rates on lots of freight from 5,000 lb. up to 20,000 lb. However, many of the small shippers will have to be edu-

COMMERCIAL CAR JOURNAL







TANKS: Streamlined, semi-streamlined or conventional designs for gasoline, fuel oil, milk, etc.



BOTTLER'S BODIES: All steel, deck type.

Maximum strength and capacity, minimum

weight. All types and sizes.

### .. means GAR WOOD

Experienced trucking men in every field depend on Gar Wood equipment. Twenty-three years of constant development—twenty-three years of close cooperation with truck manufacturers and users, have made Gar Wood equipment so useful, so dependable and so efficient that today Gar Wood Industries are the largest builders of truck equipment in the world. We can help you make your present truck better or your next truck the best in its field.

There is a Wood Branch or Distributor nearby who can serve you. Let these hauling specialists give you recommendations on your next equipment.



of Issi-

with with the ting, that uckare

this ation the ordi-

uck.

oups

and

and.

e in

aver-

min-

ecia-

vollotor

p to

lated y the

ne is

and

mod-

lume

pub-

en a turns o dis-0, the

sifica-

5,000 iny of e edu-

#### GAR WOOD INDUSTRIES, Inc. Detroit, Michigan

WINCHES: All types for all classes of boisting and bauling work. Also power take-offs and drives.

COAL AND COKE BODIES: Fuel dealers will find a wide range of steel and aluminum bodies, boists and bi-lift units in the Gar Wood line.

CONTRACTOR'S BODIES: Many combinations of boists and bodies are available for the contractor, landscape gardener, and general trucker.



CRANES: The complete line of Mead Morrison cranes and derricks provides a wide selection of models to suit individual needs.





(CONTINUED FROM PAGE 82)

cated to that idea. It is something they will not often think of or expect. In many cases of this kind, business will probably go to the railroads until such oversights are eliminated.

It is interesting to note, in this connection, how Dabney T. Waring, agent for the Middle Atlantic Motor Carriers Conference, has met this question of high minimum weights for the volume ratings. In a tariff of exceptions to the National Classification, Rule 10 neatly disposes of this barrier by saying: Where the volume ratings provided in

classification apply on freight in truckloads, subject to minimum weights as follows:

	T. L. Minimum Will Be		T. L. Minimun Will Be
8.000	8.000	18,000	13,000
10,000	8,500	20,000	14,000
12,000	9,000	21,000	14,500
14,000	10,000	24,000	16,000
15,000	11,000	26,000	17,000
16,000		28,000	18,500
17,000	12,500	30,000 up	20,000
	10,000 12,000 14,000 15,000 16,000	8,000 8,000 10,000 8,500 12,000 9,000 14,000 10,000 15,000 11,000 16,000 11,500	8,000         8,000         18,000           10,000         8,500         20,000           12,000         9,000         21,000           14,000         10,000         24,000           15,000         11,000         26,000           16,000         11,500         28,000

However, many truck carriers have not yet provided the same arrangement.

THE National Classification, Rule 12, governing mixed truckloads can, in my

opinion, stand revision. As it is now the shipper must pay on all the load the rate for the highest rated article at the highest minimum weight for any article. The railroads have a fairer rule in that it allows several alternatives. It is hardly more than a question of printing to make this change. Few should object.

The striking feature of the Official Motor Freight Classification No. 1, published by J. M. Adelizzi, Agent, Hart. ford, Conn., for New England motor carriers, is its liberality to the shippers. Although there is not space here to analyze the publication, nevertheless many of the ratings provided are so low that even avaricious shippers cannot conceal their astonishment. Look in the index of this classification and you will find innumerable references to item one on page nine. Turn to that item and page and you discover that such articles take the Fifth Class rate. T.L. and L.T.L. Now remember that Fifth Class is the usual rating for carloads via railroad. But carriers subject to this classification will even haul L.T.L. shipments at the same rating. A few of the articles taking Fifth Class T.L. and L.T.L., and the rail classification for L.C.L., are shown below so that readers will not think this an exagger-


#### Comparison of T.L. & L.T.C. Classification to L.C.L. Classification

	T.L. & L.T.L. Classification	Railroad L.C.L. Classification
Abrasive	5	4
Acetylene gas		3
Acetanalid		3 3 2
Advertising calendars	5	2
Air brakes, auto	5	1
Alcohol (various)	5	1st, 2nd, 3rd
Alloys (various)		3
Aluminum articles	5	1st, 2nd, 3rd
Ventilating apparatus	5	3
Asbestos packing, sheathing.	5	2nd, 3rd
Bolsters, truck body	5	4
Auto parts (various)		1st, 2nd, 3rd
Carbon tubes, carbon product	8 5	2
Cards, accounting machine	5	3
Compound, motor-fuel, anti-k	nock 5	1
Copper articles	5	1st, 2nd, 3rd
Iron or steel drums		2nd, 3rd
Engines, internal combustion	5	1st, 2nd, 3rd
Extracts (various)	5	1st, 2nd
Hardware, N.O.I.B.N.	5	3
Petroleum oils		3
Paper (various)	5	1st, 2nd, 3rd

Except for these and many other such clearly depressed ratings this classification is a worthwhile piece of work. Its mixed T.L. rule is better than the National Classifications, its "over-flow" rule is good, and the general tone of the publication is helpful. However, I question most seriously if such low ratings can be justified. Surely they are not necessary in order to garner the traffic.

FOR clarity, brevity and originality the Trans-Continental Motor Truck Classification No. 1, published under

# TRUXMORE WORLD'S BEST 3RD AXLE



A standard Diamond T-TRUXMORE 3-Axle Truck.

#### Reduces Your Insurance Costs

Buffalo to New York City . . \$228.38\*
Detroit to Chicago . . . . . . 112.44\*
Cleveland to Buffalo . . . . . 147.54\*
Philadelphia to Pittsburgh . . . 214.81\*

#### COMPARED TO ANY SEMI-TRAILER OF SAME CAPACITY

\*Difference in lowest premium for Public Liability & Property Damage Insurance between points shown.

TRUXMORE 3rd AXLE makes further SAVINGS on Gasoline, Tires, Deadweight, and Running Time—often totalling \$1,000 a year per truck.

#### We Make Both 3rd Axles and Semi-Trailers

Write for what users of Both Say-Address Dept. A



COMMERCIAL CAR JOURNAL



"My vote goes to the M-7.3. This squatty 5tonner boosts up heavy trucks or buses without disturbing load or passengers."— Driver. \$23.00\* Price ..



rd

er

of

er

its

en-

ul. if reto s

lity ick der

NAL

"I'm strong for the D-8.7 - a 12-ton shop worker that can't be beat." -Shop man. Price \$20.70\*



"The AA-8.5 gets my vote. Sturdy, compact -5-ton Light-Heavyand a fast, easy lifter." -Fleet Owner. \$10.85\*



"I need a husky that will stand the gaff of heavy duty jobs-so I check on this CB9 8tonner." -Trucker. \$14.15\*

WHAT a landslide! Throughout the country leading truck and bus makers, fleet operators, shop-men and drivers are voting the straight Blackhawk ticket! They KNOW from actual experience that Blackhawk Hydraulic Jacks have EVERYTHING. Power galore dependability-wide range of uses-easy operation - micro-control - safety. Yes Sir! - they save time and money-and make money, too!

FOR

#### **NEW LOW PRICES!**

Now Blackhawk offers greater values than ever with lower prices. Get on the Blackhawk band-wagon-and ride to success with the line of hydraulic jacks that have won the nation's vote for all-around supremacy! Ask your Jobber Salesman about Blackhawk's full line of hydraulics-1 to 75 tons. Write for free literature. Better still - order NOW!

BLACKHAWK MFG. COMPANY MILWAUKEE, WISCONSIN DEPT. CJ-6

\*Prices slightly higher on West Coast and Canada.



job-11" Low-hydrau-lic lift 6½"- total High 171/2". Price ......\$35.00\*

(CONTINUED FROM PAGE 84) the auspices of the Keeshin Motor Express, seems superior to the others already mentioned. Of course, the compiler of this classification had the highly important advantage of a unified and closely-knit organization back of him. Since the Classification is primarily for the Keeshin organization there were no compromises to be effected between conflicting interests, no factional disputes as to methods and objectives. Moreover, the compiler no doubt had the benefit of carefully gathered operating data and traffic statistics. Nevertheless, it is a wholly

worthwhile document of only 83 pages.

In examining this classification one gets the impression that Keeshin is going to make a reasonable profit on your traffic or he is not going to handle it. For example, one finds a rule to the effect that articles not specifically listed in the classification will be charged the Column One, or First Class, rate, subject to a minimum weight of 15 lb. per cubic foot.

Brevity is well illustrated by turning to "acids." Keshin's classification simply says, "Acids, N.O.I.B.N."; in the National Classification there are 30 subdivisions under heading "Acids."

Keeshin's classification will not cause any confusion because of volume ratings since all ratings are for L.T.L. only. However, large lots of freight are provided for by a table in the tariff that reduces the rate as the weight increases. Moreover, the tariffs provide for "All Commodity" rates between principal points. Incidentally, they are not too low, either.

A MONG other provisions of interest in Keeshin's tariffs is a "Maximum Load Limit." It is, 20 ft. long, 6 ft. wide and 5 ft. 9 in. high. These tariffs have clauses for the assessment of demurrage at the expiration of 24 hours free time on truckloads, trailer loads and semi-trailer loads. The charge is \$5 for the first 24 hours; after that storage at shipper's expense, at the option of the carrier. This is not unreasonable. There is also a "tolerance" or overload rule permitting up to 5% over 20,000 lb., chargeable at the Trailer Load rate. Any excess above that is charged the L.T.L. rate.

A minor but commendable feature of the Keeshin tariffs is that they list the street addresses and telephone numbers of all terminal points. Warning is given in the publications that instructions to pickup received after 3 P. M. cannot be acted upon that day.

In bringing this discussion to a close there is just space enough to mention a few other items in the new tariffs which have thus far caught the eye. Agent Waring publishes a "re-delivery" charge which consists of the tariff rate from the nearest terminal point to destination, subject to a 10 cent per cwt. minimum charge, plus accrued freight and storage. While this may be just, it is sure to brew some delightful pro and conning. Central Motor Freight Association tariffs, Harry M. Slater, Agent, provide that rates lower than fourth class apply only to movements handled by a single carrier. These tariffs-which, by the way, are excellently put together-carry density regulations, over-flow rules, intermediate rules, and an involved rule covering mixed T.L.'s.

The Cleveland, Columbus, Cincinnati Highway, Inc. Tariff No. 1 publishes exceptions to the National Motor Classification which increase ratings on certain articles more than 400 per cent. For example, boxes, other than iron or steel, and cans, pails, tubs, 2-qt. capacity or less, are charged four times first class rate. Neon signs, for some unknown reason, are charged ten times the first class rate. Rather than refuse to accept these and other articles considered undesirable, this outfit charges unbelievably high rates on them. Some shippers might bite.

(TURN TO PAGE 88, PLEASE)



always look like new. Plymetl is extremely light, yet extra strong and exceedingly durable. Insist upon it in your specifications.

so easily and quickly that trucks

weight in a truck body means less pay load, higher

cost per ton-mile. Haskelite Plymetl truck paneling

eliminates dead weight, makes flatter, smoother sides

and stronger bodies. Plymetl is many times as stiff

Plymetl has other outstanding qualities. It comes

in shippable sizes large enough for an entire side. It

needs no inside braces or supports to give it needed

rigidity and strength. Moreover, it is as easy to clean

as a window—dirt, scum and grease can be removed

as steel of the same weight.





# Make more round trips at low cost per load mile!

TRANSPORTING heavy, bulky loads at present day speed demands, over variable roads in all weather conditions with Safety — is assured those haulers operating FWD Trucks.

The FWD divides the load and power over the four driving wheels, consequently the driver has more control over the truck... There is not the danger of sluing or skidding on slippery or icy roads, or on curves — because the four wheels have positive traction.

Include FWDs in your fleet...They will give you more round trips at low cost per load mile...They will perform dependably, economically and safely regardless of roads or loads. " " " "

Let us give you the detailed story of FWD Controlled Power. Write today.

FW TH

THE FOUR WHEEL DRIVE AUTO CO.

CLINTONVILLE, WISCONSIN

Canadian Factory, KITCHENER, ONTARIO

TRUCKS

5 S T E P S
TO UNMATCHED TRUCK
PERFORMANCE

 GREATER SAFETY. Front axles are set back, resulting in power, as well as load being distributed to all four wheels. This gives the FWD sure footing on slippery pavements, in congested traffic, and when going around curves.

2. GREATER DEPENDABILITY OF SERVICE. Reserve power, rugged construction throughout, and true application of the four-wheel-drive principle, insure continuous operation under any condition. Backed by a nation-wide organization of parts depots and service men available at a moment's notice.

3. FASTER SERVICE. FWDs, with their powerful engines, wide range of gear ratios and four-wheel traction cut down trip time by being able to "make" the hills, curves, and poor going, faster than average trucks. No necessity for overspeeding on the straight stretches.

4. WIDER RANGE OF OPERATION.
Four-wheel traction enables the FWD to handle its regular hauling job easily and do the tough jobs as a matter of course.

5. OPERATING ECONOMY. Definite savings are made in gasoline, tire wear, maintenance cost, and other "out-of-pocket" expenses. This is the result of equal distribution of power, load, and scientific four-wheel-drive construction throughout.

CONTROLLED POWER ON AND OFF CONCRETE

L. ht he he ffs oe-

ft. iffs deis hat the unce" the

the uming inr 3

lose tion

riffs

eye.

ery"

rate

des-

cwt.

ight

just,

pro

eight ater.

than

ents

hese

xcel-

regu-

diate

ering

ncin-

pub-

Aotor

gs on

cent.

on or

. ca-

times

some

ten

than

r ar-

RNAL

(CONTINUED FROM PAGE 86)

The biggest mistake truckers have made, in my opinion, is to become participating carriers in the Consolidated Freight Classification, the railroad publication. The only justification for this might be that they had nowhere else to go. But they did have the National Motor Freight Classification. In fact, they still have it. In joining in on the railroad publication these hundred-odd truckers suggest they are guided by a counsel of despair. There is no occasion for that attitude. I question whether the rail carriers permitted these truckers to participate in their

classification purely out of kindness or sympathy for their plight. More likely they were delighted to have them, since it was playing right into their hands. It is possible these truckers will have to publish almost as many exceptions to that classification as there are rules and ratings in it. After all, this classification was put together with the railroads and not the trucks in mind. The National Truck Classification can be amended and revised so as to prove more beneficial to truckers. You may be sure that the railroads will not revise their classification to that end.

This raises another question. It has

been said that several of the motor carrier tariff agents found themselves so swamped with work that they were obliged to borrow help from the railroad tariff publishing agents. Even considering the emergency, and never for a minute doubting the good faith of the men from the railroad tariff bureaus, the wisdom of such action is highly speculative. This may in part explain the more than accidental parallel between many of the new truck tariffs and the railroad publications. At any rate, it is slightly absurd. Railroad men are steeped in their own business, have unyielding views about tariffs and rates, and are by reason of their personal interests antagonistic to development of highway transportation.

OUT of all these comments one certain conviction arises, the soundness of which can hardly be disputed. That is, there should be but one classification for all of the trucking industry. The sooner this is done the better it will be for the shippers and the truckers. There seems no necessity to argue the point. There is a necessity that this be done without delay.

Because so many of the new truck tariffs are valuable and commendable I am anxious that readers should not misunderstand the intent of these remarks. Many of the good things about the tariffs were not mentioned because it seems more important to consider the questionable parts, with a view to their possible correction. For the same reason there has been no attempt to dwell upon the undoubted difficulties that have attended the compiling of these tariffs; difficulties inevitable when thousands of truck operators must of a sudden revise their methods. outlook, operations, and act with a unity heretofore not required of them. Even the fellow on the shipper's side of the problem can appreciate these things. These views may take on a little more importance and significance when it is mentioned that they are not the exclusive outpourings of a single mind. My respect for truckers is such that I deemed it wise to check these views with other traffic men.

ti

B

0

Ju

Perhaps a few insatiable characters will wonder why there has been no mention made herein of the rates themselves. They may plead that these criticisms are unfair unless they are coupled with a discussion of the rates. However, editors also have a "STOP" signal. As it is now I've probably crossed the line. When the light changes to green the discussion of the rates will come charging, or maybe purring, along. (Ed. Note: The green signal is on and the rate discussion will be published in the July issue.)

#### SHEFFIELD

for good steel

STERLING for good silver

#### DRYZERO

for good insulation

# You can trust these names. Time has proved that they mean definite standards of quality. . .

Many times the elements that go to make up quality are hidden deep within the product. It is for this reason that NAMES have become established as marks of quality—names like Sheffield for steel, Sterling for silver. When these particular names appear on a product you feel reassured. They are the tangible marks or identifications of hidden elements that you cannot readily measure or test. You accept these names as sufficient proof of quality.

0 0 0

QUALITY may be claimed by the maker, but it is attested by others. Since it was introduced in 1921 Dry-Zero Insulation has had its quality endorsed repeatedly by people who know, by engineers, body builders and operators.

That is why Dry-Zero Insulation is accepted as a standard of truck body insulation. Its inherent qualities have been attested by those who are in a position to know what insulation quality must be.

Because Dry-Zero Insulation has been measured and tested many times by independent engineers and laboratories you can be sure of the high degree of the three primary requirements for truck body insulation — Efficiency, Permanence and Lightness.

Engineers and laboratories have placed a rating of .24 B.t.u. on Dry-Zero Insulation, the best rating of any commercial insulant.

This efficiency is permanent. It lasts for the full life of your truck. Dry-Zero Insulation does not settle or rot, is not affected by molds, never absorbs odors, never breaks up or disintegrates.

Neither do you pay for excessive deadweight. Dry-Zero Insulation weighs only 2 oz. per board foot. This means both a saving in dead-weight and additional payload capacity.

Find out for yourself the possible saving by using Dry-Zero Insulation in your trucks, operated at either refrigerated or normal temperatures. Ask your body builder. Or write to us for a complete report, giving the size of your truck body, the merchandise to be carried and the required temperature.

DRY-ZERO CORPORATION

222 North Bank Drive, Chicago 687 Broadview Avenue, Toronto

DRY-ZERO INSULATION The Most Efficient Commercial Insulant Known



e l- n r of

rt

1

nut

10

n.

of at acary.

kue

at

ck ole

101

re-

ler to

me

to ies

of ble

ors

ds,

m.

ide

esc

nce

not

gle ich

ese

no

ese

are tes. )P"

ibly iges will

ing,

gnal

be

NAL

#### A Solid-Action Starting Drive for Diesel and Heavy-Duty Gas Engines

The DELCO-REMY DYER DRIVE is a heavy-duty mechanical drive designed to transmit the greater horsepower required for cranking Diesel and the larger gas engines. Used with either a pedal or solenoid shift, it definitely engages the pinion with the flywheel ring gear before power is applied and before any rotation of the starting motor shaft occurs. It provides a "solid" drive through the splines of the armature shaft; automatically disengages the pinion when the engine fires, and does not chip the flywheel teeth. A positive lock prevents the pinion from "drifting" into the flywheel.

Because of its dependable performance in service, the Dyer Drive is rapidly increasing in favor with operators of larger commercial vehicles everywhere.


DELCO - REMY CORPORATION, ANDERSON, INDIANA

## Delco-Remy



Service and parts for all Delco-Remy units are available in the United States and Canada through Branches and Distributors of United Motors Service . . . in other countries through Overseas Motor Service Corporation.





Illustrations show operation of Delco-Remy Dyer Drive—from Delco-Remy Service Bulletin 1M-155. Write for free copy.



#### THE BURCH CORP. Dept. F - CRESTLINE, OHIO

#### Motor Tune-Up

is a real profit and business building service.

Send for free Tune-Up Charts

CARTER CORP.

CARBURETOR 2834-56 N. Spring Ave. St. Louis

#### "Our trucks never looked so clean!"



That's what one truck owner said after using M AG N U S 55-P. For, trucks washed this way take a better polish and delicate striping or finishes are not affected. Write for 48-page "AUTOMOTIVE CLEANING H AN D BO O K" which gives the whole story.

Magnus Chemical Co., Inc. 38 South Ave. Garwood, N. J.

#### **New Products on Parade**

(CONTINUED FROM PAGE 44)

#### Portable Welder

A PORTABLE arc welder known as the King type W-1, is the latest product of the Electric Heat Control Co., Cleveland, Ohio, Several new features are claimed, among



them being an indicating selecting switch. The operator can select the desired welding current by merely throwing the switch to the "off" position and turning a rheostat. There are no exposed terminals or plugs and no danger of shock when changing welding rates.

#### Synchro-Start

SYNCHRO-START automatically functions as a starting unit when the engine drops below its lowest pulling speed. When this occurs, the control instantly closes the starting switch and synchronizes the engagement of the starter pinion while the flywheel is still in motion. The instantane-



ous live flywheel pick-up which this device provides is said to prevent back-roll and back-fire as well as stalling. As long as the switch is in the "on" position the flywheel will never stop turning forward. Synchro-Start Corp., 213 Cherry St., Toledo, Ohio.



#### SPONGEX

GRID CONSTRUCTION

Seat Cushions or Fillers

All Sponge Rubber Construction Cheaper Than Springs • The Most Comfortable Cushion Ever Made

Address Dept. C SPONGE RUBBER

PRODUCTS CO. DERRY CONN.

#### DEPEND

oendability. write Hays Cornoration. gan City, Indiana, erature describthis ne husky wiper that slashes through clotted mud or snow with the 100-lb, kick of the air-brake supply behind it.



THE WORLD'S FINEST

#### ALL-WHEEL-DRIVE TRUCKS\*

ARE BUILT BY


#### MARMON-HERRINGTON

Factory and General Offices: Indianapolis, Indiana

\*The new line of Marmon-Herrington All-Wheel-Drive Ford V-8 models and the recently expanded line of regular Marmon-Herrington four and six wheel-drive units.



#### CONSIDER THE VALUE OF Black Diamond SEAT CUSHIONS



When you are ready to equip your trucks with seat cushions and back rests consider the eproven performance value of BLACK DIAMOND All-Rubber cushions. Performance is proved, not in laboratory tests alone, not in road tests alone, but in actual service in thousands of trucks. The famous exclusive diamond grid construction quarantees even better than above average results. As new car and replacement equipment, these cushions offer not only a new comfort and safety for drivers but eliminate upkeep expense. Designed to fit any size or shaped cab. Write direct for complete details.

KARPEX MANUFACTURING CO. 1424 E. 19th St., Indianapolis, Ind.

#### OSHKOSH

4 Wheel Drive Trucks

A proven product. 11/2 to 10 ton capacity. Write for complete information.

#### OSHKOSH

Motor Trucks, Inc. Oshkosh, Wis.



Look for the name "TIMKEN" stamped on every cup and cone.

THE TIMKEN ROLLER BEARING SERVICE & SALES CO., CANTON, O.



#### NEW SPARK PLUG BREATHES

Note the Ventilated feature. Each stroke of the piston drives clean, cool gases up around the porcelain and points and the plug stays cool and clean. Road tests show smoother, more efficient engine performance and much longer life. Write for details.

"ECCO" STANDARD SPARK PLUG CO. 4505 Wayne Ave., Philadelphia, Pa.

#### W. G. B. Oil Clarofier

THE new "Super" model W. G. B. Oil Clarofier has 21/2 times the capacity of the popular W. G. B. standard model. Cartridge life has also been lengthened in this new model. This unit is designed for use on engines having over 300 cu. in. engine displacement. According to W. G. B. Oil Clarifier, Inc., Kingston, N. Y., this model



does not allow oil to become contaminated, it efficiently removes abrasives, carbon and discoloration. With the use of this unit, the cartridge should be changed only when the oil begins to darken. The drain plug at the bottom of the clarifier should be opened occasionally to drain water and sludge which has been separated from the oil. The cartridge is changed without the Total capacity of the use of tools. clarifier is 239 cu. in.

#### Finish for Refrigeration Units

BRINE, constant moisture from frozen condensation, repeated cycles of defrosting and cooling cause rust and corrosion of refrigerating units. A system that withstands these conditions is a new two-coat, air-dry synthetic finishing schedule that has been developed by the Roxalin Flexible Lacquer Co., Elizabeth, N. J., from whom further data may be obtained.

#### Las-Stik Wood Putty

LAS-STIK wood putty repairs anything made of wood. It is useful in the repair shop for molds, patterns, inlays, etc. It may be used on trucks for repairing holes in floors, sides, roofs, door locks and hinges. Las-Stik won't shrink, sticks like glue and can be easily cut and drilled. Las-Stik Mfg. Co., Hamilton, Ohio.

#### DEARBORN LINE CAB-OVER-ENGINE FOR FORD TRUCKS

MORE ROOM FOR PAYLOAD

Dearborn Line Cab-Over-Engine Conversions give you a whale of a lot of room for payload and more profits! Moving the cab over the engine increases the payload space of your Ford Truck by 30% to 50%. You have the payload space of a large van and retain the fuel economy and maneuverability of a small truck! See your nearest Ford Dealer or write us direct.

TRANSPORTATION ENGINEERS, Inc. P. O. BOX 116 HIGHLAND PARK DETROIT, MICHIGAN

#### NOW It will pay You to Reclaim Oil—The New

#### Hileo Oil Reclaimer

with an entirely different process is the result of our ten years' experience in oil refining for fleets.



Model C-Capacity 12 gals. per day

#### ITS FEATURES ... proven in the field:

- 1. Complete restoration of your oil, re-oving acid and all foreign material and dilution.
- dilution.

  2. Low first cost—low operating cost.

  3. A machine that is simplicity itself, continuous, all electric and automatic.

  4. Low operating temperature high recovery.
- 5. Capacities from 12 to 50 gallons per

#### The Hilliard Corporation

102 Fourth Street, Elmira, N. Y.

-+信息掛+-


#### SEND THIS COUPON

-for information on how the New Hilco pays by producing these results at a low first cost. Ask about our "PAY AS YOU SAVE" PLAN.

THE HILLIARD CORPORATION 102 Fourth Street, Elmira, N. Y.

the New		 in tormation	8000
Name	 	 	
Company	 	 	
Address	 *****	 	

#### **CLEAN TRUCKS.**



#### **SPEEDWASHING**

Big and little truck, bus and cab owners are switching to the years ahead Rotawasher—for quicker washing at a substantial saving in labor costs. And the finished job is CLEAN! The list of Rotawasher users will convince you.

Write at once full details. Address THE

#### ROTAWASHER

CORPORATION, DEPT. CC 118 E. St. Clair Ave., CLEVELAND, OHIO

#### QUICK CRACK REPAIRS

#### WONDERWELD

Repairs Blocks In 1/2 Hour

No more tearing down and loss of income for days. Pour Wonderweld in top hose connections of hot engine. Cracks fill with Wonderweld, making block tight as new. Not a radiator repair. One can enough for most jobs. Cut repair cost and layup time. Ask your jobber.

MILLER MANUFACTURING COMPANY 1218 Kaighn Avenue, Camden, N. J.

FOR FORD Trucks CHEVROLET Trucks International Trucks

#### **POWER BRAKES**

WITH

Heretofore Power Brakes with Reactionary Control were obtainable only at much higher prices. Now you can get them at this very low price. Write at once for full information and trade discounts.

up

Power Brakes for Pass. Cars, \$12.50

BERG BROS. MFG. CO. 4520-22 W. North Ave., CHICAGO

#### Do-Ray Foglite

DO-RAY LAMP CO., Chicago, announces its new Amb-O-White fog light. The


ambo-white lens is so designed that the light rays cover the roadway but are not thrown upward. The lens is a white glass subjected to a special process transmitting an amber light. The Perma-Seal door is of stainless steel. The re-



flector is designed for a fixed focus 32 c.p. bulb. The lamp is dust and water proof. The bracket is spot welded and riveted to the lamp body. Nine feet of weather-proof cord is furnished with the lamp. Black body lists at \$4 and the full chrome is \$5.

#### **AC Plugs Sealed Hot**

IMPORTANT changes in the method of manufacture are said to be responsible for the leak-proof construction of the new AC spark plugs. The



center electrode where gas might leak was solved by the adoption of the two-piece center wire, and now through the development of new automatic machinery, all other sources of leakage have been stopped. The steel shell is heated to a red glow permitting the shell and insulator

to adjust themselves to each other while the metal is soft. The solid copper gaskets, shown in the sectional view, mould themselves around the insulator and when the heat is shut off shrinkage of the plug body makes the seal permanent. AC spark plugs are made in Flint, Mich.



A New Safety Device for TRUCKS and TRAILERS

AUTOMATIC BRAKE LOCK

Holds break-a-ways . . provides Sure and Safe parking . . meets all legal requirements . . easy to install . . automatic and unfailing. Write for illustrated details and prices.

AMERICAN DIE & TOOL C.

#### HERCULES POWER

Hercules engines, both gasoline and Diesel, have long been standard equipment on many leading makes of trucks, truck tractors and delivery units as well as urban and interurban buses, road building and maintenance equipment, industrial, oil field and agricultural machinery. Hercules provides an engineering service which includes a study of specialized power applications.

HERCULES MOTORS CORPORATION
Canton, Ohio, U.S.A.
America's Foremest Engine Manufacturer
Power Plants from 4 to 200 HP.

94 - 97%

of your crankcase drainings may be recovered for use, at a cost of 3-6 cents per gallon.

2221 Dalzelle

SKINNER PURIFIERS, INC., Detroit

Good Ventilation for truck cabs

N-L

FLEXIBLE VENTILATORS
The Nichols-Lintern Co.
7960 Lorain Ave. Cleveland, Ohio

#### DeVilbiss

Spray-Painting Equipment—Spray Booths—Canopy Exhaust Systems —Exhaust Fans—Air Compressors —Hose and Hose Connections— Oil Guns.

Write for catalog

THE DEVILBISS COMPANY
TOLEDO, OHIO

Distributors or direct sales and service representatives available everywhere.

#### THE COMPLETE LINE THAT COMPLETELY SATISFIES



THE FITZGERALD MFG. CO., TORRINGTON, CONN.

FITZGERALD GASKETS

COMMERCIAL CAR JOURNAL



-the trucks that are "BUILT TO MEET
A CONDITION"

THE **HUG** COMPANY
Highland • Illinois

McCORD REFRIGERATION
—FUEL SYSTEM
FOR TRUCKS
REFRIGERATION
AT NO COST
—BY THE FUEL
THAT RUNS THE MOTOR

McCORD RADIATOR AND MFG. CO. DETROIT

#### ALCO

#### FOUR WHEEL DRIVE

Converts your Ford or Chevrolet truck into a RUGGED, POWER-FUL FOUR WHEEL DRIVE able to do the job with ease where much heavier trucks fail, and at a fraction of the cost.

Write

ALMA MANUFACTURING CO. ALMA, MICHIGAN

#### HOOF GOVERNORS



Used Exclusively on Hundreds of National Fleets

HOOF PRODUCTS CO. 162 N. FRANKLIN ST. CHICAGO, ILL

#### Grounding Plug

APPLETON Auto Tank Truck Grounding Plug and Receptacle is a safety device required in certain states at all gasoline stations and bulk stations in connection with trucks used in transporting hazardous liquids. Appleton Electric Co., 1701 Wellington Avenue, Chicago.

#### **Dualift Auto-Hoist**

DUALIFT auto-hoist is actually two lifts in one, one section being permanently mounted in the floor, and the other section being portable. An interlocking control operates the units together or separately as needed, and a safety mechanism regu-



lates both the air and oil flow to make lifting and lowering steadier. A feature claimed for the Dualift is that there are no cross-beams to interfere with the mechanic when he is working under a car or truck. A vertical lift of 66 in. is possible with this equipment. Cochin Mfg. Co., 116 New Montgomery St., San Francisco.

#### If In Quest of Safety Try a Quiz

(CONTINUED FROM PAGE 15)

were found to be thought more prevalent than has been previously recognized.

The questionnaire was written around our accident experience, was timed to determine if prior dissemination of accident facts had hit the mark and how well we were selling our ideas of how accidents might be avoided. I believe considerable thought along correct lines was stimulated. Some research among safe driving manuals and other such sources of information, was detected.

(TURN TO NEXT PAGE, PLEASE)

### SAVES OIL!

SAVES ENGINE WEAR



"SUPER"

MODEL W. G. B. OIL CLAROFIER . . .

TWO AND ONE-HALF TIMES CAPACITY OF STANDARD MODEL

Designed for large motor equipment, particularly Diesel motors and all motors having over 400 cubic inch displacement.

Write for information to 101 GREENKILLAVE., KINGSTON, N.Y.

W. G. B. OIL CLAROFIER, INC

#### Ahlberg Ground Bearings

40% Saving Over New Bearing Costs

AHLBERG BEARING CO.
Chicago

Branches and Distributors Everywhere

Ahlberg Grand Bearings

# PERMAX

#### PER-MAX

the Dermanent TRUCK FINISH

Ask for list of prominent fleets successfully using PeR-Max. We will send one pint

of black for test if you will write us giving the size of your fleet.

#### RINSHED-MASON COMPANY

Manufacturers of Automotive Finishes 5935-71 Milford Street, Detroit, Michigan

#### THORNTON

Dual Ratio Four Rear Wheel

#### DRIVE

FOR TRUCKS

THORNTON TANDEM CO.

Detroit

#### "Over 200,000 miles and no cracks or uneven wear'

Leaman Transportation Company, Downingtown, Pa., writes: "We have equipped about 20 trailers, 8 semi-trailers and a few tractors with your drums, working in mountain as well as level territory. We have had no replacements after we continued with the seminary of the semi have had no replacements after we equipped with your drums. Some have had over 200,000 miles of operation and show no signs of cracks or uneven wear.

\*\*\*reduced our brake costs very materially."



#### End Your Brake Drum Trouble

Made of Cemcalloy, the special heat and wear resisting alloy metal, our brake drums are non-checking, and non-warp-ing. Thoroughly tested on hundreds of trucks during the past  $2\frac{1}{2}$  years without one failure due to breakage, heat checking and undue or uneven wear.

Write for information and prices, stating make, model, quantity and type of service. CHRISTIANA MACHINE CO., Christiana, Pa.



"Supervised Transportation"



and the last word in governors

Write for complete information — there is a MONARCH distributor in your area.

MONARCH GOVERNOR CO., DETROIT

Based on the experience of our drivers, we installed right-hand mirrors and we have reduced this type of accident experience 90 per cent. The public knows little of the use of mechanical turn indicators, right hand turns are difficult to signal and about the only means you have of doing so in tractor-trailer use is in assuming your position for the turn as early as possible. Such units need more than an average amount of space for a right hand turn and the mirror permits the driver to watch to the rear on his right side.

However, we can install every safety device on the market-but still the most important factor in highway safety is the driver

THERE is a shortage of good drivers. To realize how appalling that shortage is just look around you, on open highway or in city traffic.

General accident statistics tend to show that poor driving is entirely too prevalent in all classes of drivers. I think too, that our type of business has created a demand for drivers quite in excess of the supply of trained men. Also, adequate supervision of truck drivers, on the whole, is sufficiently laggard to have permitted a number of men to consider themselves as drivers, in error. Again, long distance driving, I'm referring to trucks, does not seem to attract the level headed, emotionally stable individual who in my opinion makes the best driver. Of course we get some of these people, but not in sufficient numbers.

Good drivers are alert, well coordinated mentally and physically, have a well developed sense of responsibility to their self respect, their employer and the rights of all other people, they diagnose accident hazards before they reach them and they must know the limitations of their ability and the ability of their vehicle.

We interview all applicants for driving jobs with a view toward estimating their intelligence, studying their appearance, and getting an outline of

No matter what your customer requirements are you can fill them better and easier with Hercules Steel Dump Bodies and Tubeless Hydraulic Hoists.

Hercules offers a full line of bodies--all types and all sizes and several models of powerful tubeless Hydraulic Hoists.

Any user will tell you that "Hercules Dumps are better."

Distributors Everywhen WRITE FOR NEW ILLUSTRATED LITERATURE

HERCULES STEEL PRODUCTS CO. GALION, OHIO, U. S. A.

ALSO HERCULES SPLIT DRIVE POWER TAKE-OFFS

DOUBLE POSITIVE SAFETY TRACTION DOUBLE MILEAGE

McKay Multi-Grip Double-Bar-Reinforced Truck Chains

THE McKAY COMPANY PITTSBURGH, PA. McKAY BLDG

VALVES . GUIDES . SPRINGS . KEYS SEAT INSERTS . WATER PUMP PARTS CHASSIS BOLTS AND BUSHINGS TRYON SHACKLES SILENT "U" SHACKLES HARRIS SHACKLE BUSHINGS ECCENTRIC TIE RODS . PISTONS CHROME-PLATED PISTON PINS

Write for Catalogs The Toledo Steel Products Co. 3304 SUMMIT STREET TOLEDO, OHIO, U. S. A.

#### 10,000 MILES OF CONTINUOUS, POSITIVE HIGH PRESSURE LUBRICATION ON ONE FILLING

. QUICKLY REFILLED

. INSTALLED IN 5 MINUTES

Water Pumps

• Fan Bearings • Clutch Yokes

Pedal Bearings

Steering Spindles

Shackle BoltsWheel SuspensionSaddle Bearings

• Tie Rods

ATTENTION SALESMEN

To men having a following of fleet owners, we offer an opportunity of a lifetime. With our introductory offer you can close five to eight accounts daily. You do not get a turndown. Alcos are used and endorsed by the largest fleets in the country. Write today and tell us about yourself. This may be the opportunity you are seeking.

**AUTOMATIC LUBRICATOR CO.** 53 W. Jackson Blvd.. Chicago, III.

# St.Paul HYDRAULIC HOISTS BODIES

There's a St. Paul Hoist to fit every need. Distributors conveniently located in leading distributing centers . . . stocked and ready to make prompt shipments.

St. Paul Hydraulic Hoist Co.

#### Commercial Car Journal Truck Specifications Are Corrected Monthly

You can depend on the information they contain as being accurate and up to the minute. Use them to buy and use them to sell trucks.

Motor Reconditioning Should Start with Ring Ridge Removal



MADE IN Model 210, \$1250

Every new piston, oversize ring or connecting rad job demands ring ridge removal. This low-cost tool is the quick-this low-cost tool is the quick-this low-cost tool is removed ring ridges. Follows contour of cylinder exactly and stops cutting when ridge is removed flush with cylinder wall. Pays for itself in the time it saves. Order from your Jobber now.

RING RIDGE REAMER


WEAVER



Hydraulic PRESSES

Speed, Ease and Efficiency

In 60 and 30 Ton Sizes
Ask for Details
WEAVER MANUFACTURING COMPANY



their previous experience. If, in this interview, we are satisfied that the applicant has met our preliminary requirements, then, and not until then, we request formal application for employment on a regular bonding company form.

W HEN we are satisfied as to the man's past history and his physical and personal make-up, we require a demonstration of his driving ability. This demonstration period represents a sort of apprenticeship during which the new man is accompanied by a seasoned driver whose ability to properly handle our tractor-trailer units has been proved through long experience. The driver, who has the job of breaking in all new men and who also investigates the driving habits of older men having too great accident frequency, passes upon the new man's driving ability and the promise he shows before permitting him to take a truck out alone.

We avoid fatigue, a big accident contributing factor, by limiting our drivers to 200 miles daily. There are, of course, exceptions to that rule but very few. Drivers were formerly responsible for the regulation of their hours and on the average were found not competent to do so. Fatigue, while usually difficult to detect in causations in a large number of accidents, was without doubt present and due in a great measure to the drivers' habits, overwork being caused by lack of planning, largely. Limiting of daily miles provides ample rest periods with regularity. Men are given definite runs and are through for the day when the run is completed, a minimum number of hours of rest are required before returning to the truck.

At three-month intervals we hold general safety meetings at which qualified speakers discuss safety in the drivers' own language. A portion of each meeting is usually given over to the men for suggestions and discussions. Here, also, innovations in methods are proposed and discussed, and past records are quoted to show where improvement is needed. Decatur Cartage Co. has profited by these meetings and so have our drivers.

WHEN one of our drivers is involved in an accident, no matter how trivial its nature, he fills out the accident card. Next, he reports at our nearest office where the Preliminary Vehicle Accident Report is made. A copy of this report is sent to the insurance company as notification of an accident and as a forerunner of the regular Vehicular Accident Report. The driver reports in person to the safety director with his card and the preliminary report. At that time it is determined if the case

The <u>new</u> Schrader Chuck Gauge (No. 2030)

offers complete


"TRIGGER CONTROL"

of Tire Inflation, Pressure Recording and Deflation . . .

... and the new Schrader

#### DUAL-FOOT EXTENSION CHUCK

(No. 8340) makes it easy to reach dual-tire or other hard-to-get-at valves



EQUIPMENT that makes air-servicing of tires easier and speedier will earn its cost many times a year for the truck or bus fleet operator. With the new Schrader air-line appliance shown above tire inflation is simpler, faster, and more accurate than ever before. They save time; save tires—minimize the chance of neglect. Order through your distributor.

A. SCHRADER'S SON, BROOKLYN, N. Y.

Division of

SCOVILL MANUFACTURING COMPANY

Schrader

TIRE-SAVING VALVES, CAPS and GAUGES

June, 1936

NAL



needs immediate action of a disciplinary nature, if not, the driver appears at the next regular monthly meeting of the trial board to get his rating on the case in question. The board reviews the driver's original report and the results of the insurance carriers investigation, if any was made. The driver is thoroughly questioned to determine what his actions were in the accident. If it is found that the driver could have prevented the accident, regardless of the action of the other driver, the accident is chargeable. The board does not assess penalties, it establishes only if our driver contributed to the causes of the accident. It is made up of our safety director, the insurance company broker and engineer, and one accidentfree driver.

IF the trial board finds our driver did not contribute to the cause of the accident it cannot be charged to him. If any action on his part was in violation of good driving practice he is charged with the accident. Penalties for chargeable accidents are assessed according to frequency, amount of carelessness evident, previous record, etc. Layoffs are occasionally employed, but as a last resort, since they are a distinct hardship to the man. Chronic repeaters are eventually let out. We try to build up a desire to drive safely since we feel that is the only lasting remedy.

At regular intervals we make up an accident summary report which gives us a clear picture of all minor and major accidents incurred in the period. and which includes all information

relative to age groups, experience, actions of drivers, locations, the type of accident, results, time, road, weather, and light conditions, and many other items which enable us to seek out causes which are reflected in greater accident frequency and which obviously must be improved.

#### Yankee Lighting Equipment

A COMPLETE line of directional signals, reflectors and clearance lights is announced by the Yankee Metal Products Corp., Norwalk, Conn. The front of the directional signal is a metal face with an arrow silhouetted in it and an amber pyralin backing. The maker claims it is visible at a distance of 200 ft. in bright sunlight. Yankee reflectors are visible up to 1000 ft. The silver-plated glass lens is set in special cushioning asphaltum making it shatter-proof and sealing against dust.

#### **Halide Leak Detector**

THE Halide leak detector for refrigerant gases consists of a regular Prest-O-Lite needle valve torch handle assembly, a burner which includes a suction nipple for



attaching a rubber hose, and a chimney with a copper reaction plate. The rapid flow of acetylene through the burner causes a suction which draws in any refrigerant gas near the open end of the suction tube.

To operate the detector, the flame is first adjusted so that the top of the outside cone is level with or slightly above the

#### ARMORPLY

 A metal faced plywood panel of high quality for building better panel bodies.

Armorply is the lightest panel of its type available. It is faced with rust resisting galvanneal steel, and has a hard birch back.

Write for samples, prices and full information.



chimney of the detector. The open end of the suction tube is used to explore around those places where a leak might occur. Any halide refrigerant gas drawn into the burner is decomposed with the formation of free acids. These acids, coming into contact with the hot copper reaction plate cause instant color response in the flame. Visible color indication of the smallest concentration of refrigerant gas by a green-tinted flame is given by the Detector.

Decatur drivers' employment and accident records are kept on the reverse sides of one form. This is the 8½ x 11-in. form shown here. The accident summary and accident reporting forms are described in the article by Fleetman Pride

MERIT AWARDS	Anciden	t Record		DATE	
MERIT AWARDS			-	PENALTIES	
				-	
VEHICLE ACCIDENT			-	MP ACCIDE	
ME ONE TO PE	PORADES	-		MIP ACCIDE	
	PORAPET .	BATE ACC.	MOST TIME	-	DEMARKS
				-	
		STATISTICS.			
Leadin	TIME Date Work	THE PARTY	DA See Fig Au	ACTION	DEWARES
		-			
		_	1111		
NAME		1	GE	Dan Em	(kgo4
ADDRESS		Married or	Section 1	Sun	ther of Dependents
			- SALLA		
Last Previous Position	Where and With It				How Long
Last Previous Position  Wate You Ever Bonded	Where and With W	Thom		For Ween	
		N bom			How Long
Wicen Your Ever Benefits	North What Compar Previous Develop E	N bom		For Ween	How Long
Were You Ever Bonded Position	Stath What Compar Freezess Deving E	N hom.		For Ween	How Long
Were You Ever Bonded  Position  Vito How You Dreven For and How How Many  How Many We	Stath What Compar Freezess Deving E	N hom.		For Ween	Now Ling Valueles  Con Charles
Were You Ever Bended  Province  Who Hore You Divers For and Her- Hore Many Previous Accidents  Vert Facts	Stath What Compar Freezess Deving E	N hom.		For 33 hours	Mow Long  Volume  Volume  Country  1951
Were You Ever Bended  Province  Who Hore You Divers For and Her- Hore Many Previous Accidents  Vert Facts	Stath What Compar Freezess Deving E	N hom.		For 33 hours	Hew Long  Velocity  Velocity  Total Transport Charles
Were You Ever Bended  Province  Who Hore You Divers For and Her- Hore Many Previous Accidents  Vert Facts	Stath What Compar Freezess Deving E	N hom.		For 33 hours	Mow Long  Volume  Volume  Country  1951
Were You Ever Bended  Province  Who Hore You Divers For and Her- Hore Many Previous Accidents  Vert Facts	Stath What Compar Freezess Deving E	N hom.		For 33 hours	New Long  Volunts  Opening  Op
Were You Ever Bended  Province  Who Hore You Divers For and Her- Hore Many Previous Accidents  Vert Facts	Stath What Compar Freezess Deving E	N hom.		For When Kind	New Long